KCC OIL/GAS REGULATORY OFFICES

Date: <u>11/23/09</u>	District: <u>01</u>
	New Situation Lease Inspection
·	Response to Request Complaint
	Follow-Up Field Report
Operator License No: 9408	API Well Number: <u>15-135-24983-00-00</u>
Op Name: Trans Pacfic Oil Corporation	Spot: SE-SW-NE-SW Sec 3 Twp 19 S Rng 25 E / W
Address 1: 100 S Main Ste 200	1610 Feet from N/ S Line of Section
Address 2: P.O. Box 783188	1770 Feet from E / W Line of Section
City: Wichita	GPS: Lat: 38.42524 Long: 100.07535 Date: 11/23/09
State: Kansas Zip Code: 67202 -3735	Lease Name: Spruill Well #: 2-3
Operator Phone #: <u>(316) 262-3596</u>	County: Ness
Reason for Investigation:	
Witness Alt.II	
Problem:	
None cement circulated to surface	
Persons Contacted:	
Findings:	
8-5/8" @ 222'W/160sxs	
TD. @ 4462'	•
4-1/2" @ 4457'W/170sxs Port Collar @ 1696' cemented with 140sxs-si	md-1/4# flo seal-2%cc-15sys went to nit
	111u-1/4# 110 Seai-2 /0cc-105x5 werk to pit
·	
Action/Recommendations: Follow	v Up Required Yes No 🗹 Date: 7/14/09
Action/Recommendations: Follow	
	RECEIVED
Action/Recommendations: Follow RECEIVED	
RECEIVED	RECEIVED DEC 0 7 2009
RECEIVED DEC - 3 2009	RECEIVED
RECEIVED	RECEIVED DEC 0 7 2009
RECEIVED DEC - 3 2009 KCC DODGE CITY Verification Sources:	RECEIVED DEC 0 7 2009 KCC WICHITA Photos Taken:
RECEIVED DEC - 3 2009 KCC DODGE CITY Verification Sources: RBDMS KGS	RECEIVED DEC 0 7 2009 KCC WICHITA Photos Taken:

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>11/23/09</u>		_	District	: 01	-	Lice	nse #: <u>9408</u>	<u> </u>
Op Name: 9408			Spot: <u>S</u>	Spot: <u>SE-SW-NE-SW</u>		Twp <u>19</u>	S Rng <u>25</u>	∏Ė √ W
County: Ness †				ame: <u>Sprui</u>			Well #: 2-3	
I.D. Sign Yes	No		· [6]	Gas Ven	ting Yes	No		, in
Tank Battery Cond Condition: Good		ole Overflow	ving	Pits Fluid De	pth:f	t; Approx. Size	::ft. x	ft.
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:f	t. xft.		vater Pipelines Visible: Y	N T	ested for Leaks:[o o
Oil Spill Evidence				Flow	ing Holes			·
Abandoned Well	Potential Polli	ution Problem [Yes No		Wells		·	
Lease Cleanliness Very Good Sa	atisfactory	Poor Ver	y Bad	Moni	toring Records			
SWD/ER Injection Well Permit #:	ressure – Actua ressure – Actua ressure – Actua	al: psi; Au al: psi; Au al: psi; Au	thorized: psi thorized: psi	Tubing: Tubing: Tubing:	; T/C	C Annulus: C Annulus:	; C/SP Annu ; C/SP Annu ; C/SP Annu ; C/SP Annu	ulus: ulus:
API Number	Footages	Spot Location	GPS	v	Vell #		Well Status	
15-135-24,983-00-00	1610FSL 1770FWL	SE-SW-NE-SW	38.42524-100 <u>.</u> 0	07535 2-	3 New w	ell, Alt.II com	pleted	
							·	
1					1.	1 1		
:					i.			