15-051-22900-00-00

KANSAS

FORM CP-3 Rev. 1-8-82

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT REPORT

| API Number 15- 051-22,900 API Number 15- 051-22,900 Wichita, KS 67202 Operator's Full Name Murchison Oil & Gas Complete Address 2500 Diamon Shamrock Tover, 717717 No. Harvood, Dalles, Texa Lease Name McIntosh Well No. #1 Location SE SW SW Sec. 6 Twp. 12 Rge. 18 (East) (West County Ellis Total Depth 3676' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereinafter indicated Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Voodlawn, Wichita, License No. Apperation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. Amount of Surface Casing: 261' of 8 5/8". I hereby certify that the above plugging instructions were given as here |
|---|
| Complete Address 2500 Diamon Shamrock Tover, 717717 No. Harvood, Dallas, Texas Lease Name |
| Lease Name McIntosh Location SE SW SW Sec. 6 Twp. 12 Rge. 18 (East) (West County Ellis Total Depth 3676' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereinafter indicated Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Woodlawn, Wichite, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Sec. 6 Twp. 12 Rge. 18 (East) (West County Ellis Total Depth 3676' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereinafter indicated Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Woodlawn, Wichita, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| County Ellis Total Depth 3676! Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereinafter indicated Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Woodlawn, Wichita, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Abandoned 0il Well Gas Well Input Well SWD Well D&A X Other well as hereinafter indicated Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Voodlawn, Vichita, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Other well as hereinafter indicated Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Woodlawn, Wichita, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Plugging Contractor Big Springs Drilling, Inc. Address Box 8287 Munger Station, 400 N. Voodlawn, Vichita, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Address Box 8287 Munger Station, 400 N. Woodlawn, Wichita, License No. Kansas 67208 Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Operation Completed: Hour: 8:45PM Day: 23rd Month: March Year: 1982 Plugging Operations attended by Agent?: All XX Part None The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| The above well was plugged as follows: 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| 8 5/8"-261' s.p. cuc. w/165 sacks common-2% Gel3% Cal. Cl. Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. Cl. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Ordered 130 sacks 50/50 posmix-4% Gel3% Cal. C. and 8 5/8" plug. Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| Spot with drill stem with heavy mud between all plugs. 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| 1st plug @ 750' w/70 sacks cement 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. |
| 2nd plug @ 250' w/40 sacks cement 3rd plug-solid bridge of hulls and plug @ 40' w/10 sacks cement Circulate 10 sacks of cement in rat hole. The Change of hulls and plug @ 40' w/10 sacks cement State Change of hulls and plug @ 40' w/10 sacks cement MAD 62-100 |
| Amount of Surface Casing: 261' of 8 5/8". |
| Amount of Surface Casing: 261' of 8 5/8". CONSERVATION ONLY |
| Amount of Surface Casing: 261' of 8 5/8". |
| I hereby certify that the above plugging instructions were given as here stated. Signed: Jallo C. School |
| Conservation Division Agent |
| I hereby state that I was not present while the above well was being plugged, however, to the best of my knowledge and belief it was plugged as herein stated. A full account for my not being present is as follows: |
| |
| |
| |
| Signed: Conservation Division Agent |

119.47