## KANSÁS STATE CORPORATION COMMISSION

## CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

Remarks:



PLUGGING

FILE SEC / 4 T /O R 204 BOOK PAGE 32 LINE 39

TATION DIVISION :

County: Rooks Location: CSE SE Sec. 14 Twp. 10 Rge. 20 (E) (W) Name of Field: Total Depth: 3789  I have this date completed supervision of plugging of: Lease Name: Sutor Well No. 8  Operator's Full Name: I. O. Miller Complete Address: Box 274 Ellis, Kans Plugging Contractor: Forbes Casing Pulling Co Address: Great Bend, Kans License No. 49  Oli Well X Gas Well Input Well SWD Well D 6 A  Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? Yes_No If yes how long? Reason:  Operation Completed: Hour 5PM Day 25 Month 4 Year_ The above well was plugged as follows:  8 5/8" at 227' circulated with 0 ment 0 52" 3783! with 100 max cement.  Filled with sand to 3770', set 4 sax cement with dump haller, pulled. 2995 52" to 600', circulated hole with heavy mud through 52" (38 sax displaced 20 sax cement through 52" at 150', heavy mud to 150', displace.  20 sax cement through 52" at 150', heavy mud to 35', sat rock and 10 sac cement to bottom cellar.  Mudding and cementing by Globe Cementing Co.	File No. 32-39	County:	Rooks						·
Name of Field:	•							(E)	_(W)
I have this date completed supervision of plugging of:  Lease Name: Sutor Well No. 8  Operator's Full Name: I. O. Miller  Complete Address: Box 274 Ellis, Kans  Plugging Contractor: Forbes Casing Pulling Co  Address: Great Bend, Kans License No. 49  Oli Well X Gas Well Input Well SWD Well D&A  Other well as hereafter indicated:  Was any delay in plugging operations caused by Conservation Division Agent? Yes No  If yes how long? Reason:  Operation Completed: Hour 5PM Day 25 Month Year  The above well was plugged as follows:  8 5/8" at 227' circulated with coment A 52" 3783! with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump bed lar, pulled  2995' 52" to 600', circulated hole with heavy mud through 52" (38 sax displaced 20 sax coment through 52" at 150', heavy mud to 35', sat rook and 10 sax coment to bottom cellar.  Mudding and comenting by Globe Cementing Co.									
Decase Name: Sutor									
Deperator's Full Name: I. O. Miller  Domplete Address: Box 274 Ellis, Kans  Plugging Contractor: Forbes Casing Pulling Co  Address: Great Bend, Kans License No. 49  Dil Well X Gas Well Input Well SWD Well D & A  Dither well as hereafter indicated:  Was any delay in plugging operations caused by Conservation Division Agent? Yes No.  If yes how long? Reason:  Deperation Completed: Hour 5PM Day 25 Month 4 Year  The above well was plugged as follows:  8 5/8" at 227' circulated with coment 9 52" 3783' with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump heller, pulled  2995' 52" to 600', circulated hole with heavy mud through 52" (39 sax displaced 20 sax coment through 52" at 600', heavy mud to 150', displaced 20 sax coment through 52" at 150', heavy mud to 35', Sat rock and 10 say coment to bottom cellar.  Mudding and comenting by Globe Comenting Co.		,			Well	No	8		
Complete Address:  Box 274 Ellis, Kans  Plugging Contractor:  Forbes Casing Pulling Co  Address:  Great Bend, Kans License No. 49  Dil Well  Cas Well  Input Well  SWD Well  DeA  Deter well as hereafter indicated:  Was any delay in plugging operations caused by Conservation Division Agent? Yes_No.  Reason:  Operation Completed: Hour  SPM  Day  25  Month  Year  The above well was plugged as follows:  8 5/8" at 227' circulated with owment 9 5\frac{1}{2}" 3783' with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump heller, pulled  2995' 5\frac{1}{2}" to 600', circulated hole with heavy mud through 5\frac{1}{2}" (38 sax displaced 20 sax coment through 5\frac{1}{2}" at 600', heavy mud to 150', displaced 20 sax coment through 5\frac{1}{2}" at 150', heavy mud to 35', set rook and 10 say coment to bottom cellar.  Mudding and comenting by Globe Cementing Co.									
Plugging Contractor: Forbes Casing Pulling Co  Address: Great Bend, Kans License No. 49  Address: Great Bend, Kans License No. 49  Onli Well X Gas Well Input Well SWD Well D&A  Other well as hereafter indicated:  Was any delay in plugging operations caused by Conservation Division Agent? Yes No.  If yes how long? Reason:  Operation Completed: Hour 5PM Day 25 Month 4 Year  The above well was plugged as follows:  8 5/8" at 227' circulated with c ment 9 5\frac{1}{2}" 3783' with 100 sax cement.  Filled with sand to 3770', set 4 sax cement with dump heller, pulled  2995' 5\frac{1}{2}" to 600', circulated hole with heavy mud through 5\frac{1}{2}" (38 sax displaced 20 sax cement through 5\frac{1}{2}" at 600', heavy mud to 150', displace  20 sax cement through 5\frac{1}{2}" at 150', heavy mud to 35', set rook and 10 saccement to bottom cellar.  Mudding and cementing by Globe Cementing Co.		and the second s							
Address: Great Bend, Kans License No. 49  Dil Well X Gas Well Input Well SWD Well D & A  Other well as hereafter indicated:  Was any delay in plugging operations caused by Conservation Division Agent? YesNo.  If yes how long? Reason:  Operation Completed: Hour 5PM Day 25 Month 4 Year_  The above well was plugged as follows:  8 5/8" at 227' circulated with coment 9 5%" 3783' with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump beller, pulled.  2995' 5%" to 600', circulated hole with heavy mud through 5%" (38 sax displaced 20 sax coment through 5%" at 600', heavy mud to 150', displaced 20 sax coment through 5%" at 150', heavy mud to 35', set rock and 10 sax coment to bottom cellar.  Mudding and comenting by Globe Comenting Co.									
Other well as hereafter indicated:  Was any delay in plugging operations caused by Conservation Division Agent? YesNo.  If yes how long?									
No. If yes how long? Reason:  Operation Completed: Hour 5PM Day 25 Month 4 Year  The above well was plugged as follows:  8 5/8" at 227' circulated with coment 0 50 3783! with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump better, pulled 2995! 50 to 600', circulated hole with heavy mud through 50 (38 sax displaced 20 sax coment through 50 at 600', heavy mud to 150!, displace 20 sax coment through 50 at 150!, heavy mud to 35', set rock and 10 say coment to bottom cellar.  Mudding and comenting by Globe Comenting Co.									
No. If yes how long? Reason:  Operation Completed: Hour 5PM Day 25 Month 4 Year  The above well was plugged as follows:  8 5/8" at 227' circulated with coment 9 52" 3783! with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump better, pulled 2995' 52" to 600', circulated hole with heavy mud through 52" (38 sax displaced 20 sax coment through 52" at 600', heavy mud to 150', displace 20 sax coment through 52" at 150', heavy mud to 35', set rock and 10 say coment to bottom cellar.  Mudding and comenting by Globe Comenting Co.	Other well as hereafter	Indicated:							
Operation Completed: Hour 5PM Day 25 Month 4 Year The above well was plugged as follows:  8 5/8" at 227' circulated with coment 9 5½" 3783' with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump had ler, pulled 2995' 5½" to 600', circulated hole with heavy mud through 5½" (38 sax displaced 20 sax coment through 5½" at 600', heavy mud to 150', displace 20 sax coment through 5½" at 150', heavy mud to 35', set rock and 10 sax coment to bottom cellar.  Mudding and comenting by Globe Comenting Co.	If yes how long?	<u> </u>	Reason:						
Operation Completed: Hour 5PM Day 25 Month 4 Year The above well was plugged as follows:  8 5/8" at 227' circulated with coment 9 5½" 3783' with 100 sax coment.  Filled with sand to 3770', set 4 sax coment with dump had ler, pulled 2995' 5½" to 600', circulated hole with heavy mud through 5½" (38 sax displaced 20 sax coment through 5½" at 600', heavy mud to 150', displace 20 sax coment through 5½" at 150', heavy mud to 35', set rock and 10 sax coment to bottom cellar.  Mudding and comenting by Globe Comenting Co.									
The above well was plugged as follows:  8 5/8" at 227' circulated with orment 9 5\frac{1}{3}" 3783' with 100 sax coment.  Filled with sand to 3770', set 4 sax cement with dump better, pulled 2995' 5\frac{1}{2}" to 600', circulated hole with heavy mud through 5\frac{1}{2}" (38 sex displaced 20 sax cement through 5\frac{1}{2}" at 600', heavy mud to 150', displace 20 sax cement through 5\frac{1}{2}" at 150', heavy mud to 35', set rock and 10 section to bottom cellar.  Mudding and cementing by Globe Cementing Co.	Operation Completed: Ho							Ye.	ar50
Filled with sand to 3770', set 4 sax cement with dump beiler, pulled 2995' $5\frac{1}{2}$ " to 600', circulated hole with heavy mud through $5\frac{1}{2}$ " (38 sax displaced 20 sax cement through $5\frac{1}{2}$ " at 600', heavy mud to 150', displace 20 sax cement through $5\frac{1}{2}$ " at 150', heavy mud to 35', set rock and 10 say cement to bottom cellar.  Mudding and cementing by Globe Cementing Co.	·	•							
Filled with sand to 3770', set 4 sax cement with dump beiler, pulled 2995' $5\frac{1}{2}$ " to 600', circulated hole with heavy mud through $5\frac{1}{2}$ " (38 sax displaced 20 sax cement through $5\frac{1}{2}$ " at 600', heavy mud to 150', displace 20 sax cement through $5\frac{1}{2}$ " at 150', heavy mud to 35', set rock and 10 say cement to bottom cellar.  Mudding and cementing by Globe Cementing Co.	8 5/8" at 227' circ	ulated with or	ment 0 5	<u>}" 3783</u>	31 wit	h 100	) anx	- C eme	nt.
displaced 20 sax cement through $5\frac{1}{2}$ " at 600. heavy mud to 150. displace 20 sax cement through $5\frac{1}{2}$ " at 150. heavy mud to 35. set rock and 10 sax cement to bottom cellar.  Mudding and cementing by Globe Cementing Co.		•	•				•		`
20 sax cement through $5\frac{1}{2}$ " at 150', heavy mud to 35', set rock and 10 second to bottom cellar.  Mudding and cementing by Globe Cementing Co.  Signed:	2995! 5½" to 6001.	circulated hol	e with her	a <b>v</b> y muć	l thro	nigh !	5글"	( 38	sex Go
Cement to bottom cellar.  Mudding and cementing by Globe Cementing Co.  Signed:	displaced 20 sax cer	ment through 5	<u> </u>	heav	7y mud	L to	150 <b>'</b> ,	diap	laced
Mudding and cementing by Globe Cementing Co.  Signed:	20 sax cement throu	gh 5½" at 150'	. heavy m	ad to 3	35¹, s	et r	ock ar	nd 10	SOX
Signed: Ledon Vett.	cement to bottom ce	llar.		•				· 	· ·
	Mudding and cementi	ng by Globe Ce	menting Co	٥.					
					,				
			Signed:		Les	land.	\frac{1}{2\pi}	<u>)                                    </u>	
Conservation Division Agent		•	2-8,1001	Co	merva	tion [	ivisi	on/Age	nt
Reviewed: Livin Brock Field Supervisor		Brock	, 				å	/	