

KCC OIL/GAS REGULATORY OFFICES

Date: 11/17/09

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5135
 Op Name: John O Farmer
 Address 1: 370 W Wichita Ave
 Address 2: P.O. Box 352
 City: Russell
 State: Kansas Zip Code: 67665 -2635
 Operator Phone #: (785) 483-4144

API Well Number: 15-135-24985-00-00
 Spot: SE-SW-SW-SW Sec 14 Twp 17 S Rng 25 E / W
 120 Feet from N / S Line of Section
 430 Feet from E / W Line of Section
 GPS: Lat: 38.56637 Long: 100.06424 Date: 11/17/09
 Lease Name: Mishler-Potter B Well #: 1
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None cement circulated

Persons Contacted:

Findings:

8-5/8" @ 221'W/150sxs cement
 TD @ 4500'
 5-1/2" @ 4498'W/125
 Port Collar @ 1776' cemented with 175sxs multi density- 2%cc-1/4# flo seal- 20sxs went to pit

Action/Recommendations:

Follow Up Required Yes No

Date: 7/14/09

Alt.II requirements have been met

RECEIVED

DEC - 3 2009

KCC DODGE CITY

RECEIVED

DEC 07 2009

KCC WICHITA

Verification Sources:

Photos Taken: _____

- RBDMS
- T-I Database
- Other: _____
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office
 Send 1 Copy to Conservation Division

Date: 11/17/09

District: 01

License #: 5135

Op Name: 5135

Spot: SE-SW-SW-SW Sec 14 Twp 17 S Rng 25 E W

County: Ness

Lease Name: Mishler-Potter B Well #: 1

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24985-00-00	120FSL 430FWL	SE-SW-SW-SW	38.56637-100.06424	1	New well, Alt. II completed