## KCC OIL/GAS REGULATORY OFFICES

Date: <u>02/09/10</u>	District: <u>01</u>
•	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
	45 000 04 000 00
Operator License No: 4058	API Well Number: <u>15-083-21,622-00-00</u>
Op Name: American Warrior	Spot: NE-NE-SE-SW Sec 11 Twp 21 S Rng 25 E / W
Address 1: P.O. Box 399	1150 Feet from N/ S Line of Section
Address 2: P.O. Box 783188	2560 Feet from E/W Line of Section
City: Garden City	GPS: Lat: 38.23589 Long: 100.03751 Date: 2/9/10
State: Kansas Zip Code: <u>67846 -0399</u>	Lease Name: Nuss Well #: 1
Operator Phone #: <u>(620) 587-3224</u>	County: Hodgeman
Reason for Investigation:	
Witness Alt.II	
Problem:	
None, cement circulated to surface	
Persons Contacted:	
Findings:	
8-5/8" @ 212W/150sxs cement	·
TD @ 4475'	
5-1/2" @ 4474'W/125sxs cement Port Collar @ 1551' cemented with 295sxs-s	md-1/4# flo seal-2%cc-15sxs went to nit
Collai @ 1331 Cemented with 2935x5-5	111d-174# 110 Seai-27000 103X3 Went to pit
	•
Action/Recommendations: Follow	w Up Required Yes No 🔊 Date:
Alt.II requirements have been met	RECEIVED KANSAS CORPORATION COMMISSION
FEB 2 2 2010	MAR <b>0 1</b> 2010
KCC DODGE CITY	CONSERVATION DIVISION WICHITA, KS
Verification Sources:	Photos Taken:
RBDMS KGS	TA Program
	Courthouse By: Michael Maier
Other:	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: <u>02/09/10</u>		_	District	: <u>01</u>		License #: <u>4058</u>
Op Name: <u>4058</u>			Spot: N	E-NE-SE-S	SW	Sec <u>11                                  </u>
County: Hodgeman			Lease Na	me: <u>Nuss</u>		Well #: 1
I.D. Sign Yes	No		<u>s</u>	Gas Venti	ing [	Yes No
Tank Battery Condition				Pits		·
Condition:	Questiona	ble Overflow	ving 🛅	Fluid Dep	th:	ft; Approx. Size:ft. xft.
Pits, Injection Site				Saltwa	ter Pi	pelines s
Fluid Depth:	_ft; Approx. S	Size:f	t. xft.	Leaks V	/isible	: Y N Tested for Leaks: Y N
Oil Spill Evidence				Flowin	ıg Hol	es
Abandoned Well	Potential Poll	ution Problem [	Yes No S	TA W	'ells	
				Monite	oring]	Records
Lease Cleanliness  Very Good S	Satisfactory	Poor Ver	y Bad			
SWD/ER Injection Well		•	Hodgeman 🔄	_		ons Yes No
Permit #: P Permit #: P						; T/C Annulus:; C/SP Annulus:
Permit #: P						; T/C Annulus:; C/SP Annulus:; T/C Annulus:; C/SP Annulus:;
Permit #:P			thorized: psi			; T/C Annulus: ; C/SP Annulus:
API		Spot				Well
Number	Footages	Location	GPS	W	ell#	Status
15-083-21,622-00-00	1150FSL 2560FWL	NE-NE-SE-SW	38.23589-100.0	3751 1		New well, Alt.II completed
						(°)
			701			. •
			1,000			,
·						
						,
						•