KCC OIL/GAS REGULATORY OFFICES

	New Situation	Lease Inspection							
		Licase hispection							
	Response to Request	t Complaint							
•	Follow-Up	Field Report							
Operator License No: 5144	API Well Number: 15-	135-25,025-00-00							
Op Name: Mull Drilling Company, Inc.	Spot: <u>NW-NE-SE-SE</u>	Sec 19 Twp 16 S Rng 22 E / ✓ W							
Address 1: 1700 N Waterfront Pkwy	_1266	Feet from N/ S Line of Section							
Address 2: Bldg. 12000	410	Feet from E/ W Line of Section							
City: Wichita	GPS: Lat: 38.64340	Long: 99.79123 Date: 2/18/10							
State: Kansas Zip Code: 67206 -6637	Lease Name: Wierman	Well #: <u>1-19</u>							
Operator Phone #: (316) 264-6365	County: Ness								
Reason for Investigation:									
Witness Alt.II									
Problem:									
None, cement circulated to surface									
Persons Contacted:									
Tersons Contacted.									
Findings:									
8-5/8" @ 220' W/150sxs cement	·								
TD @ 4550'									
5-1/2" @ 4542' W/125sxs cement									
Port Collar @ 1770' cement with 155sxs-smd-1/4# flo seal-2%cc-15sxs went to pit									
·									
Action/Recommendations: Follow	Up Required ✓Yes	No Date:							
Alt.II requirements have been met.		RECEIVED COMMISSION KANSAS CORPORATION COMMISSION							
		NANSAS CUTI O							
RECEIVED ()		MAR 0 1 2010							
FEB 2 2 2010		CERVATION DIVISION							
\		CONSERVATION DIVISION WICHITA, KS							
KCC DODGE CITY Verification Sources:		Photos Taken:							
	A Program								
	Courthouse By: _M	lichael Maier							

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>02/18/10</u>		_	District	: <u>01</u>		License #: <u>5144</u>	· · · · · · · · · · · · · · · · · · ·
Op Name: <u>5144</u>			Spot: <u>N</u>	<u>W-NE-SE-SE</u>	Sec <u>19</u> Tw	rp <u>16</u> S Rng <u>22</u>	E √ w
County: Ness			Lease Na	Lease Name: Well #: 1-19			·
I.D. Sign Yes	No		তি	Gas Venting [Yes No		n
Tank Battery Cond		ble Overflov	ving	Pits Fluid Depth:	ft; Appro	x. Size:ft. x	ft.
Pits, Injection Site	· · · · · · · · · · · · · · · · · · ·	,		Saltwater I	Pinelines	·	
Fluid Depth:	_ft; Approx.	Size:f	t. xft.	Leaks Visibl		Tested for Leaks:	Y N
Oil Spill Evidence				Flowing Ho	oles	•	
Abandoned Well	Potential Poll	ution Problem [Yes No 🔊	TA Wells			
Lease Cleanliness], [],	<u> </u>	Monitoring	Records		
Very Good	ressure – Actu ressure – Actu ressure – Actu	No al:psi; Au al:psi; Au al:psi; Au	thorized: psi	Tubing: Tubing: Tubing:	; T/C Annulus	No ; C/SP Ann	ulus: ulus:
API Number	Footages	Spot Location	GPS	Well#		Well Status	
1266FSL 15-135-25,025-00-00 410FEL NW-NE-SE-S		NW-NE-SE-SE	38.64340-99.79	123 1-19	New well, Alt.I	Lcompleted	***************************************
						10 g	
						1	\w
·						•	* A