DISTRICT CONSERVATION AGENT'S REPORT

R

TO:

15-195-00186-00-00

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

	4
· · · · · · · · · · · · · · · · · · ·	FILE NO.
	LOCATION SE SE SW
	SEC. 15 TWP. 12 ROE. 22
Dry Hole X Abandoned Oil Well _	Abandoned Gas Well
I have today completed supervision of	plugging of:
Well No. 1 Lease 01	lsen
Operator C & G Drg Co Ac	
FieldC	ounty decas
Total Depth 4103 Feet.	0
(Describe briefly the manner in	which the well was plugged)
3 5/8" at 210' circulated with ce	ement - $5\frac{1}{2}$ " at 4095! with
LOO sax cement behind.	
illed with chat to 4085, set 4	sax cement with dump bailer,
oulled 3347' $5\frac{1}{2}$ ", filled hole with	th mud to 210', set rock bridge
and 15 sax cement, filled with mu	ad to 35°, set rock and 10 sax ce
to bottom cellar.	
	adamatikus anakata peringa Mata di deriman perumanan anakata perumanan dan dan mengenakan dan deriman deriman
	MEBEIVER
and the second s	10-13-193903
	OCI I 3 1951
	Vichita, Kajago
Direction of the state of the s	District Conservation Acent

Date

10-10-51

PLUGGING
PLE SEC_15_T_12_R_22

MOOK PAGE_15_T_18_E_3