KCC OIL/GAS REGULATORY OFFICES

Date: <u>01/28/10</u>	District: _0	1	Case	#:			
	New S	ituation	Lease Insp	pection			
	Respo	nse to Request	Complain	t			
	Follow	v-Up	Field Rep	ort			
Operator License No: 4058	API Well N	umber: <u>15-135-25</u>	015-00-00				
Op Name: American Warrior	Spot: <u>S/2-</u>	SW-SE-NW Sec	2 Twp19	_S Rng <u>21</u>			
Address 1: P.O. Box 399	2570		Feet from	N/ S Line of Section			
Address 2: P.O. Box 783188	1650		Feet from	E / W Line of Section			
City: Garden City	GPS: Lat: _	38.42956 Lon	g: <u>100.61672</u>	Date: <u>1/28/10</u>			
State: Kansas Zip Code: 67846 -0399	Lease Name	: Ryersee		Well #: <u>1-SW2</u>			
Operator Phone #: (620) 587-3224	County: N	ess					
Reason for Investigation:							
Witness Alt.II							
Problem:							
None, cement circulated to surface							
Persons Contacted:							
				·			
Findings:				L			
8-5/8" @ 219W/150sxs cement							
TD @ 4210'							
5-1/2" @ 4209'W/175sxs cement							
Port Collar @ 1317' cemented with 100sxs-sn	na-1/4# 110	seal-2%cc-15s>	s went to pit	RECEIVED			
				FEB 0 8 2010			
·				KCC WICHITA			
Action/Recommendations: Follow	Up Required	Yes No [🗠 Date:				
Alt.II requirements have been met							
RECEIVED							
\							
FEB - 4 2010							
Verification Source DODGE CITY				Photos Taken:			
	A Program	By: Michael	Maier				
	ourthouse	≈,, <u>iviiciiaci</u>	Maioi	_			
Other:							

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>



Date: <u>01/28/10</u>		-	District:	01		License #: 4058
Op Name: 4058			Spot: <u>S/2</u>	2-SW-S	E-NW	Sec <u>2</u> Twp <u>19</u> _ S Rng <u>21</u> E 🕢 W
County: Ness			Lease Na	me: <u>Rye</u>	rsee	Well #: <u>1-SW2</u>
I.D. Sign Yes	No	· · · ·	. 9	Gas Vo	enting _	Yes No
Tank Battery Condi		le Overflow	ing .ɔ	Pits		ft; Approx. Size:ft. xft.
Pits, Injection Site	_ft; Approx. S	ize:ft	. xft.	$\boldsymbol{\vdash}$	twater Pi	pelines : Y N Tested for Leaks: Y N
Oil Spill Evidence				Flo	owing Hol	es
Abandoned Well	Potential Poll	ution Problem	Yes No 🗈	TA	A Wells	
Lease Cleanliness Very Good S	atisfactory -	Poor Very	v Bad	М	onitoring l	Records
SWD/ER Injection Well Permit #: Pr Permit #: Pr Permit #: Pr	Yes ressure – Acturessure – Acturessure – Acturessure – Acturessure – Actu	No al:psi; Aut al:psi; Aut al:psi; Aut	Ness psi thorized: psi thorized: psi	Tubin Tubin Tubin	g: g:	ions Yes No ; T/C Annulus: ; C/SP Annulus:
API Number	Footages	Spot Location	GPS		Well#	Well Status
15-135-25,015-00-00	2670FNL 1650FWL	S/2-SW-SE-NW	38.42956-100.6	31672	1-SW2	New well, Alt.II completed
						·