

KCC OIL/GAS REGULATORY OFFICES

Date: 12/17/09

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 31783

API Well Number: 15-101-22,207-00-00

Op Name: Mid-Continent Energy Operating Co.

Spot: NE-NW-NE-NW Sec 6 Twp 19 S Rng 27  E /  W

Address 1: 100W 5th St. Ste 450

180 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

1865 Feet from  E /  W Line of Section

City: Tulsa

GPS: Lat: 38.43788 Long: 100.45889 Date: 12/17/09

State: Ok Zip Code: 74103 -4254

Lease Name: Hineman Unit Well #: 1-6

Operator Phone #: (918) 587-6363

County: Lane

Reason for Investigation:

Witness Alt.II

Problem:

None cement circulated to surface.

RECEIVED

Persons Contacted:

DEC 31 2009

KCC WICHITA

Findings:

8-5/8" @ 306'W/  
TD. @ 4675'  
4-1/2 @ 4674'W/175sxs  
Port Collar @ 2205W/ 200sxs-smd-1/4# flo seal-2%cc-20sxs to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: 7/14/09

Alt.II requirements have been met.

RECEIVED

DEC 29 2009

KCC DODGE CITY

Verification Sources:

Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 12/17/09

District: 01

License #: 31783

Op Name: 31783

Spot: NE-NW-NE-NW Sec 6 Twp 19 S Rng 27  E  W

County: Lane

Lease Name: Hineman Unit Well #: 1-6

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Lane

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-101-22.207-00-00	180FNL 1865FWL	NE-NW-NE-NW	38.43788-100.45889	1-6	New well, Alt. II completed