DISTRICT CONSERVATION AGENT'S REPORT

TO:

	The state of the s
State Corporation Commission Conservation Division 211 North Broadway	FILE NO.
Wichita, Kansas	LOCATION SW SW NW
	SEC. 15 TWP. 10 RGE. 25 W
Dry Hole X Abandoned Oil We	Abandoned Gas Well
I have this date completed supervis	ion of plugging of:
Well No. lease	Knoll
Operator Herndon Drg Co	Address 423 Mayo Bldg Tulsa, Okla
Field	
Feet.	
Plugging Contractorsame	
Plugging Contractor's License No	
Address	
	e manner in which the well was plugged) ith cement.
Circulated home with heavy	mud, set cementing plug at 200', 1/2 sack
hulls and 15 sax cement thr	ough drill pipe, mud to 40', set cementing
plug, $1/2$ sack hulls and 10) sax cement to bottom cellar.
11-12-55 11-12-55 11-12-55	District Conservation Agent 11-10-55
	Date