

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. ✓

LOCATION S.E. 4, S.W. N.E

SEC. 15 TWP. 11 RGE. 18

Dry Hole Rotary Abandoned Oil Well — Abandoned Gas Well —

I have today completed supervision of plugging of:

Well No. 1 Lease McIntire

Operator Magda Oil Co Address Palace Bld. Tulsa, Okla

Field — County Ellis

Total Depth 3488 Feet.

(Describe briefly the manner in which the well was plugged)

Well was filled heavy mud 3488 to
340 ft permanent bridge cement
340 to 310 ft. 15 sacks. Heavy mud
310 to 10 ft. Cement into base of
cellar. 10 sacks. 65 ft 13 3/8 pipe.
1187 of 8 5/8 pipe cemented + left in
hole.

7-28-45

pd.
8/2/45
NA,
1,

15 11 18W
27 21

H.M. Ness
District Conservation Agent

Date July 25, 1945