

WELL COMPLETION FORM
WELL HISTORY - DESCRIPTION OF WELL & LEASE

OPERATOR: License # 7076

Name: Black Diamond Oil, Inc.

Address 1: PO Box 641

Address 2: _____

City: Hays State: KS Zip: 67601 + _____

Contact Person: Kenneth Vehige

Phone: (785) 625-5891

CONTRACTOR: License # 6426

Name: Express Well Service

Wellsite Geologist: None

Purchaser: Coffeyville Resources

Designate Type of Completion:

- New Well Re-Entry Workover
- Oil SWD SIOW
- Gas ENHR SIGW
- CM (Coal Bed Methane) Temp. Abd.
- Dry Other _____
(Core, WSW, Expl., Cathodic, etc.)

If Workover/Re-entry: Old Well Info as follows:

Operator: Bowman Oil Company

Well Name: Kellogg B #1

Original Comp. Date: 5/9/1977 Original Total Depth: 3440

Deepening Re-perf. Conv. to Enhr. Conv. to SWD

Plug Back: _____ Plug Back Total Depth _____

Commingled _____ Docket No.: _____

Dual Completion _____ Docket No.: _____

Other (SWD or Enhr.?) _____ Docket No.: _____

11/13/2009 12/15/2009 1/29/10
3/24/2010

Spud Date or Recompletion Date _____ Date Reached TD _____ Completion Date or Recompletion Date _____
KCC-10g

API No. 15 - 163-20694-00-01

Spot Description: SW-SW-SW

SW SW SW Sec. 23 Twp. 8 S. R. 19 East West

330 Feet from North / South Line of Section

330 Feet from East / West Line of Section

Footages Calculated from Nearest Outside Section Corner:

- NE NW SE SW

County: Rooks

Lease Name: Kellogg B Well #: 1

Field Name: Webster

Producing Formation: Arbuckle

Elevation: Ground: 1926 Kelly Bushing: 1931

Total Depth: 3440 Plug Back Total Depth: 3378

Amount of Surface Pipe Set and Cemented at: 259 Feet

Multiple Stage Cementing Collar Used? Yes No

If yes, show depth set: See Attachment A Feet

If Alternate II completion, cement circulated from: _____

feet depth to: _____ w/ _____ *W2-Dlg - 6/3/10*

Drilling Fluid Management Plan

(Data must be collected from the Reserve Pit)

Chloride content: 35,000 ppm Fluid volume: 80 bbls

Dewatering method used: Hauled to SWD

Location of fluid disposal if hauled offsite: _____

Operator Name: Black Diamond Oil, Inc.

Lease Name: Veverka License No.: 7076

Quarter NW Sec. 26 Twp. 8 S. R. 19 East West

County: Rooks Docket No.: D-22285

INSTRUCTIONS: An original and two copies of this form shall be filed with the Kansas Corporation Commission, 130 S. Market - Room 2078, Wichita, Kansas 67202, within 120 days of the spud date, recompletion, workover or conversion of a well. Rule 82-3-130, 82-3-106 and 82-3-107 apply. Information of side two of this form will be held confidential for a period of 12 months if requested in writing and submitted with the form (see rule 82-3-107 for confidentiality in excess of 12 months). One copy of all wireline logs and geologist well report shall be attached with this form. ALL CEMENTING TICKETS MUST BE ATTACHED. Submit CP-4 form with all plugged wells. Submit CP-111 form with all temporarily abandoned wells.

All requirements of the statutes, rules and regulations promulgated to regulate the oil and gas industry have been fully complied with and the statements herein are complete and correct to the best of my knowledge.

Signature: *Kenneth Vehige*

Title: _____ Date: _____

Subscribed and sworn to before me this 27th day of May

20 10

Notary Public: *Verda M. Brin*

Date Commission Expires: 7-18-2011



KCC Office Use ONLY

Letter of Confidentiality Received **RECEIVED**

If Denied, Yes Date: KANSAS CORPORATION COMMISSION

Wireline Log Received **JUN 01 2010**

Geologist Report Received

UIC Distribution **CONSERVATION DIVISION WICHITA, KS**

Operator Name: Black Diamond Oil, Inc. Lease Name: Kellogg B Well #: 1
 Sec. 23 Twp. 8 S. R. 19 East West County: Rooks

INSTRUCTIONS: Show important tops and base of formations penetrated. Detail all cores. Report all final copies of drill stems tests giving interval tested, time tool open and closed, flowing and shut-in pressures, whether shut-in pressure reached static level, hydrostatic pressures, bottom hole temperature, fluid recovery, and flow rates if gas to surface test, along with final chart(s). Attach extra sheet if more space is needed. Attach copy of all Electric Wireline Logs surveyed. Attach final geological well site report.

Drill Stem Tests Taken <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <i>(Attach Additional Sheets)</i> Samples Sent to Geological Survey <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Cores Taken <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Electric Log Run <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <i>(Submit Copy)</i> List All E. Logs Run: 5/11/1977 log	<input checked="" type="checkbox"/> Log Formation (Top), Depth and Datum <input type="checkbox"/> Sample <table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">Name</td> <td style="width:15%;">Top</td> <td style="width:15%;">Datum</td> </tr> <tr> <td>Anhydrite</td> <td>1332</td> <td>+599</td> </tr> <tr> <td>Heebner</td> <td>3068</td> <td></td> </tr> <tr> <td>Lansing KC</td> <td>3108</td> <td></td> </tr> <tr> <td>Arbuckle</td> <td>3358</td> <td></td> </tr> </table>	Name	Top	Datum	Anhydrite	1332	+599	Heebner	3068		Lansing KC	3108		Arbuckle	3358	
Name	Top	Datum														
Anhydrite	1332	+599														
Heebner	3068															
Lansing KC	3108															
Arbuckle	3358															

CASING RECORD <input type="checkbox"/> New <input type="checkbox"/> Used							
Report all strings set-conductor, surface, intermediate, production, etc.							
Purpose of String	Size Hole Drilled	Size Casing Set (In O.D.)	Weight Lbs. / Ft.	Setting Depth	Type of Cement	# Sacks Used	Type and Percent Additives
Surface	12 1/4	8 5/8	NA	259	Common	160	2 % Gel; 3%CC
Production	7 7/8	5 1/2	14 #	3439	Common	200	10% Salt

ADDITIONAL CEMENTING / SQUEEZE RECORD				
Purpose:	Depth Top Bottom	Type of Cement	#Sacks Used	Type and Percent Additives
<input type="checkbox"/> Perforate <input type="checkbox"/> Protect Casing <input type="checkbox"/> Plug Back TD <input type="checkbox"/> Plug Off Zone				See Exhibit A

Shots Per Foot	PERFORATION RECORD - Bridge Plugs Set/Type Specify Footage of Each Interval Perforated	Acid, Fracture, Shot, Cement Squeeze Record (Amount and Kind of Material Used)	Depth
2	3359.5-3369.5	1500 gals 20% NE	
			RECEIVED KANSAS CORPORATION COMMISSION JUN 01 2010 CONSERVATION DIVISION WICHITA, KS

TUBING RECORD: Size: <u>2 7/8</u> Set At: <u>3340</u> Packer At: <u>None</u> Liner Run: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Date of First, Resumed Production, SWD or Enhr. <u>1/29/2010</u> <u>3/24/10</u> <u>McC-Dlg</u> Producing Method: <input type="checkbox"/> Flowing <input checked="" type="checkbox"/> Pumping <input type="checkbox"/> Gas Lift <input type="checkbox"/> Other (Explain)
Estimated Production Per 24 Hours: Oil <u>4</u> Bbls. Gas <u>0</u> Mcf Water <u>10</u> Bbls. Gas-Oil Ratio Gravity <u>27</u>

DISPOSITION OF GAS: <input checked="" type="checkbox"/> Vented <input type="checkbox"/> Sold <input type="checkbox"/> Used on Lease <i>(If vented, Submit ACO-18.)</i>	METHOD OF COMPLETION: <input type="checkbox"/> Open Hole <input checked="" type="checkbox"/> Perf. <input type="checkbox"/> Dually Comp. <input type="checkbox"/> Commingled <input type="checkbox"/> Other (Specify) _____	PRODUCTION INTERVAL: _____ _____
--	---	--



BLACK DIAMOND OIL, INC

PO Box 641
Hays, KS 67601
(785) 625-5891

Exhibit A

Kellogg B #1

- 05/09/1977** - 5 ½ set @ 3439 and cmt with 200 sks common.
- 11/28/1990** - Plugged - perf @ 750', 1340' & 3164'. Pumped 350 sks cmt down 5 ½ + 600# hulls max 300# SIP 100#, pumped 100 sks down annulus @ max 300 # SIP 300#
- 11/11/2009** - Re-entry cmt from 10' to 3379'
- 12/17/2009** - Holes 1964-1996 squeeze with 75 sks common
Holes 1333-1365 squeeze with 40 sks common
Holes 798-1047 squeeze with 135 sks common
- 12/21/2009** - 798-1047 Re-squeeze with 250 sks common
- 12/30/2009** - 798-923 Re-squeeze with 175 sks common

RECEIVED
KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
WICHITA, KS

QUALITY OILWELL CEMENTING, INC.

Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 3603

Date	12/30/09	Sec.		Twp.		Range		County	Rooks	State	KS	On Location		Finish	3:00 PM	
Lease	Kellogg		Well No.	1		Location Zurich, 1E, 6 3/4 N, 1/2 E, N+W into										
Contractor	Express Well Service							Owner								
Type Job	Squeeze							To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.								
Hole Size	T.D.							Charge To								
Csg.	5 1/2"							Black Diamond								
Tbg. Size	2 7/8"							Street								
Tool	Reinhart							City								
Cement Left in Csg.	Shoe Joint							State								
Meas Line	Displace							The above was done to satisfaction and supervision of owner agent or contractor.								
EQUIPMENT							CEMENT									
Pumptrk	9	No.		Cementer	Paul		Amount Ordered									
Bulktrk	8	No.		Helper	Blake		200 ex Cam 3% CC									
Bulktrk	PV	No.		Driver	Doug		Common 200 @ 10 ⁰⁰									
JOB SERVICES & REMARKS							Poz. Mix									
Remarks: Sand Tagged at 970'							Gel.									
Holes 798' - 923'							Calcium 7 @ 42 ⁰⁰									
Spot S sx at 954'							Hulls									
Wash Clean at 923'							Salt									
923' - Spot 150 gal. Acid							Flowseal									
Breakdown - 4 Bbl./min, 600#							Handling 207 @ 2 ⁰⁰									
Spot 20sx at 923'							Mileage 450 ⁰⁰									
Wash Clean at 798'							FLOAT EQUIPMENT									
Packer at 704'							Guide Shoe									
Mix 175 sx							Centralizer									
Squeeze to 1000#							Baskets									
Wash Clean at 704'							AFU Inserts									
Pressure 5 1/2" to 500#																
							RECEIVED KANSAS CORPORATION COMMISSION									
							JUN 01 2010									
							CONSERVATION DIVISION WICHITA, KS									
Thank You!!							Pumptrk Charge									
							Squeeze 550 ⁰⁰									
							Mileage 37 @ 7 ⁰⁰									
							Tax									
							Discount									
							Total Charge									
Signature							Share (Signature)									

QUALITY OILWELL CEMENTING, INC.


Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 3602

Date	12/29/09	Sec.	Twp.	Range	County	State	On Location	Finish
Lease	Kellogg	Well No.	1	Location	Zurich	7N, 1E, 1/4S, 1/2E, N+W into		4:30 PM
Contractor	Express Well Service			Owner	To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.			
Type Job	Squeeze	Spot Sand			Charge To	Black Diamond		
Hole Size		T.D.						
Csg. Size	5 1/2"	Depth						
Tbg. Size		Depth						
Tool		Depth						
Cement Left in Csg.		Shoe Joint	The above was done to satisfaction and supervision of owner agent or contractor.					
Meas Line		Displace	CEMENT					
EQUIPMENT				Amount Ordered				
Pumptrk	No.	Cementer	Paul	Common				
Bulktrk	No.	Driver	Blake	Poz. Mix				
Bulktrk	No.	Driver	Neal	Gel.				
JOB SERVICES & REMARKS				Calcium				
Remarks:				Hulls				
Dump R Sand				Salt				
down 5 1/2"				Flowseal				
				18 Sand @ 12 ⁰⁰ 216 ⁰⁰				
				Handling 18 @ 2 ⁰⁰ 36 ⁰⁰				
				Mileage 100 ⁰⁰				
				FLOAT EQUIPMENT				
				Guide Shoe				
				Centralizer				
				Baskets				
				AFU Inserts				
RECEIVED KANSAS CORPORATION COMMISSION JUN 01 2010 CONSERVATION DIVISION WICHITA, KS				Pumptrk Charge				
				Spot Sand				
				Mileage 37 @ 4 ⁰⁰ 148 ⁰⁰				
				Tax				
				Discount				
				Total Charge				
Signature				Shane Vohgel				

Thank You



QUALITY OILWELL CEMENTING, INC.

No. 3702

Phone 785-483-2025
Cell 785-324-1041


Home Office P.O. Box 32 Russell, KS 67665

Date	12-21-09	Sec.	Twp.	Range	County	State	On Location	Finish
					Rooks	Kansas		2:30PM
Lease	Kellogg	Well No.	1		Location Zurich TN 1E 1S 1E 1/4			
Contractor	Express Well Service				Owner			
Type Job	Squeeze				To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.			
Hole Size	5 1/2				Charge To Black Diamond			
Csg.	2 3/8				Street			
Tbg. Size	2 3/8				City			
Tool	Reinhardt				State			
Cement Left in Csg.	Depth 704				The above was done to satisfaction and supervision of owner agent or contractor.			
Meas Line	Shoe Joint				CEMENT			
	Displace 40T 2 3/8 C				Amount Ordered 250 Com 3% CC			
EQUIPMENT					Common			
Pumptrk	1	No.	Cementer	Steve	Poz. Mix			
Bulktrk	8	No.	Driver	Brandon	Gel.			
Bulktrk		No.	Driver	Rocky	Calcium			
JOB SERVICES & REMARKS					Hulls			
Remarks:					Salt			
Holes 798-923 & 954-1047					Flowseal			
Packer @ 704 to squeeze					Handling			
Tng rate 1 BPM @ 800psi					Mileage			
Mix 250sx Hold 1100psi					FLOAT EQUIPMENT			
Wash Clean & come out of hole					Guide Shoe			
Shut in @ 500psi - 5 1/2 Swage					Centralizer			
					Baskets			
					AFU Inserts			
					Rumptrk Charge			
					Mileage			
					Tax			
					Discount			
					Total Charge			
Signature Blue V. [Signature]								

RECEIVED
KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
WICHITA, KS



QUALITY OILWELL CEMENTING, INC.

Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 3599

Date	12/16/09	Sec.	Twp.	Range	County	State	On Location	Finish	
Lease	Kellogg	Well No.	1	Location Zurich, 6N, 1E, 1/2N, 1/2E, N+W into					
Contractor	Express Well Service			Owner To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.					
Type Job	Squeeze			Charge To Black Diamond					
Hole Size	T.D.			Street					
Csg.	5 1/2"	Depth			City				State
Tbg. Size	2 3/8"	Depth			City				State
Tool	Depth			City					State
Cement Left in Csg.	Shoe Joint			The above was done to satisfaction and supervision of owner agent or contractor.					
Meas Line	Displace			CEMENT					
EQUIPMENT				Amount Ordered 250 s x Com 30/60					
Pumptrk	9	No.	Cementor Helper	Paul		Common			
Bulktrk	8	No.	Driver	Blake		Poz. Mix			
Bulktrk	PV	No.	Driver	Doug		Gel.			
JOB SERVICES & REMARKS				Calcium					
Remarks:				Hulls					
Plug at 3158'				Salt					
Spot Sand 2156'				Flowseal					
Hunt Holes				3 Sand @ Next Ticket					
Holes 1964' - 96'				# 3600					
Holes 1365' + ↑				Handling					
				Mileage					
RECEIVED				FLOAT EQUIPMENT					
KANSAS CORPORATION COMMISSION				Guide Shoe					
JUN 01 2010				Centralizer					
CONSERVATION DIVISION				Baskets					
WICHITA, KS				AFU Inserts					
<p style="font-size: 2em; opacity: 0.5;">Quality Oilwell Cementing</p> <p>Thank You!!!</p>				Pumptrk Charge 9 hrs pump & Testing 1025.00					
				Mileage 37 @ 7.00					
<p>X Signature <i>Shane Vahze</i></p>				Tax					
				Discount					
				Total Charge					

QUALITY OILWELL CEMENTING, INC.

Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 3600

Date	12/17/09	Sec.	Twp.	Range	County	State	On Location	Finish	7:15 PM
Lease	Keillogg	Well No.	1	Location	Zurich, 6 N, 1 E, 1/2 N, 1/2 E, N + W int.				
Contractor	Express Well Service				Owner: To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.				
Type Job	Squeeze				Charge To: Black Diamond				
Hole Size	5 1/2"				T.D.				
Csg. Size	2 7/8"				Depth				
Tbg. Size	Reinhart				Depth				
Tool	Reinhart				City				
Cement Left in Csg.	Shoe Joint				State				
Meas Line	Displace				The above was done to satisfaction and supervision of owner agent or contractor.				
EQUIPMENT					CEMENT				
Pumptrk	9	No.	Cement	Paul	Amount Ordered				
Bulktrk	8	No.	Driver	Blake	250 ex Com 3% CC				
Bulktrk	PV	No.	Driver	Doug	Common 250 @ 10 ⁰⁰				
JOB SERVICES & REMARKS					Gel.				
Remarks: Hunt Holes					Calcium 9 @ 42 ⁰⁰				
Holes - 798'-923', 954'-1047'					Hulls				
- 1333'-1365', 1964'-1996'					Salt				
1964'-1996' - Mix 75 sx, Squeeze to 1000#					Flowseal				
Packer at 1365'					Sand 2 @				
Packer at 1365' - Spot 40 sx					Handling 261 @ 2 ⁰⁰				
735' Wash Tool Clean					Mileage 700 ⁰⁰				
Packer - 704' - Mix 135 sx, Squeeze to 1000#									
Wash Tool Clean									
					FLOAT EQUIPMENT				
					Guide Shoe				
					Centralizer				
					Baskets				
					AFU Inserts				
RECEIVED KANSAS CORPORATION COMMISSION JUN 01 2010 CONSERVATION DIVISION WICHITA, KS									
Thank You!!					Pumptrk Charge 11 hrs x Testing pump & Squeeze 1025 ⁰⁰				
					Mileage N/A				
					Tax				
					Discount				
X Signature <i>Glenn V. [unclear]</i>					Total Charge				



Gaschler Pulling Service, Inc.
Kent Gaschler—Owner
785-650-7878

1811 Monroe P.O. Box 21
Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 3-19-10
Lease: DELLOGG Well #: 1 County: ROCKS State: KS
WORKOVER
Job description

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
	1	1 1/4 x 10'	Polish Rod			
	1	7'	Liner			
	2	2' x 6' x 7/8	Rod Subs			
	64	7/8 - 10 ON BOTTOM	Rods			
	66	3/4	Rods			
			Rods			
	1	2 1/2 x 1 1/2 x 12	Pump			
			Tubing Subs			
	104	2 7/8	Tubing			
			Tubing			
	1	S.N.	Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
	1	2 7/8 x 15'	Mud Anchor			

Y N Paint _____

Y N Diesel _____ GAL. _____ = _____

Thread Dope 5 x 3 Each 15

Circ Rubber New _____ (Used) 50

Circ Head 75

Y N Sand Pump _____

Y N Oil Saver Rubber _____

Y N Swab Cup _____

Y N Other _____

Unit RIG 1 DDP

Operator KENT G

Floorman MIKE H

Floorman MATT D

Hrs.	Per. Hr	Amount
8	90	\$720
8	30	\$240
8	25	\$200
8	25	\$200
Extra Equip.		\$140
Sales Tax		79.50
TOTAL		1579.50

RECEIVED
KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
WICHITA, KS

Remarks: MOVED IN & RIGGED UP - UNHUNG WELL & LATCHED ONTO
RODS. UNSEATED PUMP. PULLED RODS & PUMP. RIGGED OVER FOR
TUBING. LAID TUBING OUT. TALLED PACKER & TUBING IN HOLE.
SET PACKER @ 3302' & SHUT DOWN.

By: Kent Gaschler
Gaschler Pulling Service, Inc.

By: _____
Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 3-22-10
 Lease: HELLO Well #: 1 County: ROCKS State: KS
 WORKOVER
 Job description _____

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber 1 @ \$15
 Y N Swab Cup 1-2 7/8 @ \$25
 Y N Other _____

Unit BIG 1 DDP
 Operator KENT G
 Floorman MIKE H
 Floorman MATT D

Hrs.	Per. Hr	Amount
5 1/2	90	\$495
5 1/2	30	\$165
5 1/2	25	\$137.50
5 1/2	25	\$137.50
		Extra Equip. \$40
		Sales Tax 51.67
		TOTAL 1026.67

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Remarks: DID NOT GET CHEMICAL SQUEEZE DONE OVER WEEKEND.
SWABBED DOWN. GOT READY TO PUMP CHEMICAL DOWN. WAS
GOING SLOW. GOT ORDERS TO SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIA Date: 3-23-10
 Lease: KELLOGG Well #: 1 County: ROOKS State: KS
WORKOVER
 Job description

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 N Oil Saver Rubber 1 @ \$15
 N Swab Cup 1-2 7/8 @ \$25
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
RIG 1 DDP	8 1/2	90	\$765
Operator KENT G	8 1/2	30	\$255
Floorman MIKE H	8 1/2	25	\$212.50
Floorman MAT D	8 1/2	25	\$212.50

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Extra Equip.	\$40
Sales Tax	78.71
TOTAL	1563.71

Remarks: STARTED SWABBING @ 10:30. MADE 3 PULLS THEN RELEASED PACKER & LET SWING. SWAPPED DOWN TO 2600' THEN SET PACKER. TAGGED FLUID @ 2600' & LET SET 45 MIN. TAGGED @ 2400'. SWAPPED DOWN THEN DID 4 - 1 HOUR TESTS. FLUID STARTED @ 550' THEN WENT DOWN TO 400'. HAD 35% OIL. SHOT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL

Date: 5-24-10

Lease: WELLDGG

Well #: 1

County: ROOFS

State: KS

WORKOVER

Job description

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod		1	1 1/4 x 16'
			Liner		1	7'
			Rod Subs		2	2' x 6' x 7/8
			Rods		164	7/8-10 ON BOTTOM
			Rods		166	3/4
			Rods			
			Pump		1	2 1/2 x 1 1/2 x 12
			Tubing Subs			
			Tubing		104	2 7/8
			Tubing			
			Bbl. Seat N		1	S.N.
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor		1	2 7/8 x 15'

Y N Paint _____

Y N Diesel _____ GAL. _____ = _____

Thread Dope 5 x 3 Each 15

Circ Rubber New _____ Used _____

Y N Circ Head _____

Y N Sand Pump _____

DN Oil Saver Rubber 10 @ 15

DN Swab Cup 1-2 7/8 @ 25

Y N Other _____

Unit REG 1 DDP
 Operator KENT G
 Floorman MIKE H
 Floorman MATT D

Hrs.	Per. Hr	Amount
9	90	\$810
9	30	\$270
9	25	\$225
9	25	\$225
		Extra Equip. \$55
		Sales Tax 84.01
		TOTAL 1669.01

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Remarks: CHECKED OVERNITE FILLUP. FLUID WAS @ 2150'. PULLED 1000' + HAD 50% OIL. MADE 1 PULL OFF BOTTOM THEN DID 2-1 HOUR TESTS. HAD 450' + 400' WITH 23% OIL. PULLED PACKER + GOT READY TO RUN IN FOR PRODUCTION. RAN TUBING IN + LANDED. RIGGED OVER FOR RODS. RAN NEW PUMP + RODS. SEATED PUMP + LONGSTROKED. HUNG ON, RIGGED DOWN + MOVED OFF.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 1-26-10
 Lease: KELLOGG Well #: 1 County: ROCKS State: KS
 Job description: RUN IN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
	105	2 7/8	Tubing	104		2 7/8
			Tubing			
			Bbl. Seat N		1	5 N
	1	Where Set 1/2 OFF BOTTOM Type MODEL R Size 2 7/8 x 5 1/2	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor		1	2 7/8 x 15'

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope 5 x 3 Each #15
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit BIG IDDP
 Operator KENT G
 Floorman MICHAEL H
 Floorman MATT D

Hrs.	Per. Hr	Amount
5	90	\$450
5	30	\$150
5	25	\$125
5	25	\$125
	Extra Equip.	\$15
	Sales Tax	45.85
	TOTAL	910.85

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Remarks: MOVED IN + RIGGED UP TO TUBING HOLE. GOT READY TO PULL TUBING + PACKER. PULLED SLIPS + RELEASED PACKER. LAID OUT. GOT READY TO RUN IN FOR PRODUCTION. RAN TUBING IN BUT DID NOT LAND. SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 1-27-20
 Lease: DELLOGG Well #: 1 County: ROCK State: KS
 Job description: Run In

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod		1	1 1/4 x 16'
			Liner		1	2'
			Rod Subs		1	6' x 7/8"
			Rods		64	7/8" - 10 On Bottom
			Rods		66	3/4"
			Rods			
			Pump		1	2 1/2 x 1 1/2 x 12
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope 5 x 3 Each # 15
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
<u>BIG 1 DDP</u>	<u>11 1/2</u>	<u>90</u>	<u>\$1035</u>
Operator <u>KENT G</u>	<u>11 1/2</u>	<u>30</u>	<u>\$345</u>
Floorman <u>MICHAEL H</u>	<u>11 1/2</u>	<u>25</u>	<u>\$287.50</u>
Floorman <u>MATT D</u>	<u>11 1/2</u>	<u>25</u>	<u>\$287.50</u>
Extra Equip.			<u>\$15</u>
Sales Tax			<u>104.41</u>
TOTAL			<u>2074.41</u>

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Remarks: LANDED TUBING & RIGGED OVER FOR RODS. REMOVED CAPS & PUT ON BOXES. STARTED RUNNING PUMP & RODS. GOT 95 RODS IN & HIT TIGHT SPOT. COULD NOT GET PUMP THROUGH. RIGGED UP TO ROD HOLE & PULLED RODS. RIGGED OVER FOR TUBING. LAID TUBING OUT THEN RAN RABBIT. FOUND 1 BAD JT. LANDED TUBING & RIGGED BACK OVER FOR RODS. RAN PUMP & RODS. SPACED OUT & SEATED PUMP. SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 1-28-10
 Lease: KELLOGG Well #: 1 County: ROOS State: KS
 Job description: Run in

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
RIG 1 DDP	1 1/2	90	\$ 135
Operator KENT G	1 1/2	30	\$ 45
Floorman MICHAEL H	1 1/2	25	\$ 37.50
Floorman MATT D	1 1/2	25	\$ 37.50
Extra Equip.			
Sales Tax			13.51
TOTAL			268.51

Remarks: DROVE TO LOCATION. RIGGED DOWN & MOVED OFF.

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-11-09
 Lease: KELLOGG Well #: B#1 County: ROCKS State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
RIG 1 DDP	2	90	180
Operator KENT G	2	30	60
Floorman MICHAEL H	2	25	50
Floorman LUKE K	2	25	50
Extra Equip.			
Sales Tax			18.02
TOTAL			358.02

Remarks: MOVED IN + RIGGED UP TO TUBING HOLE. GOT READY TO WASH WELL DOWN + SHUT DOWN.

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 1 2010

REGISTRATION DIVISION
 TOPIKA, KS

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-13-09
 Lease: HELLOGG Well #: 13#1 County: ROCKS State: KS
WASH DOWN
 Job description

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used 50
 N Circ Head 75
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
REG 1 DDP	10 1/2	90	\$945
Operator KENT G	10 1/2	30	\$315
Floorman MICHAEL H	10 1/2	25	\$262.50
Floorman LUKE K	10 1/2	25	\$262.50

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Extra Equip.	\$125
Sales Tax	101.23
TOTAL	2011.23

Remarks: REGGED UP GOLDEN B. LINED PIT. AFTER GOT LOAD OF WATER IN PIT, WE STARTED DRILLING. TAGGED 10' DOWN. GOT THROUGH THAT SPOT. HIT A FEW SPOTS OF CEMENT + WOOD. GOT DOWN TO 100' + STARTED BOUNCING LIKE ON METAL. PULLED OUT + RAN A TAR BLOCK. RAN A 4' MILL. MADE 4' + PULLED OUT. HAD CEMENT IN + A DIG BIT. RAN BIT BACK IN. DRILLED SMOOTH. PULLED UP + SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-16-09
 Lease: KELLN066 Well #: B #1 County: ROCKS State: KS
WASH DOWNS
 Job description

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit Big 1 DDP
 Operator KENT G
 Floorman MICHAEL H
 Floorman LUKE K

Hrs.	Per. Hr	Amount
10 1/2	90	\$945
10 1/2	30	\$315
10 1/2	25	\$262.50
10 1/2	25	\$262.50

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Extra Equip.	
Sales Tax	94.61
TOTAL	1819.61

Remarks: STARTED DRILLING. RETURNS LOOKED LIKE REDT-MIX CEMENT. HAD ALOT OF SAND. DRILLED HALF DAY & WAS VERY HARD. PULLED BIT & RAN DIFFERENT ROCK BIT & 1 COLLAR. STILL DRILLED HARD. CIRCULATED CLEAN @ 180'. PULLED UP 1 FT. & SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-17-09
 Lease: HELLOGO Well #: B #1 County: ROCKS State: KS
 Job description: WASH Down

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit RIG 1 DDP
 Operator KENT G
 Floorman MICHAEL A
 Floorman LUKE K

Hrs.	Per. Hr	Amount
11	90	\$990
11	30	\$330
11	25	\$275
11	25	\$275

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Extra Equip.	
Sales Tax	99.11
TOTAL	1969.11

Remarks: PULLED BIT & RAN NEW BOTTOM BIT. HAD TO REAM DOWN ABOUT 40'. BOTTOM BIT DRILLED A LITTLE FASTER. DRILLED DOWN TO APPROXIMATELY 320'. CIRCULATED CLEAN & SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-18-09
 Lease: BELOGG Well #: B#1 County: ROCKS State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit RIG 1 DDP
 Operator KENT G
 Floorman MICHAEL H
 Floorman LUKE K

Hrs.	Per. Hr	Amount
11	90	\$990
11	30	\$330
11	25	\$275
11	25	\$275
Extra Equip.		
Sales Tax		99.11
TOTAL		1969.11

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Remarks: WENT BACK TO DRILLING. STARTED TO DRILL A LITTLE BETTER. AROUND 450' STARTED JUMPING + DRILLING ROUGH. CIRCULATED CLEAN + PULLED BIT. RAN IN WITH SHORT MILL. MADE 3' + CAME OUT. HAD NOTHING. SHUT DOWN.

By: Kent Gasella
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
Kent Gaschler—Owner
785-650-7878

1811 Monroe P.O. Box 21
Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-19-09
Lease: NEURGG Well #: B #1 County: ROCKS State: KS
Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
Y N Diesel _____ GAL. _____ = _____
Thread Dope _____ x _____ Each _____
Circ Rubber New _____ Used _____
Y N Circ Head _____
Y N Sand Pump _____
Y N Oil Saver Rubber _____
Y N Swab Cup _____
Y N Other _____

Unit RIG 1 DDP
Operator KENT G
Floorman MICHAEL H
Floorman LUKE K

Hrs.	Per. Hr	Amount
11	90	\$990
11	30	\$330
11	25	\$275
11	25	\$275
Extra Equip.		
Sales Tax		99.11
TOTAL		1969.11

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 01 2010
CONSERVATION DIVISION
WICHITA, KS

Remarks: DROVE TO P. VILLE & GOT AN 18' JS OF WASH PIPE. GOT TO LOCATION & RAN WASH PIPE WITH DIFFERENT SHOE ON BOTTOM. DRILLED VERY ROUGH. PULLED OUT & HAD NOTHING. RAN TAR BLOCK & MAGNET ON SANDLINE. NEXT RAN WASH PIPE WITH DIFFERENT BOTTOM. CAME OUT & HAD NOTHING. RAN COMPANY MILL. SECOND RUN CAME OUT WITH A 4" PIECE OF 3/4 ROD. SHUT DOWN.

By: Kent Gaschler
Gaschler Pulling Service, Inc.

By: _____
Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: Black Diamond Oil Date: 11-20-09
 Lease: Hellsgg Well #: D #1 County: ROCKY State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
<u>REG DDP</u>	<u>10 1/2</u>	<u>90</u>	<u>\$945</u>
<u>Operator: KENT G</u>	<u>10 1/2</u>	<u>30</u>	<u>\$315</u>
<u>Floorman: MICHAEL H</u>	<u>10 1/2</u>	<u>25</u>	<u>\$262.50</u>
<u>Floorman: LUKE K</u>	<u>10 1/2</u>	<u>25</u>	<u>\$262.50</u>

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Extra Equip.	
Sales Tax	<u>94.61</u>
TOTAL	<u>1879.61</u>

Remarks: RAN IN WITH ROCK BIT + 1 COLLAR. STARTED DRILLING ON CEMENT. MADE ABOUT 20' THEN STARTED BOUNCING AGAIN. ALSO STARTED TO SEE METAL IN THE RETURNS. PULLED BIT + RAN IN WITH METAL MUNCHER. TAGGED + STARTED DRILLING. NEVER JUMPED OR ACTED LIKE WAS ON METAL. MADE 14' CIRCULATED CLEAN, HUNG SWIVEL, PICKED UP + SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-23-09
 Lease: NECLOGG Well #: B-21 County: ROCKY State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit RIG 1 DDP
 Operator KENT G
 Floorman MICHAEL H
 Floorman MATT D

Hrs.	Per. Hr	Amount
11	90	\$990
11	30	\$330
11	25	\$275
11	25	\$275
Extra Equip.		
Sales Tax		99.11
TOTAL		1969.11

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Remarks: PULLED METAL MUNCHER BIT. RAN 3 COLLARS & BUTTON BIT + WENT BACK TO DRILLING. DRILLED VERY SLOW BUT CEMENT SEEMED TO BE VERY SOFT. CIRCULATED CLEAN & PULLED BUTTON BIT. RAN IN WITH NEW ROCK BIT. DRILLED A LITTLE FASTER BUT WAS SEEING METAL. MADE TOTAL OF 75.' CIRCULATED CLEAN, PULLED UP & SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-24-09
 Lease: BELOGG Well #: B #1 County: ROCKS State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
RIG / DDP	11	90	\$990
Operator KENT G	11	30	\$330
Floorman MICHAEL H	11	25	\$275
Floorman MATT D	11	25	\$275
Extra Equip.			
Sales Tax			99.11
TOTAL			1969.11

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Remarks: WENT BACK TO DRILLING. SOMETIMES WOULD DRILL 7-8 MINUTES
A FOOT + SOMETIMES 1 TO 2 MINUTES. PULLED BIT LATE IN THE
AFTERNOON. HAD A BIT WEDGED IN CONES. RAN MAGNET ON
SAMPLING TWICE + GOT OUT SMALL CHUNKS OF IRON. RAN
BIT BACK IN + SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-25-09
 Lease: KELLOGG Well #: D # 1 County: ROOKS State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
RIG / DDP	8 1/2	90	\$ 765
Operator KENT G	8 1/2	30	\$ 255
Floorman MICHAEL H	8 1/2	25	\$ 212.50
Floorman MATT D	8 1/2	25	\$ 212.50
Extra Equip.			
Sales Tax			76.59
TOTAL			1521.59

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Remarks: HOOKED UP SWIVEL & WENT BACK TO DRILLING. DRILLED HARD BUT SMOOTH & DID NOT SEE ANY MORE IRON. MADE ABOUT 100' CIRCULATED CLEAN, PACKED UP & SHUT DOWN.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature



Gaschler Pulling Service, Inc.
 Kent Gaschler—Owner
 785-650-7878

1811 Monroe P.O. Box 21
 Ellis, KS 67637

Company: BLACK DIAMOND OIL Date: 11-30-09
 Lease: NEEDGE Well #: 5th 1 County: BOONVILLE State: KS
 Job description: WASH DOWN

Pulled From Well

Reran In Well

Feet	Joints	Description	Equipment	Feet	Joints	Description
			Polish Rod			
			Liner			
			Rod Subs			
			Rods			
			Rods			
			Rods			
			Pump			
			Tubing Subs			
			Tubing			
			Tubing			
			Bbl. Seat N			
		Where Set Type Size	Packer or Tubing Anchor			Where Set Type Size
			Mud Anchor			

Y N Paint _____
 Y N Diesel _____ GAL. _____ = _____
 Thread Dope _____ x _____ Each _____
 Circ Rubber New _____ Used _____
 Y N Circ Head _____
 Y N Sand Pump _____
 Y N Oil Saver Rubber _____
 Y N Swab Cup _____
 Y N Other _____

Unit	Hrs.	Per. Hr	Amount
RIG 1 DDP	2 1/2	90	\$ 225
Operator KENT G	2 1/2	30	\$ 75
Floorman MICHAEL M	2 1/2	25	\$ 62.50
Floorman MATT D	2 1/2	25	\$ 62.50

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Extra Equip.	
Sales Tax	22.52
TOTAL	447.52

Remarks: GOT TO LOCATION. RIGGED DOWN GOLDEN B. PULLED TUBING + COLLARS.
RIGGED DOWN. LOADED ALL EQUIPMENT + MOVED OFF.

By: Kent Gaschler
 Gaschler Pulling Service, Inc.

By: _____
 Authorized Signature

No: 07342

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-2 200 9
 Lease Kellogg B' Well # 1 Co. KANSAS
 Directions Zurich 1 E 7N 1/4 E TO T.B. N. into
follow lease rd. N.W. down draw to well.
 Job Description Wash down Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Paint _____
- Diesel _____ Gal x _____ = _____
- Thread Dope 3 # \$4.55 each = \$13.65 (T)
- Stuff Box Rub _____
- Fishing Tool _____
- Circ Head \$75.00
- Circ Rubber New 2 7/8 Used \$172.00 (T)
- Packer (type) _____
- Plug _____
- Sand Pump _____
- Swab Equip _____
- Oil Saver Rub _____
- Swab Cups _____

Unit Rig # G
 Operator Luis F
 Floorman PAT F
 Floorman CHRIS J

Hrs.	Per Hr.	Amount
12	8900	1068.00
12	3200	384.00
12	2800	336.00
12	2800	336.00
EXTRA EQUIP		260.65
SALES TAX		9.84
TOTAL		2394.49

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION WICHITA, KS

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____

Results: _____
Items used from Express: _____

Items used from other suppliers: Golden 'B' Drilling equip.

Remarks: M.I.R.U. Ran in hole w/ 4 7/8 drill bit G-drill collars and tbg tagged cement @ 798' rigged up pump & swivel got circ. the long way, drilled down to 1054' circ clean, pulled up 1 jt, cleaned tools, shut down

By: Luis F. Ferrandez
Express Well Service & Supply, Inc.

"Thank You"

By: _____
Authorized Signature

No. 07343

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond

Date 12-3

200 9

lease Kellogg 'B'

Well # 1

Co. _____

KANSAS

Directions _____

Job Description	Cause of Failure	No. of Rods or Joints Deep	Size and Type of Replacement (new) (used)
-----------------	------------------	----------------------------	---

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Paint _____
- Diesel _____ Gal x _____ = _____
- Thread Dope 2 # \$4.55 each = \$9.10 (+)
- Stuff Box Rub _____
- Fishing Tool _____
- Circ Head _____
- Circ Rubber New _____ Used _____
- Packer (type) _____
- Plug _____
- Sand Pump _____
- Swab Equip _____
- Oil Saver Rub _____
- Swab Cups _____

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION WICHITA, KS

Unit Big # 6
 Operator Luis F.
 Floorman PAT F.
 Floorman CHRIS J.

Hrs.	Per Hr.	Amount
11	8900	979.00
11	3200	352.00
11	2800	308.00
11	2800	308.00
EXTRA EQUIP		9.10
SALES TAX		1.48
TOTAL		1956.58

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D.I.H. Got circ started drilling @ 1064, circ. the short way drilled down to 1375' circ. clean, pulled up 1jt cleaned tools, shut ↓

By: Luis Aubeart Tex. A1022

Express Well Service & Supply, Inc. "Thank You"

By: _____ Authorized Signature

No. 07344

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-4 2009
Lease Kellogg B Well # 1 Co. KANSAS
Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- Paint
Diesel Gal x =
Thread Dope 2 # 14.55 each = 29.10 (T)
Stuff Box Rub
Fishing Tool
Circ Head
Wire Rubber: New Used
Packer (type)
Plug
Sand Pump
Swab Equip
Oil Saver Rub
Swab Cups

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 01 2010
CONSERVATION DIVISION
WICHITA, KS

Unit Rig # 6
Operator Luis F.
Floorman PAT F.
Floorman Chris J.

Table with columns: Hrs., Per Hr., Amount. Includes rows for 11 hrs at 89.00, 11 hrs at 32.00, 11 hrs at 28.00, 11 hrs at 28.00, EXTRA EQUIP 9.10, SALES TAX 48, TOTAL 1956.58.

Table with columns: Bad, Replacements. Includes rows for # jts, # rods, Rod Boxes Replaced 3/4", 7/8", 1".

Testing tbg: Who tested:
Results:
Items used from Express:

Items used from other suppliers:

Remarks: D.I.B. Got circ started drilling @ 1377' got down 1657' circ. clean pulled up 1jt cleaned tools, shut down.

By: Luis Antonio FERNANDEZ Express Well Service & Supply, Inc. "Thank You"
By: Authorized Signature

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

No: 07346

Company Blick Diamond Date 12-7 200 9
 Lease Kellogg 'B' Well # 1 Co. KANSAS
 Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Paint _____
- Diesel _____ Gal x _____ = _____
- Thread Dope 2 # \$4.55 each = \$9.10 (T)
- Stuff Box Rub _____
- Fishing Tool _____
- Circ Head _____
- Wire Rubber - New _____ Used _____
- Packer (type) _____
- Plug _____
- Sand Pump _____
- Swab Equip _____
- Oil Saver Rub _____
- Swab Cups _____

Unit Rig #6
 Operator Lus F.
 Floorman Pat F.
 Floorman Chris J.

Hrs.	Per Hr.	Amount
11	8900	979.00
11	3200	352.00
11	2800	308.00
11	2800	308.00
EXTRA EQUIP		9.10
SALES TAX		48
TOTAL		1956.58

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____
 Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D.J.L. Got circ. started drilling @ 1654' drilled down to 1937' circ. clean pulled up 1st. cleaned tools, shut v

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No. 07348

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-9 2009
Lease Kellogg B Well # 1 Co. KANSAS
Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- Paint
Diesel Gal x =
Thread Dope 3 # \$4.55 each = \$13.65 (T)
Stuff Box Rub
Fishing Tool
Circ Head
Circ Rubber New 2 7/8 Used \$172.00 (T)
Packer (type)
Plug
Sand Pump
Swab Equip
Oil Saver Rub
Swab Cups

RECEIVED KANSAS CORPORATION COMMISSION JUN 01 2010 CONSERVATION DIVISION WICHITA, KS

Unit Rig # 6
Operator Luv F
Floorman Pat F
Floorman Chris J

Table with columns: Hrs., Per Hr., Amount. Includes rows for 5 1/2 hrs at 89.00 (489.50), 5 1/2 hrs at 32.00 (176.00), 5 1/2 hrs at 28.00 (154.00), 5 1/2 hrs at 28.00 (154.00), EXTRA EQUIP (185.65), SALES TAX (9.85), TOTAL (1169.00).

Table for Bad Replacements with columns for # jts, # rods, and Rod Boxes Replaced (3/4, 7/8, 1).

Testing tbg: Who tested:
Results:
Items used from Express:

Items used from other suppliers:

Remarks: D.I.H. pulled bit O.O.H. ran back in w/ another used bit that was setting here on bc and put a new circ. rubber. cleaned tools, shut off.

By: [Signature] Express Well Service & Supply, Inc. "Thank You"
By: [Signature] Authorized Signature

No: 07349

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-10 200 9

Lease Kellogg 'B' Well # 1 Co. KANSAS

Directions _____

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Rows include Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- (N) Paint
(N) Diesel Gal x =
Thread Dope 2 # \$4.55 each = \$9.10 (T)
(N) Stuff Box Rub
(N) Fishing Tool
(N) Circ Head
(N) Rubber New Used
(N) Packer (type)
(N) Plug
(N) Sand Pump
(N) Swab Equip
(N) Oil Saver Rub
(N) Swab Cups

Unit Rig # 6
Operator Leo F.
Floorman Pat
Floorman Chris J.

Table with columns: Hrs., Per Hr., Amount. Rows for 10 1/2 hrs at 89.00, 32.00, 28.00, 28.00. Includes EXTRA EQUIP 9.10, SALES TAX 1.48, TOTAL 1868.08.

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 01 2010
WICHITA, KS

Table for Replacements: # jts, # rods, Rod Boxes Replaced 3/4", 7/8", 1"

(N) Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D.I.H. got circ started drilling @ 1937' drilled down to 2193' circ clean, pulled up 1jt cleaned tools, shut

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No. 07350

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-10 200 9
Lease Kellogg B Well # 1 Co. KANSAS
Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- Paint
Diesel Gal x =
Thread Dope 2 1/2 # \$4.55 each = \$11.38 (T)
Stuff Box Rub
Fishing Tool
Circ Head
Circ Rubber New Used
Packer (type)
Plug
Sand Pump
Swab Equip
Oil Saver Rub
Swab Cups

Unit Rig # 6
Operator Gus F.
Floorman Pat
Floorman Chris J

Table with columns: Hrs., Per Hr., Amount. Includes rows for 11 1/2 hrs at 8900, 3200, 2800, 2800 and totals for EXTRA EQUIP (11 38), SALES TAX (60), TOTAL (2047.48).

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

WICHITA, KS

Table for Bad Replacements with columns for # jts and # rods. Includes row for Rod Boxes Replaced 3/4", 7/8", 1".

Testing tbg: Who tested:
Results:
Items used from Express:

Items used from other suppliers:

Remarks: D.I. got circ started drilling @ 2193' drilled down to 2607' circ clean pulled up 1jt cleaned tools shut v

By: Express Well Service & Supply, Inc. "Thank You" By: Authorized Signature

No: 10551

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond

Date 12-12

200 9

Case Kellogg 'B'

Well # 1

Co.

KANSAS

Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- (N) Paint
(N) Diesel Gal x =
Thread Dope 1/2 # \$4.55 each = \$6.83 (T)
(N) Stuff Box Rub
(N) Fishing Tool
(N) Circ Head
Circ Rubber New Used
(N) Packer (type)
(N) Plug
(N) Sand Pump
(N) Swab Equip
(N) Oil Saver Rub
(N) Swab Cups

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

WICHITA, KS

Unit Rig #6
Operator Luis F.
Floorman PAT F.
Floorman Chris S

Table with columns: Hrs., Per Hr., Amount. Includes rows for 6 1/2 hrs at 8900, 6 1/2 hrs at 3200, 6 1/2 hrs at 2800, 6 1/2 hrs at 2800, EXTRA EQUIP 6.83, SALES TAX 36, TOTAL 1157.69.

Table with columns: Bad, Replacements. Includes rows for # jts, # rods, Rod Boxes Replaced 3/4", 7/8", 1".

Testing tbg: Who tested:

Results:

Items used from Express:

Items used from other suppliers:

Remarks: D.I. got circ started drilling @ 2607' drilled down to 2858, circ clean pulled up 1st, cleaned tools, shut off.

By: [Signature]

Express Well Service & Supply, Inc.

"Thank You"

By:

Authorized Signature

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

No: 10552

Company Black Diamond Date 12-14 200 9
 Lease Kellogg B Well # 1 Co. KANSAS
 Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Paint _____
- Diesel _____ Gal x _____ = _____
- Thread Dope 2 1/2 # \$4.55 each = \$11.38 (T)
- Stuff Box Rub _____
- Fishing Tool _____
- Circ Head _____
- Wire Rubber - New _____ Used _____
- Packer (type) _____
- Plug _____
- Sand Pump _____
- Swab Equip _____
- Oil Saver Rub _____
- Swab Cups _____

Unit Rig # 6
 Operator Law F.
 Floorman Pat F.
 Floorman Chris M.

Hrs.	Per Hr.	Amount
11	8900	979.00
11	3200	352.00
11	2800	308.00
11	2800	308.00
EXTRA EQUIP		11.38
SALES TAX		.60
TOTAL		1958.98

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 DIVISION
 WICHITA, KS

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____
 Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D.I.H. got circ. started drilling @ 2858, drilled down to 3240' circ. clean, pulled 4 jts, clean tools, shut in.

By: Lucy Adams Terhune By: _____
 Express Well Service & Supply, Inc. "Thank You" Authorized Signature

No. 10553

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond

Date 12-15

200 9

Lease Kellogg 'B'

Well # 1

Co. _____

KANSAS

Directions _____

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Rows include Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- (N) Paint
(N) Diesel Gal x =
Thread Dope # each = \$4.55 (T)
(N) Stuff Box Rub
(N) Fishing Tool
(N) Circ Head
(N) Packer (type)
(N) Plug
(N) Sand Pump
(N) Swab Equip
(N) Oil Saver Rub
(N) Swab Cups

Unit Rig # 6
Operator Luz F.
Floorman Pat F.
Floorman Chris J.

Table with columns: Hrs., Per Hr., Amount. Rows for 10 hrs at 89.00, 10 hrs at 32.00, 10 hrs at 28.00, 10 hrs at 28.00. Includes EXTRA EQUIP (4.55), SALES TAX (25), and TOTAL (1774.80).

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION WICHITA, KS

Bad Replacements form with fields for # jts, # rods, and Rod Boxes Replaced (3/4, 7/8, 1).

(N) Testing tbg: Who tested: _____

results: _____

ems used from Express: _____

ems used from other suppliers: _____

Remarks: D.F. got circ started drilling @ 3240, drilled down to 3378' that is the deepest they want to go. circ. clean, rigged down Golden B. laid off tbg and drill collars, tbg will be tested, cleaned tools, shut off

By: Luz Alberto Fernandez Express Well Service & Supply, Inc.

"Thank You"

By: _____ Authorized Signature

No: 10554

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-16 200 9

lease Kellogg 'B' Well # 1 Co. KANSAS

Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Y Paint _____
- Y Diesel _____ Gal x _____ = _____
- Thread Dope 6/2 # \$4.55 each = \$29.58
- Y Stuff Box Rub _____
- Y Fishing Tool _____
- Y Circ Head _____
- Circ Rubber New 2 7/8 Used _____ \$172.00
- Y Packer (type) _____
- Y Plug _____
- Y Sand Pump _____
- Y Swab Equip _____
- Y Oil Saver Rub _____
- Y Swab Cups _____

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 01 2010
WICHITA, KS

Unit Rig # 6
Operator LWS F.
Floorman PAF.
Floorman Chris J.

Hrs.	Per Hr.	Amount
<u>11 1/2</u>	<u>89.00</u>	<u>1023.50</u>
<u>11 1/2</u>	<u>32.00</u>	<u>368.00</u>
<u>11 1/2</u>	<u>28.00</u>	<u>322.00</u>
<u>11 1/2</u>	<u>28.00</u>	<u>322.00</u>
EXTRA EQUIP		<u>201.58</u>
SALES TAX		<u>10.68</u>
TOTAL		<u>2247.76</u>

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Y N Testing tbg: Who tested: ELITE
Results: 14 bad jts, 4 collar changes
Items used from Express: NONE

Items used from other suppliers: Reinhardt's tools, National's tbg & collars

Remarks: D.I.H. Ran tools, set plug @ 3316' tested tools @ 1000# held good, set pkr @ 3158, tested casing & tbg held good, moved plug @ 3158 tested tools @ 1000# held good, hunt holes, located bottom hole @ 1996, spotted sand @ 2156', pulled pkr o.o.H., ran back in w/ one more plug, set it @ 1900' pressure test tools @ 1000# held good, hunt holes. Found another set of holes @ 1333'-1365', moved plug @ 1302' pkr @ 1270' shut ✓.

By: Angie FRANKLIN Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No: 10555

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-17 200 9

Lease Kellogg B' Well # 1 Co. KANSAS

Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- (N) Paint _____
- (N) Diesel _____ Gal x _____ = _____
- Thread Dope 1/2 # \$4.55 each = \$6.82 (T)
- (N) Stuff Box Rub _____
- (N) Fishing Tool _____
- (N) Circ Head _____
- Circ Rubber New _____ Used _____
- (N) Packer (type) _____
- (N) Plug _____
- (N) Sand Pump _____
- (N) Swab Equip _____
- (N) Oil Saver Rub _____
- (N) Swab Cups _____

Unit Rig # 6
 Operator Luis F.
 Floorman Pat F.
 Floorman Chris J.

Hrs.	Per Hr.	Amount
<u>13 1/2</u>	<u>89.00</u>	<u>1201.50</u>
<u>13 1/2</u>	<u>32.00</u>	<u>432.00</u>
<u>13 1/2</u>	<u>28.00</u>	<u>378.00</u>
<u>13 1/2</u>	<u>28.00</u>	<u>378.00</u>
		<u>6.82</u>
		<u>36</u>
		<u>2396.68</u>

RECEIVED
KANSAS CORPORATION COMMISSION

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____

Results: _____

Items used from Express: None

Items used from other suppliers: _____

Remarks: D.I.B. Hunt For holes, loc holes @ 1964-96, 1333-65, 954-1047, 798-923, squeezed w/pkr @ 1869', spotted cement @ 1365', squeezed w/pkr @ 704' left pressure on casing (500#) cleaned tools, shut

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No. 10556

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond

Date 12-18

200 9

Lease Kellogg 'B'

Well # 1

Co.

KANSAS

Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor, and Where Set Type Size.

- Paint
Diesel Gal x =
Thread Dope 2 1/2 # \$4.55 each = \$11.38 (T)
Stuff Box Rub
Fishing Tool
Circ Head
Rubber New Used
Packer (type)
Plug
Sand Pump
Swab Equip
Oil Saver Rub
Swab Cups

Unit Right 6
Operator Lus F.
Floorman Pat F.
Floorman Chris J.

Table with columns: Hrs., Per Hr., Amount. Includes rows for 11 hrs at 89.00 (979.00), 11 hrs at 32.00 (352.00), 11 hrs at 28.00 (308.00), 11 hrs at 28.00 (308.00), EXTRA EQUIP (11.38), SALES TAX (60), TOTAL (1958.98).

RECEIVED KANSAS CORPORATION COMMISSION

JUN 1 1990

WICHITA, KS

Table for Replacements: Bad # jts, # rods, Replacements # jts, # rods. Includes Rod Boxes Replaced 3/4", 7/8", 1".

Testing tbg: Who tested:

Results:
Items used from Express: NONE

Items used from other suppliers: Golden B' drill bit

Remarks: D.I.L. released pkr, pulled pkr. o.o.# run in w/ new bit, and six drill collars, a tugged cement @ 767' & rigged up Golden 'B' drilled down to 941' circ clean, pressure test, it leaked. From 500# down to 250# in 1m pulled up lit cleaned tools shut.

By: [Signature] Express Well Service & Supply, Inc. "Thank You" Authorized Signature

Company Black Diamond Date 12-19 200 9
Case Kellogg 'B' Well # 1 Co. KANSAS
Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Paint _____
- Diesel _____ Gal x _____ = _____
- Thread Dope 1 # _____ each = \$4.55 (T)
- Stuff Box Rub _____
- Fishing Tool _____
- Circ Head _____
- Circ Rubber - New _____ Used _____
- Packer (type) _____
- Plug _____
- Sand Pump _____
- Swab Equip _____
- Oil Saver Rub _____
- Swab Cups _____

Unit Rig # 6
 Operator Luis F.
 Floorman PA F.
 Floorman Chris J.

Hrs.	Per Hr.	Amount
9 1/2	89.00	845.50
9 1/2	32.00	304.00
9 1/2	28.00	266.00
9 1/2	28.00	266.00
EXTRA EQUIP		4.55
SALES TAX		25
TOTAL		1686.30

RECEIVED
KANSAS CORPORATION COMMISSION

JUN 1 2010

WICHITA, KS

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____
Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: O.D.H. started drilling @ 941', drilled down to 1064' circ clean, pressure test @ 500#, it leaked really fast, rigged down, Golden B. pulled bit O.D.H. cleaned tools, shut down

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No. 10558

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond

Date 12-21

200 9

Lease Kellogg B

Well # 1

Co. _____

KANSAS

Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- (N) Paint _____
- (N) Diesel _____ Gal x _____ = _____
- Thread Dope 2 # \$4.55 each = \$9.10 (T)
- (N) Stuff Box Rub _____
- (N) Fishing Tool _____
- (N) Circ Head _____
- Circ Rubber _____ New _____ Used _____
- (N) Packer (type) _____
- (N) Plug _____
- (N) Sand Pump _____
- (N) Swab Equip _____
- (N) Oil Saver Rub _____
- (N) Swab Cups _____

Unit Ry HC
 Operator L. F.
 Floorman Pat F.
 Floorman Chris J.

Hrs.	Per Hr.	Amount
8 1/2	8900	756.50
8 1/2	3200	272.00
8 1/2	2800	238.00
8 1/2	2800	238.00
EXTRA EQUIP		9.10
SALES TAX		48
TOTAL		1514.08

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

WICHITA, KS

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D.I.L. Ran in hole w/pkr set it @ 704' squeezed w/250 sxs of cement pulled pkr o.o.H. shut well in w/500 # cleaned tools, shut &

By: L. F. [Signature]
Express Well Service & Supply, Inc. "Thank You"

By: _____
Authorized Signature

No. 10559

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-22 200 9

Lease Kellogg B Well # 1 Co. KANSAS

Directions _____

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

Y Paint _____
Y Diesel _____ Gal x _____ = _____
Thread Dope 3 # \$4.55 each = \$13.65 (T)
Y Stuff Box Rub _____
Y Fishing Tool _____
Y Circ Head _____

Unit Rig #6
Operator Lu F
Floorman PA F
Floorman Chris J.

Table with columns: Hrs., Per Hr., Amount. Rows for 10 1/2 hrs at 89.00 (934.50), 10 1/2 hrs at 32.00 (336.00), 10 1/2 hrs at 28.00 (294.00), 10 1/2 hrs at 28.00 (294.00).

Y Packer (type) _____
Y Plug _____
Y Sand Pump _____
Y Swab Equip _____
Y Oil Saver Rub _____
Y Swab Cups _____

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 01 2010
WICHITA, KS

Table with columns: EXTRA EQUIP, SALES TAX, TOTAL. Values: 13.65, 72, 1872.87.

Table with columns: Bad, Replacements. Rows for # jts, # rods, Rod Boxes Replaced 3/4", 7/8", 1".

Y Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D-I-L. Raan hole w/6 drill collars same drillbit, tugged cement @ 757'
tugged up Golden B, drilled down to 941', pressure test it leaked. Kept drilling
down to 1064' pressure test, it acted like it did @ 941', did not leak any worse.
pulled up 1jt ~~swabbed~~ rigged up swab equip. swabbed down to 550'
laid it swab, shut it

By: [Signature] Express Well Service & Supply, Inc. "Thank You"

By: _____ Authorized Signature

No. 10561

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-23 2009

Case Kellogg B Well # / Co. KANSAS

Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- Y (N) Paint
Y (N) Diesel Gal x =
Thread Dope / # each = \$4.55 (T)
Y (N) Stuff Box Rub
Y (N) Fishing Tool
Y (N) Circ Head
Circ Rubber New Used
Y (N) Packer (type)
Y (N) Plug
Y (N) Sand Pump
Y (N) Swab Equip
Y (N) Oil Saver Rub
Y (N) Swab Cups

RECEIVED KANSAS CORPORATION COMMISSION JUN 01 2010 CONSERVATION DIVISION WICHITA, KS

Unit Right 6
Operator Luis F
Floorman PM F
Floorman Chris J

Table with columns: Hrs., Per Hr., Amount. Includes rows for 9 1/2 hrs at 89.00, 9 1/2 hrs at 32.00, 9 1/2 hrs at 28.00, 9 1/2 hrs at 28.00, EXTRA EQUIP 4.55, SALES TAX 2.5, TOTAL 1686.30.

Table for Bad Replacements with columns for # jts and # rods. Includes row for Rod Boxes Replaced 3/4", 7/8", 1".

Y (N) Testing tbq: Who tested:

Results:

Items used from Express:

Items used from other suppliers:

Remarks: D.J.W. ran swab, checked fill up logged @ 20' From surface kicked in 480' of fluid, laid & swab, continued drilling. drilled to 1189, circ. clean, pulled up 1 1/2" diameter cleaned tools, shut off.

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: [Signature] Authorized Signature

No. 10562

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-24 200 9

lease Kellogg 'B' Well # 1 Co. KANSAS

Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Paint _____
- Diesel _____ Gal x _____ = _____
- Thread-Dope _____ # _____ each = _____
- Stuff Box Rub _____
- Fishing Tool _____
- Circ Head _____
- Circ-Rubber New _____ Used _____
- Packer (type) _____
- Plug _____
- Sand Pump _____
- Swab Equip _____
- Oil Saver Rub _____
- Swab Cups _____

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 21 2010
WICHITA, KS

Unit Rig #6
Operator Leo F.
Floorman Pat
Floorman Chris J

Hrs.	Per Hr.	Amount
7 1/2	8900	667.50
7 1/2	3200	240.00
7 1/2	2800	210.00
7 1/2	2800	210.00
EXTRA EQUIP		
SALES TAX		-0-
TOTAL		1327.50

Bad		Replacements	
# _____	jts _____	# _____	jts _____
# _____	rods _____	# _____	rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____			

Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

Remarks: D.I.H. started drilling C188, drilled down to 1285' circ clean, pulled up 2 jts, cleaned tools, shut

By: [Signature]
Express Well Service & Supply, Inc. "Thank You"

By: _____
Authorized Signature

No. 10563

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-28 200 9

lease Kellogg B' Well # 1 Co. KANSAS

Directions _____

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Rows include Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- (N) Paint
(N) Diesel Gal x =
Thread Dope 3 # \$4.55 each = \$13.65 (T)
(N) Stuff Box Rub
(N) Fishing Tool
(N) Circ Head
(N) Packer (type)
(N) Plug
(N) Sand Pump
(N) Swab Equip
(N) Oil Saver Rub
(N) Swab Cups

Unit Rig #6
Operator Leo E
Floorman Pat T
Floorman Chris J

Table with columns: Hrs., Per Hr., Amount. Rows for labor and totals: EXTRA EQUIP 13.65, SALES TAX 72, TOTAL 1961.37

RECEIVED KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION WICHITA, KS

Table for Bad Replacements with columns for # jts and # rods. Includes Rod Boxes Replaced 3/4", 7/8", 1"

(N) Testing tbg: Who tested: _____

Results: _____

Items used from Express: NONE

Items used from other suppliers: _____

Remarks: DTL. Ran 2 jts back in. started drilling @ 1285' got drilled out @ 1440' circ. clean pressure test @ 500 #. leaked the same as top holes, ran down got to the next set of holes tagged @ 1900' drilled out @ 2010, circ. clean, pressure test, it leaked the same as above us, ran down, tagged sand @ 3144. circ. sand off plug, pulled bit O.O.H cleaned tools, shut off

By: Leo Antonio Thompson Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No. 10564

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 12-29 2009

Lease Kellogg 'B' Well # 1 Co. KANSAS

Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Equipment items include Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- (N) Paint
(N) Diesel Gal x =
Thread Dope 3 # \$4.55 each = \$13.65
(N) Stuff Box Rub
(N) Fishing Tool
(N) Circ Head
Circ Rubber (New) 2 7/8 Used \$172.00
(N) Packer (type)
(N) Plug
(N) Sand Pump
(N) Swab Equip
(N) Oil Saver Rub
(N) Swab Cups

RECEIVED KANSAS CORPORATION COMMISSION JUN 01 2010 CONSERVATION DIVISION WICHITA, KS

Unit Rig #6
Operator Luff
Floorman Puff
Floorman Chris J

Table with columns: Hrs., Per Hr., Amount. Values: 10 hrs @ 89.00 = 890.00, 10 hrs @ 32.00 = 320.00, 10 hrs @ 28.00 = 280.00, 10 hrs @ 28.00 = 280.00.

EXTRA EQUIP 185.65
SALES TAX 9.85
TOTAL 1965.50

Table for Replacements: # jts, # rods, Rod Boxes Replaced 3/4", 7/8", 1"

(N) Testing tbg: Who tested:

Results:

Items used from Express:

Items used from other suppliers:

Remarks: D.I.H. Ran in hole w/ catcher and pkr, set pkr @ 954' leaked around backside ran down to 1333, leaked around, ran down @ 1964' leaked around backside, pulled pkr o.d.H. to make sure it was alright, ran back in w/ another plug and a new pkr, tested every hole individually all of them held 500# but the top hole set plug @ 1065' and left plug there, pulled pkr o.d.H. spotted sand in casing. (175x25) cleaned loc shut.

By: Express Well Service & Supply, Inc. "Thank You" By: Authorized Signature

No. 10565

EXPRESS WELL SERVICE & SUPPLY, INC.
Victoria, Kansas 67671

Company Black Diamond Date 12-30 200 9
Case Kellogg B' Well # 1 Co. KANSAS
Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL				RERAN IN WELL			
Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

Paint _____
 Diesel _____ Gal x _____ = _____
 Thread Dope 1/2 # \$4.55 each = \$6.83
 Stuff Box Rub _____
 Fishing Tool _____
 Circ Head _____
 Circ. Rubber New _____ Used _____
 Packer (type) _____
 Plug _____
 Sand Pump _____
 Swab Equip _____
 Oil Saver Rub _____
 Swab Cups _____

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 01 2010
CONSERVATION
WICHITA, KS

Unit Rig #6
 Operator Luis F
 Floorman Pat T.
 Floorman Chris S

Hrs.	Per Hr.	Amount
9	89.00	801.00
9	32.00	288.00
9	28.00	252.00
9	28.00	252.00
		6.83
		36
		1600.19

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Testing tbg: Who tested: _____
 Results: _____
 Items used from Express: _____

Items used from other suppliers: _____

Remarks: O.I.W. Ran in w/ pkr, tagged sand @ 970', spotted cement @ 954', spotted acid @ 923, set pkr @ 704', displaced acid; ran down @ 923, spotted cement there, set pkr @ 704' squeezed w/ 200 lbs of cement. pulled pkr O.O.H. Shuttled well in @ 500# circused back, shut d.

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

No. 10566

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Black Diamond Date 1-4 200 10
Lease Kellogg 'B' Well # 1 Co. KANSAS
Directions

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Table with columns: Feet, Joints, Description, Condition, Equipment, Feet, Joints, Description. Includes rows for Polish Rod, Liner, Rod Subs, Rods, Pump, Tubing Subs, Tubing, Bbl. Seat N., Packer or Tubing Anchor, Mud Anchor.

- (N) Paint
(N) Diesel Gal x =
Thread Dope 1/2# \$4.55 each = \$6.82 (T)
(N) Stuff Box Rub
(N) Fishing Tool
(N) Circ Head
(N) Rubber New Used
(N) Packer (type)
(N) Plug
(N) Sand Pump
(N) Swab Equip
(N) Oil Saver Rub
(N) Swab Cups

RECEIVED KANSAS CORPORATION COMMISSION JUN 1 2010 CONSERVATION DIVISION WICHITA, KS

Unit Rig #6
Operator Lou F.
Floorman Pat F.
Floorman Chris J

Table with columns: Hrs., Per Hr., Amount. Includes rows for Operator, Floorman, EXTRA EQUIP, SALES TAX, TOTAL.

Table with columns: Bad, Replacements. Includes rows for # jts, # rods, Rod Boxes Replaced 3/4, 7/8, 1.

(N) Testing tbg. Who tested:

results:
ems used from Express:
ems used from other suppliers:

Remarks: D.I. Ran in hole w/ same used bit & 6 drill collars tagged cement @ 742' rigged up Golden 'B' drilled down to 941' circ. clean, pressure test @ 500# held good. Continued drilling cement to 971' then circ sand to the plug (1065') circ good and clean, pressure test @ 500# held good. laid down gravel pulled 4 jts. cleaned tools shut.

Express Well Service & Supply, Inc. "Thank You" By: Authorized Signature

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

No. 10567

Company Black Diamond Date 1-5 200 10
 Base Kellogg B Well # 1 Co. KANSAS
 Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Y Paint _____
- Y Diesel _____ Gal x _____ = _____
- Thread Dope 8 # \$4.55 each = \$36.40 (T)
- Y Stuff Box Rub _____
- Y Fishing Tool _____
- Y Circ Head _____
- Circ Rubber New _____ Used _____
- Y Packer (type) _____
- Y Plug _____
- Y Sand Pump _____
- Y Swab Equip _____
- N Oil Saver Rub 1 \$19.50 (T)
- Y Swab Cups _____

Unit Rig #6
 Operator Luis F.
 Floorman Pat F.
 Floorman Chris J.

Hrs.	Per Hr.	Amount
12	8900	1068.00
12	3200	384.00
12	2800	336.00
12	2800	336.00
EXTRA EQUIP		55.90
SALES TAX		2.96
TOTAL		2182.86

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

RECEIVED
 KANSAS CORPORATION COMMISSION

JUN 01 2010

CONSERVATION DIVISION
 WICHITA, KS

Y Testing tbg: Who tested: _____
 Results: _____
 Items used from Express: _____
 Items used from other suppliers: _____

Remarks: D.I.L. Finished pulling bit O.O.H. ran back in w/catcher pulled top plug O.O.H. Swee'dyed casing pressure test @ 500# leaked 100# in 10m, pressured test @ 350# leaked 50# in 10m, ran in w/catcher, stand 15' above plug, ran swab, swabbed d to 2200' set for 1 hr, ran down, tagged @ 2200' didn't record anything in, laid d swab, got on plug pulled plug O.O.H. perforated @ 3359 1/2' to 3369 1/2', started in hole w/pkc, ran 10 jts', cleaned tools, shut d

By: Luis F. [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

No. 10568

Company Black Diamond Date 1-26-6 200 10

Case Kellogg B Well # 1 Co. KANSAS

Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs		1	4' 12 3/8 above pkr.
				Tubing		106	2 7/8 8rd.
				Tubing			
				Bbl. Seat N:			
		Where Set Type Size		Packer or Tubing Anchor			Where Set ↓ 105 1/2 ft. Type 5 1/2 model R Size
				Mud Anchor			

Y Paint _____
 Y Diesel _____ Gal x _____ = _____
 Thread Dope 6 # \$4.55 each = \$27.30 (T)
 Y Stuff Box Rub _____
 Y Fishing Tool _____
 Y Circ Head _____

Unit Rig # 6
 Operator Lee F.
 Floorman Pat F.
 Floorman Chris J.

Hrs.	Per Hr.	Amount
12 1/2	89.00	1112.50
12 1/2	32.00	400.00
12 1/2	28.00	350.00
12 1/2	28.00	350.00
EXTRA EQUIP		331.80
SALES TAX		17.59
TOTAL		2686.89

Circ Rubber - New _____ Used _____
 Y Packer (type) _____
 Y Plug _____
 Y Sand Pump _____
 Y Swab Equip \$125.00
 Y Oil Saver Rub 1 \$19.50 (T)
 Y Swab Cups 1-R25 \$25.70 (T)

RECEIVED
 KANSAS CORPORATION COMMISSION
 JUN 01 2010
 CONSERVATION DIVISION
 WICHITA, KS

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Y Testing tbg: Who tested: _____
 Results: _____ \$19.00 (T)

Items used from Express: 1- 2 3/8 tbg collar. \$240.30 (T)
1- 2 3/8 → 2 7/8 change over
(For tail pipe on pkr)

Items used from other suppliers: _____

Remarks: D.I. Finished running pkr set pkr @ 3330, ran swab, tagged fluid @ 1150' swabb
1hr got fluid ↓ to 2500' & swabbed 33 bbls, show of oil, started 2 pulls/hr. 1st 11.5 bbl
6% oil. 2nd 11.69 bbls. 5% oil. 3rd 12 bbls show of oil, laid ↓ swab, treated w/ 1500 gal
20% acid, total load, 76 bbls, swabbed steady 74 bbls, laid ↓ swab, cleaned
loc. ~~set~~ closed tbg w/ valve. R.D.M.O.

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: _____ Authorized Signature