4-**032121**

### STATE CORPORATION COMMISSION **CONSERVATION DIVISION - PLUGGING** 130 SOUTH MARKET, SUITE 2078 ### 2970	TO:	API Number: 15-109-20,281 00-00
2270 feet from S section line WICHITA, KANSAS 67202 2270 feet from S section line WICHITA, KANSAS 67202 2270 feet from S section line WICHITA, KANSAS 67202 feet from S section line Operator license# 5393 Lease: Miller Well # 2 Operator: A.L. Abercrombie, Inc. County: Logan /S.#. S Address: Rt. 1 - Box 56 Well total depth 4755 f. Conductor Pipe: 0 inch 0 0 f. Surface pipe 8 5/8 Inch 0 0	STATE CORPORATION COMMISSION	
Operator license# 5393 Deparator license# 5393 Deparator: A.L. Abercrombie, Inc. County: Logan Address: Rt. 1 - Box 56 Great Bend, Kansas 67530 Surface pipe 8 5/8 Inch 6 313 f Aband. oil well X, Gas well , Input well , SWD , D & A Plugging contractor: Allied Cement Company License# - Address: Oakley, Kansa 67748 Company to plug at: Hour: P.H. Day: 15 Month: December Year: 1995 Plugging proposal received from: Bill Sowles Company: A.L. Abercrombie, Inc. Were: Order 200 sxs 60/40 pozmix - 10% gel - 300# hulls. Allied Cement Company. Plugging proposal Received by: Carl Goodrow Plugging proposal Received by: St. Allied Cement Company. Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Parf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4521 Rort collar at 1658' with 580 sxs. cwc. Pressured bsokside to Max. P.S.I. 300#. Hels Squeezed 5/12' w/50 sxs cement blend with 300# hulls mixed in. Pollowed with 13 sxs graffollowed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Dakota plug: YES NO Dak	CONSERVATION DIVISION - PLUGGING	7 + 010 · 11 · 12 · 13 · 1
Operator license# 5393 County: Logan		
Operator: A.L. Abercrombie, Inc. Address: Rt. 1 - Box 55	WICHITA, KANSAS 67202	2970 feet from E section line
Address: Rt. 1 - Box 56 Great Bend, Kansas 67530 Conductor Pipe: 0 inch 0 0 f Surface pipe 8 5/8 Inch 0 313 f Aband. oil well X, Gas well , Input well , SWD , D & A Plugging contractor: Allied Cement Company	Operator license#_5393	Lease: Miller Well # 2
Great Bend, Kansas 67530 Conductor Pipe: 0 inch 6 0 f. Surface pipe 8 5/8 Inch 8 313 f Aband. oil well X, Gas well , Input well , SWD , D & A	Operator: A.L. Abercrombie, Inc.	County: Logan 154.54
Surface pipe 8 5/8 Inch 6 313 f Aband. oil well X, Gas well , Input well , SWD , D & A		Well total depth 4755 feet
Plugging contractor: Allied Cement Company Address: Oakley, Kanas 67748 Company to plug at: Hour: P.M. Day: 15 Month: December Year: 1995 Plugging proposal received from: Bill Sowles Company: A.L. Abercrombie, Inc. Phone: Were: Order 200 sxs 60/40 pozmix - 10% gel - 300% hulls. Allied Cement Company. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All(], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' with 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.T.B.P. at 4570' - 4202' - 452! Port collar at 1658' with 580 sxs. cwc. Prossured backside to Max. P.S.I. 300%. Rej Squeezed 5 1/2" w/50 sxs cement blend with 300% hulls mixed in. Followed with 13 sxs que followed with 150 sxs cement blend to Max. P.S.I. 300%. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dekota plug: YES , NO Plugged through TUBING , CASING . Elevation: (agent)		Conductor Pipe: 0 inch @ 0 feet Surface pipe 8 5/8 Inch @ 313 feet
Company to plug at: Hour: P.M. Day: 15 Month: December Year: 1995 Plugging proposal received from: Bill Sowles Company: A.L. Abercrombie, Inc. Phone: Were: Order 200 sxs 60/40 pozmix - 10% gel - 300# hulls. Allied Cement Company. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' with 300 sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.T.B.P. at 4570' - 4202' - 4521 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Held. Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs graffollowed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING . Elevation: (agent)	Aband. oil well <u>x</u> , Gas well, Input well_	, SWD, D & A
Company to plug at: Hour: P.M. Day: 15 Month: December Year: 1995 Plugging proposal received from: Bill Sowles Company: A.L. Abercrombie, Inc. Phone: Were: Order 200 sxs 60/40 pozmix - 10% gel - 300# hulls. Allied Cement Company. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 452! Port collar at 1659' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hels Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs green followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs green followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD	Plugging contractor: Allied Cement Company	License#
Plugging proposal received from: Bill Sowles Company: A.L. Abercrombie, Inc. Phone: Were: Order 200 sxs 60/40 pozmix - 10% gel - 300# hulls. Allied Cement Company. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 452' Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bettom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING BAD Anhy.plug: YES , NO Lace Case Case Case Case Case Case Case Cas	Address: Oakley, Kanas 67748	
Company: A.L. Abercrombie, Inc. Phone: Were: Order 200 sxs 60/40 pozmix - 10% gel - 300# hulls. Allied Cement Company. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528' Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hel Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did(] / did not[X] observe the plugging.	Company to plug at: Hour: P.M. Day: 15	Month: Year: Year:
Were: Order 200 sxs 60/40 pozmix - 10% gel - 300# hulls. Allied Cement Company. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 452i Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hel Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING . Elevation: If did(] / did not[X] observe the plugging.	Plugging proposal received from: Bill Sowles	
Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' with 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4520' Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Held Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs queezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs queezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs queezed 5 1/2" w/50 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD	Company: A.L. Abercrombie, Inc.	Phone:
Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' with 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4520' Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Held Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs queezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs queezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs queezed 5 1/2" w/50 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD		
Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' w; 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4520' Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 130 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs graffollowed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD		
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.	Allied Cement Company.	
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.	**************************************	·
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.		
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.		
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.		* ************************************
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.		
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wides. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 13 sxs get followed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs get followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.		
Completed: Hour: 5:00 P.M., Day: 15, Month: December , Year: 1995 Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4524 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs gas followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Dakota plug: YES , NO Dak	Plugging Proposal Received by: Carl Goodro	ow
Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs gas followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.	Plugging operations attended by agent? All[], Part[], None[X]
Actual plugging report: 8 5/8" set at 313' cwc with 250 sxs. 5 1/2" set at 4753' wi 300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed with 150 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs gas followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did[] / did not[X] observe the plugging.	0	
300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hel Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs ga followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did{	Completed: Hour: 5:00 P.M., Day: 15, Month:	December , Year: 1995
300sxs. P.B.T.D. 4714'. Prod. Perf. 4668' - 4672'. C.I.B.P. at 4570' - 4202' - 4528 Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hel Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs ga followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES , CALC , NO Dakota plug: YES , NO Plugged through TUBING , CASING Elevation: I did{	Actual plugging report: 8 5/8" set at 313! cw	o with 250 eye. 5 1/2" get at 4753; with
Port collar at 1658' with 580 sxs. cwc. Pressured backside to Max. P.S.I. 300#. Hellowed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs gas followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES, CALC, NO Dakota plug: YES, NO Plugged through TUBING, CASING Elevation: I did[] / did not[X] observe the plugging. (agent)		
Squeezed 5 1/2" w/50 sxs cement blend with 300# hulls mixed in. Followed with 13 sxs gent followed with 150 sxs cement blend to Max. P.S.I. 300#. Held. Plug complete. Remarks: Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO Bottom plug(in place): YES, CALC, NO Dakota plug: YES, NO Plugged through TUBING, CASING Elevation: I did{		
Remarks: Condition of casing(in hole): GOODBADAnhy.plug: YESNO Bottom plug(in place): YES, CALC, NODakota plug: YES, NO Plugged through TUBING, CASING Elevation: I did{		
Condition of casing(in hole): GOODBADAnhy.plug: YESNOBottom plug(in place): YES, CALC, NOBakota plug: YES, NOPlugged through TUBING, CASING Elevation:	followed with 150 sxs cement blend to Max. P.S.	I. 300#. Held. Plug complete.
Condition of casing(in hole): GOODBADAnhy.plug: YESNOBottom plug(in place): YES, CALC, NOBakota plug: YES, NOPlugged through TUBING, CASING Elevation:		
Condition of casing(in hole): GOODBADAnhy.plug: YESNOBottom plug(in place): YES, CALC, NOBakota plug: YES, NOPlugged through TUBING, CASING Elevation:		26-1995
Bottom plug(in place): YES, CALC, NO Dakota plug: YES, NO Plugged through TUBING, CASING Elevation: I did[] / did not[X] observe the plugging. (agent)	Remarks:	
Plugged through TUBING, CASING Elevation: I did[] / did not[X] observe the plugging. (agent)		
I did[] / did not[x] observe the plugging. (agent)		
(agent)	Plugged through TUBING, CASING	. Elevation: GI
(agent)	I did() / did not[x] observe the plugging.	Carl Goodion
1-5-96 44388		(agent)
44388	1-5-96 W	Form CP-2/3
44200	111288	
M_{\star} (M_{\star}) is the state of M_{\star} . The state of M_{\star} is the state of M_{\star} and M_{\star} .	37, 750x 44200 - 7	