


15-169-0021-00-00

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas



FILE NO. _____

LOCATION SE 27 N. 5 W

SEC. 22 TWP. 13 RGE. 5 W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1 Lease Pictora

Operator North Cross Petr Address Tulsa Okla

Field County Salina

Total Depth 395 Feet.

(Describe briefly the manner in which the well was plugged)

Runned pipe & circulated,
Bridge at approx 160
15 sack cement on bridge
3 mud to 2.0, 5 sack cement at top
of surface pipe.
Rest hole filled with 10 sack
cement

RECEIVED
DISTRICT CONSERVATION AGENT

03-21-1953

[Signature]
District Conservation Agent

Date 3-20-53

PLUGGING
FILE SEC 22 TWP 13 R 5 W
BOOK PAGE 86 LINE 22