KCC OIL/GAS REGULATORY OFFICES

| Date: <u>04/01/10</u> | District: <u>01</u> | Case #: |
|---|--------------------------------|---|
| | New Situation | Lease Inspection |
| | Response to Request | Complaint |
| | Follow-Up | Field Report |
| Operator License No: 4058 | API Well Number: 15-083 | -21,631-00-00 |
| Op Name: American Warrior | Spot: <u>SE-SE-SE-SW</u> | Sec 17 Twp 21 S Rng 24 E / W |
| Address 1: P.O. Box 399 | 116 | Feet from N/ S Line of Section |
| Address 2: P.O. Box 783188 | 2610 | Feet from E/W Line of Section |
| City: Garden City | GPS: Lat: 38.21852 | Long: <u>99.98241</u> Date: <u>4/1/10</u> |
| State: Kansas Zip Code: 67846 -0399 | Lease Name: <u>Jarred Nuss</u> | Unit Well #: <u>1-17</u> |
| Operator Phone #: (620) 587-3224 | County: Hodgeman | |
| Reason for Investigation: | | |
| Witness Alt.II | | |
| Problem: | | |
| None, cement circulated to surface | | |
| Persons Contacted: | | |
| | | |
| | | |
| Findings: | | |
| 8-5/8" @ 215W/150sxs cement | | |
| TD @ 4445' | | · |
| 5-1/2" @ 4444'W/150sxs cement | ad 4/4# fla aaal 20/ aa 4 | Favo want to mit |
| Port Collar @ 1559' cemented with 140sxs-sr | nd-1/4# 110 Seal-2%CC-1 | osxs went to pit |
| | | |
| · | | J |
| | | · |
| | | |
| Action/Recommendations: Follow | Up Required Yes No | Date: |
| Alt.II requirements have been met | | |
| RECEIVED | | |
| \ | | |
| APR - 5 2010 | | |
| KCC DODGE CITY Verification Sources: | 5 | DI (T I |
| | A Pur curus | Photos Taken: |
| | A Program ourthouse By: Micha | ael Maier |
| Other: | | |
| Retain 1 Copy District Office | | RECEIVED |
| Send 1 Copy to Conservation Division | | APR 0 8- 2010 02/22/2008 |
| • | | AFR U & ZOIO SELECTION CONT. |

KCC WICHITA

| Date: <u>04/01/10</u> | | - | District | : <u>01</u> | | License #: 4058 | | |
|-------------------------------|-------------------|------------------|---|---|-------------|---|--|--|
| Op Name: 4058 | | | Spot: <u>S</u> | Spot: <u>SE-SE-SW</u> Sec <u>17</u> Twp <u>21</u> S Rng <u>24</u> E { | | | | |
| County: Hodgeman | | | Lease Name: <u>Jarred Nuss Unit</u> Well #: <u>1-17</u> | | | | | |
| I.D. Sign Yes | No | | 5 | Gas V | enting _ | Yes No | | |
| Tank Battery Condi | | le Overflow | ing | Pi Fluid | | ft; Approx. Size:ft. xft. | | |
| Pits, Injection Site | | | | Sa | ltwater Pi | Pipelines | | |
| Fluid Depth: | _ft; Approx. S | ize:ft | . xft. | Lea | ıks Visible | e: Y N Tested for Leaks: Y N | | |
| Oil Spill Evidence | | | | Fi | owing Ho | oles | | |
| Abandoned Well | Potential Polli | ution Problem | Yes No 17 | Т | A Wells | | | |
| | | | | М | onitoring | g Records | | |
| Lease Cleanliness Very Good S | atisfactory | Poor Ver | y Bad | | | | | |
| SWD/ER Injection Well | Yes | No | Hodgeman 🔄 | Gaug | e Connect | tions Yes No | | |
| Permit #: Pi | | | | | | ; T/C Annulus:; C/SP Annulus: | | |
| Permit #:Pi | | | | | | ; T/C Annulus:; C/SP Annulus: | | |
| Permit #: Pr | | | | | | ; T/C Annulus:; C/SP Annulus:;; T/C Annulus:; C/SP Annulus: | | |
| | - Cossuit Tittu | poi, 110 | psi | 7401 | | , 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | |
| API Number | Footages | Spot Location | GPS | | Well # | Well Status | | |
| 15-083-21,631-00-00 | 116FSL 2610FWL | SE-SE-SE-SW | 38.21852-99.9 | 8241 | 1-17 | New well, Alt.II completed | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | : | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |