To:	API NUMBER	<u>15-133-</u> 0	1852-00	-00
STATE CORPORATION COMMISSION	NE SW NE	Sec/Twp/Rge <u>33-28-21E</u> .		
Wichita State Office Bldg PLUGGING SECTION	3674 (GPS)	feet from south section line		
130 S. Market, Room 2078 Wichita, Kansas 67202	1873 (GPS)	feet from east section line		
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Vanleeuwer	GPS #17	
Operator License # 101	County	Neosho	1	
Operator: State Of Kansas Fee Fund	Well Total Depth	450 (est)		feet
Name & Dent/Vanleeuwen Lease Project	Production Pipe:	2.5	_Size Feet	450(est)
Address	Surface Casing:	NA	_Size Feet	NA
AB oil well Gas Well SWI	D Well/ Input Well	E-04612.6	D&A	
Other well as hereinafter indicated:				····
Plugging Contractor: Kepley Well Service, LLC			_ Lic. #	33749
Address: 19245 Ford Road, Chanute, Kansas 66720				
Company to plug at: Hour: Day	:5	Month:	12	2008
Plugging proposal received from: Mike Kepley			•	
Company Name:		Phone:		
·				
Plugging Proposal R	eceived by:	Alan M. Dur	 	
Plugging Proposal R	eceived by:	Alan M. Dur	TECHNICIAN	xxxxxx
	Part	Alan M. Dur	TECHNICIAN None	
Plugging attended by Agent: All	Part	Month:	TECHNICIAN None 12	2008
Plugging attended by Agent: All Operations Completed: Hour: Days	Part 5 vas removed, the res	Month:	TECHNICIAN None 12 le. The well	XXXXXX 2008 was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: 34' of the poly pipe w	Part 5 vas removed, the reservered to 410' and the	Month: st hung in ho e well pumpe	TECHNICIAN None 12 le. The welled full of cert	2008 was nent from
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Day: 34' of the poly pipe we perforated at 250' and 150'. A 1" cement string was low	Part 5 vas removed, the reservered to 410' and the	Month: st hung in ho e well pumpe	TECHNICIAN None 12 le. The welled full of cert	2008 was nent from
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Day: 34' of the poly pipe we perforated at 250' and 150'. A 1" cement string was low btm to top thru this cement string. A total of 26 sacks of	Part 5 vas removed, the reservered to 410' and the	Month: st hung in ho e well pumpe ere used to p	TECHNICIAN None 12 le. The well ed full of cem plug well. The	2008 was ment from me well
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Day: 34' of the poly pipe we perforated at 250' and 150'. A 1" cement string was low btm to top thru this cement string. A total of 26 sacks of	Part 5 vas removed, the reservered to 410' and the	Month: st hung in ho e well pumpe ere used to p	TECHNICIAN None 12 le. The well ed full of cem blug well. The	2008 was ment from me well CEIVED RATION COMMIS
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Day: 34' of the poly pipe we perforated at 250' and 150'. A 1" cement string was low btm to top thru this cement string. A total of 26 sacks of	Part 5 vas removed, the resolvered to 410' and the foortland cement w	Month: st hung in ho e well pumpe ere used to p	TECHNICIAN None 12 le. The well ed full of cem plug well. The CANSAS CORPO DEC	2008 was ment from me well
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Day: 34' of the poly pipe were perforated at 250' and 150'. A 1" cement string was low btm to top thru this cement string. A total of 26 sacks of was cut off below plow depth and the location restored. Remarks: Control #20080018-044	Part 5 vas removed, the resolvered to 410' and the foortland cement w	Month: st hung in ho e well pumpe ere used to p	TECHNICIAN None 12 le. The well ed full of cem plug well. The CANSAS CORPO DEC	2008 was ment from me well CEIVED RATION COMMIS