## DISTRICT CONSERVATION AGENT'S REPORT

TO:

Chala Camanatina Cart	• •
State Corporation Commission Conservation Division 211 North Broadway	ETTE MO
Wichita, Kansas	FILE NO.
	LOCATION NE SW NE
	SEC.31 TWP.11 RGE. 20
Dry Hole X Abandoned Cil Well	Abandoned Gas Well
I have this date completed supervision o	f plugging of:
Well No. 7 Lease J.L. Casker	ANB rcc
Operator Skelly Oil Co	Address Hutchinson, Kans
Field	County Ellis
Total Depth 3952 Feet.	
	Org Co & Halliburton Cementing Co
Plugging Contractor's License No.	
Address	
	ner in which the well was plugged)
8 5/8" at 277' circulated with	cement.
Circulated hole with heavy mud	, spotted 25 sax cement on bottom
through drill pipe, set cement	ing plug at 270', displaced 25
sax cement through drill pipe	at 270', mud to 70', set cementing
plug at 70' and filled to 0' w	ith cement.
Cementing by Halliburton Cemen	ting Co.
	Cean Let
	District Conservation Agent
	Date 5-17-56

PLUGGING FILE SEC 31T 11 RZOW BOOK PAGE 62 LINE 8

STATE CORPORT TOTAL CONTROLLES FOR وريق

Wichita, Kansca