## KCC OIL/GAS REGULATORY OFFICES

Date: <u>05/06/10</u>	District: 01	Case #:					
	New Situation	Lease Inspection					
	Response to Reques	t Complaint					
	Follow-Up	Field Report					
Operator License No: 4058	API Well Number: 15-135-25,016-00-00						
Op Name: American Warrior		Sec <u>21 Twp 18 S Rng 22 E</u> / W					
Address 1: P.O. Box 399		Feet from N/ S Line of Section					
Address 2: P.O. Box 783188		Feet from Feet from E/W Line of Section					
City: Garden City		Long: 99.75806 Date: 5/6/10					
State: Kansas Zip Code: <u>67846 -0399</u>	Lease Name: Larry Stieben Well #: 1-21						
Operator Phone #: (620) 587-3224							
Reason for Investigation:							
Witness Alt.II							
Problem:							
None, cement circulated to surface		•					
INOTIE, Cerrient Circulated to Surface							
Persons Contacted:							
		,					
Findings:	<u> </u>						
8-5/8" @ 223W/150sxs cement							
TD @ 4335'							
5-1/2" @ 4332'W/175sxs cement	1.4.1.4.4.5	as 15 ave went to nit					
Port Collar @ 1483' cemented with 135sxs	-smd-1/4# 110 Seai-2%0	CC-195XS Wert to pit					
		No Date:					
Tectom/recommonations.	llow Up Required Yes	No Date.					
Alt.II requirements have been met							
RECEIVED							
MAY 1 9 2010							
KCC DODGE CITY							
Verification Sources:		Photos Taken:					
RBDMS KGS	TA Program						
T-I Database	Courthouse By: N	Michael Maier					
Other:							
Retain 1 Copy District Office							
Send 1 Copy to Conservation Division	RECEIVED MAY 2 4 2010	Form: <u>02/22/2008</u>					
	"'n' 4 4 2010						

KCC WICHITA

B

Date: <u>05/06/10</u>		_	Distri	ct: <u>01</u>			License #: 4	058	
Op Name: 4058				Spot: SW-SE-NW-NE Sec 21 Twp 18 S Rng 22					. <b>√</b> W
County: Ness	Lease I	Lease Name: Larry Stieben Well #: 1-21							
I.D. Sign Yes	No		গ	Gas	Venting [	Yes No			S
Tank Battery Con Condition: Good		ible Overflo	wing	, <u> </u>	Pits I Depth: _	ft; Appro	ox. Size:	ft. x	ft.
Pits, Injection Site		Size:	ft. xft.		altwater I	Pipelines	Tested for	—	₽ ₽ N
Oil Spill Evidence			145	F	lowing Ho	oles			
Abandoned Well  Lease Cleanliness  Very Good  S		lution Problem			ΓA Wells	; Records			
SWD/ER Injection Well Permit #: P Permit #: P Permit #: P	Yes ressure – Acturessure – Actures – Actures – Acturessure – Actures – Acture	No al:psi; Au al:psi; Au al:psi; Au	Ness sthorized: psi	i Tubir i Tubir i Tubir	ng: ng: ng:	tions Yes ; ; T/C Annulus ; T/C Annulus ; T/C Annulus ; T/C Annulus	s:; C/ s:; C/ s:; C/	SP Annulus: _	
API Number	Footages	Spot Location	GPS		Well #		Well Status		
<u>15-135-25,016-00-00</u>	1179FNL 1684FEL	SW-SE-NW-NE	38.47695-99.7	5806	1-21	New well, Alt.II	completed		