KCC OIL/GAS REGULATORY OFFICES

Date: <u>05/12/10</u>	District: _1						
	New Situation Lease Inspection						
	Response to Request Complaint						
	Follow-Up Field Report						
Operator License No: 4058	API Well Number: 15-135-250 49-00-00						
Op Name: American Warrior, Inc.	Spot: SE-SW-NE-SW Sec 34 Twp 20 S Rng 25 E / W						
Address 1: PO Box 399	1369 Feet from N/V S Line of Section						
Address 2:	Feet from Feet from W Line of Section						
City: Garden City	GPS: Lat: 38.26547 Long: 100.07398 Date: 5/12/10						
State: KS Zip Code: 67846 -0399	Lease Name: Darren Well #: 1-34						
Operator Phone #: (316) 275-9231	County: Ness						
Reason for Investigation:							
Company requested a state witness to the A	ternate 2 cementing job.						
Problem:							
Alternate 2 cementing requirements have not been met.							
Persons Contacted:							
Joe Smith.							
Findings:							
8 5/8" was set @ 211' with 150 sx cement. 5 cementing job. Company opened port collar circulating 20 sx to the pit. Closed port collar	3 1/2" was set @ 4524' with 150 sx cement on primary @ 1598'. Swift Services, Inc. pumped 160 sx SMD cement, r. Job complete @ 10:50 a.m.						
·							
Action/Recommendations: Follow	w Up Required Yes ✓ No 🖸 Date:						
None. Alternate 2 cementing requirements	nave been met.						
RECEIVED ()							
MAY 1 4 2010 (
*CC DODGE CITY							
Verification Sources:	Photos Taken: <u>0</u>						
	TA Program By: Em Mardam						
T-I Database District Files	Courthouse						
Other:	Eric MacLaren						
Retain 1 Copy District Office Send 1 Copy to Conservation Division	RECEIVED Form:						
	RECEIVED Form:						

KCC WICHITA

MAY 1 9 2010

Date: 05/12/10		<u></u>	District:	1	License	e #: <u>4058</u>	
				E-SW-NE-SW Sec <u>34</u> Twp <u>20</u> S Rng <u>25</u> E V W			
County: Ness Lease N				ame: Darren Well #: 1-34			
I.D. Sign Yes No				Gas Venting Yes No			
Tank Battery Con		ole Overflov	ving	Pits Fluid Depth:	ft; Approx. Size: _	ft. xft.	
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N			
Oil Spill Evidence				Flowing Holes			
Abandoned Well	Potential Poll	ution Problem [Yes No 🔊	TA Wells			
Lease Cleanliness		Poor Ver	y Bad	Monitoring	Records		
SWD/ER Injection We		J	Ness started:	_	ons Yes No	: C/SP Annulus:	
Permit #: Pressure - Actual: psi; Authorized: psi Permit #: Pressure - Actual: psi; Authorized: psi				Tubing:; T/C Annulus:; C/SP Annulus:; Tubing:; T/C Annulus:; C/SP Annulus:;			
Permit #:							
Permit #: Pressure – Actual: psi; Authorized: psi				Tubing:; T/C Annulus:; C/SP Annulus:			
API Number	Footages	Spot Location	GPS	Well#		Vell tatus	
						100 (100	
					<u> </u>		