KCC OIL/GAS REGULATORY OFFICES

Date: <u>05/18/10</u>	District: <u>01</u>	
	New Situation Lease Inspection	
	Response to Request Complaint	
	Follow-Up Field Report	
0	API Well Number: <u>15-101-22,227-00-00</u>	
Operator License No: 6569		JE /[Z]W
Op Name: <u>Carmen Schmitt, Inc.</u>		_
Address 1: P.O. Box 47		
Address 2: 915 Harrison	GPS: Lat: 38.59100 Long: 100.58172 Date: 5/18/	
City: Great Bend	•	
State: <u>Kansas</u> Zip Code: <u>67530 -0047</u>		
Operator Phone #: <u>(620) 793-5100</u>	County: Lane	
Reason for Investigation:		
Witness Alt.II		<u>-</u>
Problem:		
None cement circulated to surface		
Persons Contacted:		
Findings:		
8-5/8" @ 219'W/150sxs cement TD @4608 5-1/2" @ 4605'W/150sxs cement Port collar @ 2299'-cemented with 195sxs	s-smd-1/4#flo seal-2%cc-15sxs went to pit	·
or condi & 2200 comence may recent		
	Follow Up Required Ves No Date: 7/14/09	
Action/Recommendations: F	Follow Up Required Yes No Date: 7/14/09	
Alt.II requirements have been met		
RECEIVED		
MAY 1 9 2010		
KCC DODGE CITY		
Verification Sources:	Photos Taken:	
RBDMS KGS	TA Program	
T-I Database	Courthouse By: Michael Maier	
Other:	RECEIVED	
Retain 1 Copy District Office Send 1 Copy to Conservation Division	MAY 2 4 2010 Form: 02/22/	/2008

KCC WICHITA

Date: <u>05/18/10</u> Op Name: <u>6569</u>			District:	: <u>01</u>		License #: <u>6569</u>		
			Spot: <u>N</u>	Spot: <u>NE-NE-NW-SE</u>		Sec <u>12</u> Twp <u>17</u> S Rng <u>30</u> E 🗸		
County: Lane		Lease Na	Lease Name: York Well #: 1					
I.D. Sign Yes No				Gas	Venting [Yes No	S	
Tank Battery Condition Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.				
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N				
Oil Spill Evidence		·		F	lowing Ho	oles		
Abandoned Well	Potential Poll	lution Problem [Yes No 57	1	A Wells			
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	М	onitoring	Records		
SWD/ER Injection Well Permit #:Pi Permit #:Pi Permit #:Pi	Yesressure – Acturessure – Actures – Acture – Acturessure – Actures	No al: psi; Au al: psi; Au al: psi; Au	Lane psi	Tubir Tubir Tubir	ng: ng: ng:	tions Yes No ; T/C Annulus: ; C/SP Annulus:		
API Number	Footages	Spot Location	GPS	į	Well #	Well Status		
<u>15-101-22,227-00-00</u>	2550FSL 1500FEL	NE-NE-NW-SE	38.59100-100.5	8172	1	New well, Alt.II completed		