

KCC OIL/GAS REGULATORY OFFICES

Date: 06/18/10

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 31783

API Well Number: 15-101-22,236-00-00

Op Name: Mid-Continent Energy Operating Co.

Spot: SW-SW-SW-NE Sec 22 Twp 19 S Rng 27 E / W

Address 1: 100W 5th St. Ste 450

2426 Feet from N / S Line of Section

Address 2: _____

2633 Feet from E / W Line of Section

City: Tulsa

GPS: Lat: 38.38661 Long: 100.29162 Date: 6/18/10

State: Ok Zip Code: 74103 -4254

Lease Name: Habiger Well #: 1-22

Operator Phone #: (918) 587-6363

County: Lane

Reason for Investigation:

Witness Alt.II

Problem:

None cement circulated to surface.

Persons Contacted:

Findings:


8-5/8" @ 305'W/185sxs
TD. @ 4700'
4-1/2 @ 4678'W/180sxs
Port Collar @ 2147W/ 225sxs-smd-1/4# flo seal-2%cc-20sxs to pit

Action/Recommendations:

Follow Up Required Yes No

Date: 7/14/09

Alt.II requirements have been met.

RECEIVED
JUN 25 2010 

KCC DODGE CITY

Verification Sources:

- | | | |
|---------------------------------------|--|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ | | |

Photos Taken: _____

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 02/22/2008



Date: 06/18/10

District: 01

License #: 31783

Op Name: 31783

Spot: SW-SW-SW-NE Sec 22 Twp 19 S Rng 27 E W

County: Lane

Lease Name: Habiger Well #: 1-22

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Lane

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-101-22,236-00-00	2426FNL 25633FEL	SW-SW-SW-NE	38.38661-100.29162	1-22	New well, Alt. II completed

Retain 1 Copy District Office
Send 1 Copy to Conservation Division