## KCC OIL/GAS REGULATORY OFFICES

Date: <u>06/21/10</u>	District: _	01		Case	<b>#:</b>			
	New	Situation		Lease Ins	pection			
	Resp	onse to Requ	est	Complair	nt			
	Follo	w-Up		Field Rep	ort			
Operator License No: 4058	API Well N	lumber: <u>15</u>	5-135-25,00	3-00-00				
Op Name: American Warrior			•			E / <b>_</b> W		
Address 1: P.O. Box 399						Line of Section		
Address 2:						Line of Section		
City: Garden City	GPS: Lat:	38.42534	Long:	99.70437	Date: <u>6</u>	/21/10		
State: Kansas Zip Code: 67846 -0399	Lease Nam	e: <u>Kuehn</u>			Well #: <u>5-1</u>			
Operator Phone #:	County: 1	less						
Reason for Investigation:			,			,		
Witness Alt.II								
Problem:								
None, cement circulated to surface								
Persons Contacted:						<del></del> -		
					,			
Eindin au								
Findings: 8-5/8" @ 224W/150sxs cement								
TD @ 4305'								
5-1/2" @ 4304'W/175sxs cement								
Port Collar @ 1411' cemented with 135sxs-smd-1/4# flo seal-2%cc-15sxs went to pit								
				-				
Action/Recommendations: Follow	. U- Danibad		7 <sub>N</sub> , G	D 4 7	//14/00			
	Up Required	Yes _	No 🖸	Date: _Z	/14/09			
Alt.II requirements have been met								
RECEIVED								
JUN 2 5 2010								
Verification Source CC DODGE CITY					Photos Tak	en:		
	A Program							
	Courthouse	Ву:	Michael Ma	ier		<del></del>		
Other:		_		7.00				

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>



Date: 06/21/10		-	District:	: <u>01</u>	Lice	ense #: <u>4058</u>			
Op Name: <u>4058</u>				Spot: NE-NW-SW-SE Sec 1 Twp 19 S Rng 22 E					
County: Ness			Lease Na	me: Kuehn Well #: 5-1					
I.D. Sign Yes	No		S	Gas Venting [	Yes No	•			
Tank Battery Condition  Condition: Good Questionable Overflowing				Pits Fluid Depth:	ft; Approx. Siz	ze:ft. xft.			
Pits, Injection Site Fluid Depth:	ft; Approx. S	ize:ft	. xft.	Saltwater Leaks Visib		Γested for Leaks: Y N N			
Oil Spill Evidence				Flowing Holes					
Abandoned Well	Potential Poll	ution Problem	Yes No x7	TA Wells					
Lease Cleanliness Very Good Sa	atisfactory [	Poor Very	y Rad	Monitorin	g Records				
		<del>      </del>		Cauga Canna	ctions Yes No	ភ			
SWD/ER Injection Well Permit #: Pr		•				; C/SP Annulus:			
Permit #: Pi						; C/SP Annulus:			
Permit #: Pi						; C/SP Annulus:			
Permit #: Pi									
API Number	Footages	Spot Location	GPS	Well #	#	Well Status			
15-135-25,003-00-00	1253FSL 2267FEL	NE-NW-SW-SE	38.42534-99.70	0437 5-1	New well, Alt.II completed				
			-	-					