## KCC OIL/GAS REGULATORY OFFICES

Date: <u>08/31/10</u>	District: <u>01</u>					
·	New Situation Lease Inspection					
	Response to Request Complaint					
	Follow-Up Field Report					
4050						
Operator License No: 4058	API Well Number: 15-135-25,120-00-00					
Op Name: American Warrior	Spot: NW-SE-SW-NE Sec 27 Twp 18 S Rng 22 E /√W					
Address 1: P.O. Box 399	2290 (2291) Feet from ✓N/ S Line of Section					
Address 2: P.O. Box 783188	1830 (1819) Feet from F L/W Line of Section					
City: Garden City	GPS: Lat: 38.45930 Long: 99.73990 Date: 8/31/10					
State: Kansas Zip Code: 67846 -0399	Lease Name: Schugart Well #: 1-27					
Operator Phone #: <u>(620) 587-3224</u>	County: Ness					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None, cement circulated to surface						
Persons Contacted:						
Findings:						
8-5/8" @ 221W/150sxs cement TD @ 4288'						
5-1/2" @ 4287'W/175sxs cement Port Collar @ 1467' cemented with 155sxs-sn	nd-1/4# flo seal-2%cc-15sys went to nit					
	10-1/4# 110 Seai-2 /000-133x3 Well to pit					
Action/Recommendations: Follow	Up Required Yes No 🖸 Date:					
Alt.II requirements have been met						
·						
Verification Sources:	Photos Taken:					
RBDMS KGS T	A Program					
	ourthouse By: Michael Maier					
Retain 1 Copy District Office RECEIVED						
Send 1 Copy to Conservation Division	Form: 02/22/2008					
SEP - 3 2010 \\	RECEIVED VOID OF THE PROPERTY					

KCC DODGE CITY

SEP 0 7 2010

Date: <u>08/31/10</u>		_	District	01		Lice	ense #: <u>4058</u>	
Op Name: 4058				N-SE-S	SW-NE	Sec <u>27</u> Twp <u>18</u>	Twp <u>18</u> S Rng <u>22</u>	
County: Ness Lea				se Name: <u>Schugart</u> Well #: <u>1-27</u>				
I.D. Sign Yes	No		S	Gas V	enting [	Yes No		Ŋ
Tank Battery Cond Condition: Good		ole Overflow	ring 🙃	Pi Fluid		ft; Approx. Siz	e:ft. x	ft.
Pits, Injection Site				$\Box_{Sa}$	ltwater Pi	inelines		নে নি
Fluid Depth:	_ft; Approx. S	Size:ft	. xft.	$\vdash$			Sested for Leaks:	YN
Oil Spill Evidence				FI	owing Hol	les		
Abandoned Well	Potential Poll	ution Problem	Yes No	Т	A Wells			
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	М	onitoring	Records		
SWD/ER Injection Well	Yes	No	Ness 🗈	Gaug	e Connect	ions Yes No		n
Permit #: P						; T/C Annulus:		
Permit #: P						; T/C Annulus:		
Permit #:P						; T/C Annulus:		
Permit #:P	ressure – Actu	ai:psi; Au	inorized: psi	Lubin	ıg:	; T/C Annulus:	; C/SP Annulu	is:
API Number	Footages	Spot Location	GPS		Well #		Well Status	
<u>15-135-25,120-00-00</u>	2290FNL 1830FEL	NW-SE-SW-NE	38.45930-99.73	3990	1-27	New well, Alt.II cor	mpleted	
				<del> </del>	<del></del>			
							Stevens of the steven	