
DISTRICT CONSERVATION AGENT'S REPORT



TO:

State Corporation Commission Conservation Division 211 North Broadway Wichita, Kansas	FILE NO. 38-34
	LOCATION SE SE NW
	SEC. 8 TWP. 11 RGE. 17
Dry HoleAbandoned Oil Well Abandoned Ga	as Well
I have this date completed supervision of plugging of:	
Well No. Lease Gumble	
Address	Union Natl Bak Bldg
FieldCounty	
Total DepthFeet.	
Plugging Contractor R & S Pipe Pulling Co & 1	Halliburton Cementing
Plugging Contractor's License Nol	
Address	
(Describe briefly the manner in which the 8 5/8" at 866 bcirculated with cement - $5\frac{1}{2}$ " at	e well was plugged) at 341 with 80 sax
cement behind.	
Filled with sand to 3400' set 4 sax cement w	ith dump bailer,
pulled 2793' $5\frac{1}{8}$ " - pumped hole full mud (40	sax Gel) - pumped
cementing plug to 2501, followed by 80 sax ce	ement - cement 250
to O'.	
Mudding and cementing by Halliburton Co - 400	O# pump pressure.
SHE CONVERTED DIST	Edon Seiler ict Conservation Agent

FEB 20 1906 OZ - 20 -54 ONSERVATION DIVISION Wighita, Kangag Date 2-19-56

PLUGGING

MAL SE TIL NIW

DOOK MOLSS UNESY