

J-W OPERATING COMPANY

P. O. Box 305
WRAY, COLORADO 80758-0305

OIL AND GAS PROPERTY MANAGEMENT

GZ
15-003-20356-0000
23-2-42W
PHONE (970) 332-3151

September 28, 1999

Kansas Corporation Commission
Wichita State Office Building

RE: Rath #2
One Point Stabilized
Flow Test

ATTN: Mr. Jim Hammen

Dear Mr. Hammen:

Per our conversation concerning the one point stabilized flow test on the Rath #2, we have used the assigned standard slope of 0.85 provided by the K.C.C. for low volume gas wells. The multi point test shows the well loaded up with water and was unable to unload itself. Due to the extremely low flow rate & pressure (see attached four point test), a negative slope resulted. If there is any additional information that I can provide, do not hesitate to call.

Sincerely,

J-W Operating Company



Kendall L. Read
Technical Engineer

KLR/kp

RECEIVED
KANSAS CORPORATION COMMISSION

OCT 18 1999
10-18-99
REGULATION DIVISION
WICHITA, KS