DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission

Conservation Division 800 Bitting Building	
Wichita, Kansas	
	FILE NO. 69-2 15-05/-02/69
	LOCATION NE SE SW
	SEC. 14 TWP. 11 RGE. 17
Dry Hole Abandoned Oil Well	·
I have today completed supervision of pl	
Well No. A-5 Lease Hall	
Operator Cities Service Co Addr	·
Field Bemis Coun	ty Ellis
Total Depth 3367 Feet.	
(Describe briefly the manner in wh	ich the well was plugged)
8 5/8" at 1075' with 335 sax cement	behind - $5\frac{1}{2}$ " at 3362!
with 100 sax behind - $5\frac{1}{2}$ " squeezed	at 2040' with 600 sax cement.
Dumped 5 sax cement in bottom with	dump bailer - pulled 1570
o ¹ / ₂ " - filled hole with heavy mud to	250', set rock bridge
and 15 sax cement - filled with mud	to 35', set rock and 10 sax
to bottom cellar.	
S: WE COMPARATE SOMETIMESTON	
MAY 2 - 1951	7
Concervation division	Redon to the
PLIGONO	District Conservation Agent
DE CONTRACTOR D	ate 4-30-51