

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

W

FILE NO. _____

LOCATION NE-NE-SW

SEC. 16 TWP. 11 RGE. 17W

Dry Hole Bad Hole Abandoned ~~Oil~~ Well X Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1-A Lease Bemis


Operator Nadel & Gussman Address Tulsa - Okla

Field Bemis County Ellis

Total Depth 827 Feet.

(Describe briefly the manner in which the well was plugged)

Sewer Pipe 8 1/8 - 200 ft Cemented all around -
Pumped 200 Sacks of cement into the hole -
filling the hole from top to bottom - Same Oil Well
Reinforcing Co. did the Plugging - Needer Supply -
Drilling Contractor - moved the Pig 18 ft & started
Bemis Well #1-B



C. N. Stough -
District Conservation Agent

Date 7-16-47

X

PLUGGING
FILE SEC 16 T 11 R 17W
BOOK PAGE 120 LINE 35

07-18-47