

KCC OIL/GAS REGULATORY OFFICES

Date: 10/14/10

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
 Op Name: American Warrior  
 Address 1: P.O. Box 399  
 Address 2: P.O. Box 783188  
 City: Garden City  
 State: Kansas Zip Code: 67846 -0399  
 Operator Phone #: (620) 587-3224

API Well Number: 15-083-21,670-00-00  
 Spot: NE-NW-NW-SE Sec 18 Twp 21 S Rng 24  E /  W  
 2550 (2579) Feet from  N /  S Line of Section  
 2000 (1949) Feet from  E /  W Line of Section  
 GPS: Lat: 38.22509 Long: 99.99846 Date: 10/14/10  
 Lease Name: Fuller Well #: 1-18  
 County: Hodgeman

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 222W/150sxs cement  
 TD @ 4487'  
 5-1/2" @ 4485'W/120sxs cement  
 Port Collar @ 1563' cemented with 160sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

**RECEIVED**  
**OCT 22 2010**  
**KCC WICHITA**

Verification Sources:


Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**RECEIVED**  
**OCT 19 2010**

 Form: 02/22/2008

KCC DODGE CITY

Date: 10/14/10

District: 01

License #: 4058

Op Name: 4058

Spot: NE-NW-NW-SE Sec 18 Twp 21 S Rng 24  E  W

County: Hodgeman

Lease Name: Fuller Well #: 1-18

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Gauge Connections  Yes  No

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21,670-00-00	2579FSL 1949FEL	NE-NW-NW-SE	38.22509-99.99846	1-18	New well. Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division