KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/20/10</u>	District: <u>01</u>					
	New Situation Lease Inspection					
	Response to Request Complaint					
	Follow-Up Field Report					
Operator License No: 30931	API Well Number: <u>15-083-21,663-00-00</u>					
Op Name: Daystar Petroleum, Inc.	Spot: NE-SW-NE-SW Sec 18 Twp 22 S Rng 22 E / W					
Address 1: P.O. Box 360	1880 (1880) Feet from N/ S Line of Section					
Address 2:	1850 (1832) Feet from E/W Line of Section					
City: Valley Center	GPS: Lat: <u>38.13608</u> Long: <u>99.78250</u> Date: <u>9/20/10</u>					
State: <u>Kansas</u> Zip Code: <u>67147 -0360</u>	Lease Name: <u>Sebes B</u> Well #: <u>1-18</u>					
Operator Phone #: <u>(620) 583-5527</u>	County: Hodgeman					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None						
	·					
Persons Contacted:						
Findings:						
8-5/8" @ 344'W/225sxs						
TD @ 4578'						
5-1/2" @ 4573'W/200sxs Port Collar @ 1435'cemented with 250sxs 6	0/40 8% gol 1/4# flo sool 15sys to nit					
For Collai @ 1435 cemented with 2505x5 0	0/40-8%gei-1/4# 110 Seai135x5 to pit.					
Action/Recommendations: Follow	Up Required Yes No Date:					
None, Alt.II requirements have been met.	·					
Verification Sources:	Photos Taken:					
✓ RBDMS	A Program					
	ourthouse By: Michael Maier					
Other:						
Retain 1 Copy District Office RECEIVED Send 1 Copy to Conservation Division	RECEIVED					
SEP 2 4 2010	SEP 2 7 2010 Form:					
KCC DODGE CITY	KCC MICHITA					
	THE STATE OF THE S					

Date: <u>09/20/10</u>		-	District	: 01	_	License #: 30931
Op Name: 30931			Spot: <u>NE-SW-NE-SW</u>			Sec <u>18 </u>
County: Hodgeman	***************************************		Lease Na	ame: <u>Se</u> l	oes B	Well #: <u>1-18</u>
I.D. Sign Yes	No		\$3	Gas V	enting	Yes No
Tank Battery Condi Condition: Good		le Overflow	ing 🔊	Pi Fluid		ft; Approx. Size:ft. xft.
Pits, Injection Site Fluid Depth:	ft; Approx. S	ize:ft.	xft.	\vdash	ltwater Pi	ripelines e: Y N Tested for Leaks: Y N
Oil Spill Evidence				FI	owing Hol	eles
Abandoned Well	Potential Pollu	ntion Problem	Yes No 🗠	Т	A Wells	
Lease Cleanliness			<u> </u>	М	onitoring	Records
Very Good Sa	atisfactory	Poor Very	-			
SWD/ER Injection Well			Hodgeman 🗗	Gano	e Connect	tions Yes No
Permit #: Pr		•				; T/C Annulus:; C/SP Annulus:
Permit #: Pi						; T/C Annulus:; C/SP Annulus:
Permit #:Pi						; T/C Annulus:; C/SP Annulus:
						; T/C Annulus:; C/SP Annulus:
					τ	
API Number	Footages	Spot Location	GPS		Well #	Well Status
15-083-21,663-00-00	1880FSL 1850FWL	NE-SW-NE-SW	38.13608-99.7	8250	1-18	New well, Alt,II completed
				-		