KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Diamond B Miami Flood, Ltd	License Number: 5876
Operator Address: 34475 W 263 Street	
Contact Person: Jim Ferley	Phone Number: (913) 294 - 3841
Permit Number (API No. if applicable): 15-121-28763-00-00	Lease Name & Well No.: Tarr I D-5
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	ne _ nw _ sw _ sw
Settling Pit	Sec. 19 Twp. 16 R. 22
Workover Pit Haul-Off Pit	1260 Feet from North / South Line of Section
	586 Feet from ☐ East / ✓ West Line of Section
	Miami County
Date of closure: September 1, 2010 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
natural clays in soil	RECEIVED
	OCT 1 8 2010
	OCT 1 8 2010 KCC WICHITA
Abandonment procedure of pit:	OCT 1 8 2010 KCC WICHITA
Abandonment procedure of pit: All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some 6	KCC WICHITA
All free water was sucked off top of both pits and disposed	KCC WICHITA
All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some 6	d of in the injection system on this lease, 60 plus days then backfilled and leveled.
All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some of the undersigned hereby certifies that he / she is	d of in the injection system on this lease, 60 plus days then backfilled and leveled.
All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some of the undersigned hereby certifies that he / she is	d of in the injection system on this lease, 60 plus days then backfilled and leveled.
All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some of the undersigned hereby certifies that he / she is	d of in the injection system on this lease, 60 plus days then backfilled and leveled. for
All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some of the undersigned hereby certifies that he / she is	d of in the injection system on this lease, 60 plus days then backfilled and leveled.
All free water was sucked off top of both pits and disposed permit number E-20735. Pit was allowed to air dry some of the undersigned hereby certifies that he / she is	d of in the injection system on this lease, 60 plus days then backfilled and leveled.