

KCC OIL/GAS REGULATORY OFFICES

Date: 11-1-10

District: 1

Case #: _____

New Situation

Lease Inspection

Response to Request

Complaint

Follow-Up

Field Report

Operator License No: 5144

API Well Number: 15-101-22260-0000

Op Name: Mull Drilling Company Inc Section: NW SE NW SE Sec 6 Twp 19 S Rng 28 E / W

Address 1: 1700 N Waterfront Parkway 1724 Feet from N / S Line of Section

Address 2: Bldey 200 171B Feet from E / W Line of Section

City: Wichita GPS: Lat: _____ Long: _____ Date: _____

State: Kansas Zip Code: 67206 Lease Name: Hinemans Trusts Well #: 1-6

Operator Phone #: 316 264-6366 County: Lane

Reason for Investigation:

Alterrate II Cementing

Problem:

Persons Contacted:

Findings:

8 3/8 @ 229'. 4 1/2 % 4697 w 230sx. Port Collar % 2141'. (By log)
Swift Services mixed & pumped 200sx 5MD cement thru
port collar. Circ 25sx to pit.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alterrate II Cementing Complete

Verification Sources:

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

Photos Taken: _____

By: Ken Sehtik

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

NOV - 9 2010

KCC DODGE CITY

RECEIVED

DEC 01 2010

KCC WICHITA

Form: _____