

# KCC OIL/GAS REGULATORY OFFICES

Date: 12/01/10

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-083-21,682-00-00

Op Name: American Warrior

Spot: SE-NE-SE-SW Sec 3 Twp 21 S Rng 25  E /  W

Address 1: P.O. Box 399

719 (736) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2501 (2534) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.24921 Long: 100.05611 Date: 12/1/10

State: Kansas Zip Code: 67846 -0399

Lease Name: Borger Well #: 2-3

Operator Phone #: \_\_\_\_\_

County: Hodgeman

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 234W/150sxs cement  
TD @ 4520'  
5-1/2" @ 4510'W/125sxs cement  
Port Collar @ 1569' cemented with 155sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: 7/14/09

Alt.II requirements have been met

**RECEIVED**  
**DEC 08 2010**  
**KCC WICHITA**

Verification Sources:

Photos Taken: \_\_\_\_\_

- RBDMS
- T-1 Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**RECEIVED**  
DEC - 6 2010  
KCC DODGE CITY

Form: 02/22/2008

Date: 12/01/10

District: 01

License #: 4058

Op Name: 4058

Spot: SE-NE-SE-SW Sec 3 Twp 21 S Rng 25  E  W

County: Hodgeman

Lease Name: Borger Well #: 2-3

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N  7' led for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Flange Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21.682-00-00	736FSL 2534FWL	SE-NE-SE-SW	38.24921-100.05611	2-3	New well, All completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division