

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION CSW SE

SEC. 20 TWP. 11 RGE. 17

Dry Hole _____ Abandoned Oil Well X Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. J-1 Lease Hadley

Operator Champlin Refg Co Address Box 167 Ellinwood, Kans

Field _____ County Ellis

Total Depth ~~3525~~ 3503 Feet.
ANSELL

Plugging Contractor Champlin Refg & Halliburton Cementing Co

Plugging Contractor's License No. _____

Address _____
(Describe briefly the manner in which the well was plugged)

8 5/8" at 1195' circulated with cement - 4 1/2" at 3471' with
175 sax cement behind.

Filled with cement and calseal 3525' to 3440' - perforated
4 1/2" at 600' - pumped cementing plug to 600', circulating cement
between 4 1/2" and 8 5/8" also filling hole 4 1/2" with cement to 0'.

No pipe recovery - plugging back and cementing by Halliburton
cementing Co.

RECEIVED
STATE CORPORATION COMMISSION
RCUP
MAR 22 1956
03-22-56
CONSERVATION DIVISION
Wichita, Kansas

Edson Peck
District Conservation Agent
Date 3-19-56

PLUGGING
FILE SEC 20 T 11 R 17W
BOOK PAGE 47 LINE 9