



DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. 16-33

LOCATION CSL N $\frac{1}{2}$ NE $\frac{1}{4}$

SEC. 21 TWP. 11 RGE. 17

Dry Hole SWD Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. SWD #1 Lease Bemis

Operator El Dorado Refg Co Address El Dorado, Kans

Field Bemis County Ellis

Total Depth 716' Feet.

(Describe briefly the manner in which the well was plugged)

8 5/8" at 280' circulated with cement - 7" at 571' circulated with cement.

Pumped in 300 sax cement with Halliburton Co, filling hole to bottom cellar with cement.

7-26-50
JUL 26 1950

J. Ellison
ST. CONSERVATION
District Conservation Agent

Date 7-16-50

PLUGGING
FILE SEC 21 T 11 R 17W
BOOK PAGE 16 LINE 33