DISTRICT CONSERVATION AGENT'S REPORT

TO:	
State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas	
	FILE NO. 89-14
and the second s	LOCATION NWXNWXXX NW SE*SE
	SEC. 21 TWP. 11 17RGE. 17
Dry HoleAbandoned Oil Well	X Abandoned Gas Well
I have today completed supervision of	plugging of:
Well No. 6 Lease	Bemis
Operator Cities Service Co Address	Russell, Kans
Field Bemis County	Ellis
Total Depth 3376 Feet.	
(Describe briefly the manner in	which the well was plugged)
15 at 120 circulated with cement	- 10" at 1100! circulated with
cement - 7" at 3370' - Heavy mud to	27201 - rock and 10 sax cement -
7" ripped and pulled at 2370! - Hea	vy mud to 250', wood plug, rock
and 20 sax cement - Heavy mud to 30) wood plug, rock and 10 sax
cement.	
	DECETED
	Consequence of the Consequence o
	APR 2 5 1949 STATE CORPORATION
	District Conservation Arent
Da CING Da	ate 4 - 20 - 49

