	051-05560-0000
TO:	API Number: 15-07-03-41
STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING	SE NE SE /4 SEC. 26 , 11 S, 17 W
130 SOUTH MARKET, SUITE 2078	1700 feet from S section line
130 SOUTH MARKET, SUITE 2078 WICHITA, KANSAS 67202	feet from E section line
**	
Operator license#_5447	Lease: McCord "A" Well # 10
operator licensem Jawi	Dease. Mocold A Well #
Operator: OXY USA, Inc.	County: Ellis
Address: 110 S. Main - Suite #800	Well total depth 3654 118.76 feet
Wichita, Kansas 67202	Conductor Pipe: 12 1/2 inch @ 66 0 feet
J.D. Hininger	Surface pipe 8 5/8 Inch @ 360 feet
Aband. oil well_x, Gas well, Input well	_, SWD, D & A
Plugging contractor: Halliburton Cement Company	License#
Address House Forence 67601	
Address: Hays, Kansas 67601	
Company to plug at: Hour: A.M. Day: 19	Month: December Year: 1995
Plugging proposal received from: Gary Wagone	<u>r</u>
Company: OXY USA, Inc.	Phone: 913-434-7681
Were: 12 1/2" conductor 66' cwc. w/175 sxs. 8 5/8" S.P 360' cwc. w/175 sxs cement. 5 1/2" casing set at 3553' w/100 sxs cement. C.I.B.P. at 3470'. Perfs at 3359' - 3445'. 5 1/2" casing squeeze at 410' w/229 sxs cement at 763' w/650 sxs cement. Proposal - 325 sxs 60/40 pozmix - 10% gel and 5 sxs hulls. Perforate 5 1/2" casing at 1325' and 1975'. Pump in casing with pump truck. Load all casing and annulus into cement from top to bottom. Shut in under pressure.	
in under pressure.	
Plugging Proposal Received by: Marion J. S	
Plugging operations attended by agent? All[X], Part[], None[]
Completed: Hour: 10:00 A.M. , Day: 19 , M	onth: December , Year: 1995
Actual plugging report: OXY USA, Inc. ordered 325	
	5 sxs 60/40 pozmix - 10% gel and 5 sxs hulls.
Pumped in with pump truck. 5 1/2" casing was a	squeezed with 650 sxs cement.
Pumped in with pump truck. 5 1/2" casing was a 1) Perforated 5 1/2" casing at 1325' and 1925'.	squeezed with 650 sxs cement.
Pumped in with pump truck. 5 1/2" casing was s 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for	squeezed with 650 sxs cement.
Pumped in with pump truck. 5 1/2" casing was a 1) Perforated 5 1/2" casing at 1325' and 1925'.	squeezed with 650 sxs cement.
Pumped in with pump truck. 5 1/2" casing was s 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#.	squeezed with 650 sxs cement. Ollowed with 225 sxs cement with 5 sxs hulls ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface.
Pumped in with pump truck. 5 1/2" casing was sometimes 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to	ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface.
Pumped in with pump truck. 5 1/2" casing was sometimes 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to	ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface. STATE CORPORATION COMMISSION
Pumped in with pump truck. 5 1/2" casing was s 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable	ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface. STATE CORPORATION COMMINISSICAL STATE CORPORATION CORPORATION COMMINISSICAL STATE CORPORATION CORPORATIO
Pumped in with pump truck. 5 1/2" casing was sometimes 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable Remarks: Cemented by Halliburton Cement Compa	ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface. STATE CORPORATION COMMISSION Anhy Dlug: YES_X NO Dakota plug: YES_X NO
Pumped in with pump truck. 5 1/2" casing was sometimes of the second statement statement of the second	ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface. STATE CORPORATION COMMUNICATION Apply: plug: YES X NO Dakota plug: YES.X , NO Elevation: WALLES OF GL
Pumped in with pump truck. 5 1/2" casing was a 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable condition of casing(in hole): GOOD BAD Bottom plug(in place): YES , CALC , NO	ake cement. Max. P.S.I. 500#. S.I.P. 500#. e at surface. STATE CORPORATION COMMUNISSION Anhy Dlug: YES_X NO Dakota plug: YES_X NO Elevation: GL
Pumped in with pump truck. 5 1/2" casing was a 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable Remarks: Cemented by Halliburton Cement Compact Condition of casing(in hole): GOOD BAD Bottom plug(in place): YES CALC NO Plugged through TUBING CASING . I did[X] / did note observe the plugging.	STATE CORPORATION COMMISSION Anhy Dlug: YES X NO Dakota plug: YES X NO Elevation: GL (agent)
Pumped in with pump truck. 5 1/2" casing was a 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable condition of casing(in hole): GOOD	STATE CORPORATION COMMISSION Anhy Dlug: YES X NO Dakota plug: YES X NO Elevation: GL (agent)
Pumped in with pump truck. 5 1/2" casing was and 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable Remarks: Cemented by Halliburton Cement Compact Condition of casing(in hole): GOOD BAD Bottom plug(in place): YES, CALC, NO Plugged through TUBING, CASING I did[X] / did[1006]] observe the plugging.	STATE CORPORATION COMMISSION Anhy Dlug: YES X NO Dakota plug: YES X NO Elevation: GL (agent)
Pumped in with pump truck. 5 1/2" casing was a 1) Perforated 5 1/2" casing at 1325' and 1925'. 2) Pumped in 5 1/2" casing with 10 sxs cement for added. Max. P.S.I. 1000#. S.I.P. 350#. 3) Squeezed 8 5/8" x 5 1/2" annulus, would not to 12 1/2" x 8 5/8" annulus 66' - cement visable condition of casing(in hole): GOOD	STATE CORPORATION COMMISSION Anhy Dlug: YES X NO Dakota plug: YES X NO Elevation: GL (agent)