

KCC OIL/GAS REGULATORY OFFICES

Date: 10/28/10

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 9067

API Well Number: 15-135-25,128-00-00

Op Name: DayMar Resources

Spot: SE-NE-SE-SE Sec 26 Twp 20 S Rng 24 E / W

Address 1: 234 W 11th Ste A

705 (704) Feet from N / S Line of Section

Address 2: P.O. Box 70

295 (302) Feet from E / W Line of Section

City: Hays

GPS: Lat: 38.27803 Long: 99.93456 Date: 10/28/10

State: Kansas Zip Code: 67601 -3805

Lease Name: McCreight Unit Well #: 1

Operator Phone #: (785) 625-0020

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8-5/8" @ 348'W/175sxs cement
TD @ 4462'
5-1/2" @ 4461'W/135sxs cement
Port Collar @ 1496' cemented with 175sxs-smd-1/4# flo seal-2%cc--20sxs went to pit

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None Alt.II requirements have been met.

RECEIVED

NOV - 1 2010

MP

RECEIVED

NOV 08 2010

KCC WICHITA

Verification Sources:

KCC DODGE CITY

Photos Taken: _____

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 

Date: 10/28/10

District: 01

License #: 9067

Op Name: 9067

Spot: SE-NE-SE-SE Sec 26 Twp 20 S Rng 24 E W

County: Ness

Lease Name: McCreight Unit Well #: 1

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.128-00-00	704FSL 302FEL	SE-NE-SE-SE	38.27803-99.93456	1	New well, Alt. II completed

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: _____