KCC OIL/GAS REGULATORY OFFICES

| Date: <u>01/04/11</u> | District: 0 | 1 | Case #: | | | | |
|---|--------------------|---------------------------|---------------------------------------|--|--|--|--|
| | New S | ituation | Lease Inspection | | | | |
| | Respon | nse to Request | Complaint | | | | |
| | Follow | -Up | Field Report | | | | |
| Operator License No: <u>5144</u> | API Well Nu | ımber: <u>15-135-25,1</u> | 85-00-00 | | | | |
| Op Name: Mull Drilling Company, Inc. | Spot: <u>SW-</u> | SE-NE-SWSec_ | 11 Twp 20 S Rng 23 E / W | | | | |
| Address 1: 1700 N Waterfront Pkwy | 1617 (1 | 633) | Feet from N/ S Line of Section | | | | |
| Address 2: Bldg. 12000 | | | Feet from E/W Line of Section | | | | |
| City: Wichita | GPS: Lat: <u>3</u> | 38.32422 Long: | 99.83600 Date: 1/4/11 | | | | |
| State: Kansas Zip Code: 67206 -6637 | Lease Name | : <u>Reinert</u> | Well #: <u>1-11</u> | | | | |
| Operator Phone #: (316) 264-6365 | County: N | ess | | | | | |
| Reason for Investigation: | | | | | | | |
| Witness Alt.II | | | | | | | |
| Problem: | | | | | | | |
| None, cement circulated to surface | | | | | | | |
| Persons Contacted: | | | | | | | |
| Eindings | | - MA 15 - 1874 | | | | | |
| Findings: | | | | | | | |
| 8-5/8" @ 228' W/160sxs cement TD @ 4450' | | | | | | | |
| 4-1/2" @ 4445' W/275sxs cement | | | | | | | |
| Port Collar @ 1503' cement with 180sxs-smd-1/4# flo seal-2%cc-20sxs went to pit | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Action/Recommendations: Follow | Up Required | √Yes No ✓ | Date: | | | | |
| Alt.II requirements have been met. | | hariattisi baggared | | | | | |
| · | | KAN | SAS CORPORATION COMMISSION | | | | |
| | | 0 to the 64 | SE COLL CLEATION CONTRIBUTION | | | | |
| RECEIVED | | | JAN 9 2 2011 | | | | |
| JAN 1 0 2011 | | | RECEIVED | | | | |
| Verification Sources: C DODGE CITY | | | Photos Taken: | | | | |
| RBDMS KGS | ΓA Program | | | | | | |
| | Courthouse | By: <u>Michael N</u> | 1aier | | | | |
| Other: | | | · · · · · · · · · · · · · · · · · · · | | | | |

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>



| Date: <u>01/04/11</u> | | _ | District | 01 | | License #: <u>5144</u> | | | |
|---|--|--|------------------|--|--------------------|--|--|--|--|
| Op Name: <u>5144</u> | | | Spot: <u>S</u> \ | Spot: SW-SE-NE-SW Sec 11 Twp 20 S Rng 23 E V W | | | | | |
| County: Ness | | | Lease Na | Lease Name: Reinert Well #: 1-11 | | | | | |
| I.D. Sign Yes No | | | S | Gas V | Gas Venting Yes No | | | | |
| Tank Battery Condition Condition: Good Questionable Overflowing | | | ing 🔊 | Pi Fluid | | ft; Approx. Size:ft. xft. | | | |
| Pits, Injection Site Fluid Depth: | _ft; Approx. S | iize:ft | . xft. | - | iltwater Pi | <u> </u> | | | |
| Oil Spill Evidence | | | | FI | owing Hol | les | | | |
| Abandoned Well | Potential Poll | ution Problem | Yes No 🕥 | Т | A Wells | | | | |
| Lease Cleanliness Very Good S | atisfactory | Poor Ver | y Bad | М | onitoring | Records | | | |
| SWD/ER Injection Well Permit #: Pi Permit #: Pi Permit #: Pi Permit #: Pi | Yes ressure – Acturessure – Actures – Actu | No al: psi; Aud al: psi; Aud al: psi; Aud | | Tubii Tubii Tubii | ng: ng: ng: | ions Yes No ; T/C Annulus:; C/SP Annulus:; ; T/C Annulus:; C/SP Annulus:; ; T/C Annulus:; C/SP Annulus:; ; T/C Annulus:; C/SP Annulus: | | | |
| rermit #: F1 | ressure – Actu | ai: psi; Au | morizeu: psi | Lubii | ıg | , i/c Annulus, C/Si Annulus | | | |
| API Number | Footages | Spot Location | GPS | | Well # | Well Status | | | |
| <u>15-135-25,185-00-00</u> | 1633FSL 2046FWL | SW-SE-NE-SW | 38.32422-99.83 | 3600 | 1-11 | New well, Alt.II completed | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | - | | | | | | | | |