

# KCC OIL/GAS REGULATORY OFFICES

Date: 01/26/11

District: 1

Case #: \_\_\_\_\_

- New Situation  
 Response to Request  
 Follow-Up

- Lease Inspection  
 Complaint  
 Field Report

Operator License No: 8996

API Well Number: 15-083-21687-00-00

Op Name: Mid-Continent Resources, Inc.

Spot: SW-NE-NE-SW Sec 18 Twp 21 S Rng 24  E /  W

Address 1: P.O. Box 399

2038 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2079 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.22366 Long: 100.00240 Date: 1/26/11

State: KS Zip Code: 67846 -0399

Lease Name: Danny King Well #: 1-18

Operator Phone #: (620) 275-7461

County: Hodgeman

### Reason for Investigation:

Company requested a state witness to the Alternate II cementing job.

### Problem:

Alternate II cementing requirements have not been met.

### Persons Contacted:

None.

### Findings:

8 5/8" was set @ 232' with 150 sx cement. 5 1/2" was set @ 4998' with 125 sx cement on primary cementing job. Company opened port collar @ 1547'. Swift Services, Inc. pumped 175 sx SMD cement, circulating 10 sx to the pit. Closed port collar.

RECEIVED

JAN 31 2011

KCC WICHITA

### Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None. Alternate II cementing requirements have been met.

GPS converted footages are 2068' FSL & 2127' FWL.

RECEIVED

JAN 28 2011

### Verification Sources:

KCC DODGE CITY

Photos Taken: 0

- |  |  |                                     |
|--|--|-------------------------------------|
| <input checked="" type="checkbox"/> RBDMS                          | <input type="checkbox"/> KGS                       | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database                              | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input checked="" type="checkbox"/> Other: <u>On-site witness.</u> |  |                                     |

By: Eric MacLaren

Eric MacLaren

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_

Date: 01/26/11

District: 1

License #: 8996

Op Name: 8996

Spot: SW-NE-NE-SW Sec 18 Twp 21 S Rng 24  E  W

County: Hodgeman

Lease Name: Danny King Well #: 1-18

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Gauge Connections  Yes  No

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_