TO:

STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING

130 SOUTH MARKET, SUITE 2078

WICHITA, KANSAS 67202

API Well Number: <u>15-113-20195-00-00</u>

Spot: SESESW

Sec/Twnshp/Rge: 17-17S-3W

350 feet from S Section Line,

3137 feet from E Section Line

Lease Name: REESE COMMUNITY

Well #: 1

County: MCPHERSON

Total Vertical Depth: 3478 feet

Operator License No.: 6306

Op Name: TOM BROWN CONSTRUCTION, INC.

Address: 54921 RIVERVIEW DR

ASTOR, FL 32102

String SURF	Size 12	Depth (ft) 100	Pulled (ft)	Comments 76SXS	
COND	7	100		76 SX	
PROD	,	3476	,	75SXS	

Well Type: OlL

UIC Docket No:

Date/Time to Plug: 08/16/2010 10:30 AM

Plug Co. License No.: 31529

Plug Co. Name: MIKE'S TESTING & SALVAGE, INC.

Proposal Rcvd. from: KELSO CASING

Company:

Phone: (620) 938-2943

Proposed Plugging Method:

Proposed AS PER KCC

Plugging Proposal Received By:

Date/Time Plugging Completed: 08/16/2010 3:15 PM

WitnessType: COMPLETE (100%)

KCC Agent: SHANE JONES

Actual Plugging Report:

Perfs:

8/15/2010 KELSO'S LAID OUT THE WELL, DROPPED SAND FOR BOTTOM PLUG AND
PERFORATED 7" @ 350'. 8/16/2010 KELSO'S TAGGED SAND @ 3420' AND CAPPED IT
WITH 7 SXS CEMENT. THEY HAD SCHULZ OUT TO DIG OUT WELL HEAD. THEY
FOUND THE WELL HAD A 6' X 8' CEMENT CELLAR. ONCE THEY GOT THE
CELLAR DUG DID NOT FIND AN SURFACE HEAD. FURTHER CLEANING AND
DIGGING FOUND THE 12" HAD BEEN ORANGE PEELED AND WELDED TO THE 7".
THE CELLAR FLOOR HAD BEEN PURED TO THE TOP OF THE 12". KELSO'S CUT A
WINDOW IN THE 12" AND RAN 2 7/8" TUBIN INSIDE THE 7" TO 360'. COPELAND
TIED ON AND BROKE DIRCULATION WITH WATER. THEY SWITCHED TO
CEMENT. THEY PUMPED APPROX 250 SXS BEFORE RAN OUT OF WATER. WHILE
WAITING ON THE WATER TRUCK TO GO GET MORE WATER. THE OTHER TRUCK
FINISHED SUCKING OUT THE CELLAR. NOTICED WE HAD JUST STARTED TO
CIRCULATE CEMENT UP THE BACKSIDE WHEN WE HAD RAN OUT OF WATER.
WATER TRUCK RETURNED AND STARTED PUMPING DOWN BACKSIDE AGAIN
GOT GOOD CEMENT CIRCULATED UP THE BACKSIDE. THEY THEN OPENED THE
BACKSIDE OF THE 7" HEAD AND PUMPED ANOTHER 35 SXS AND CIRCULATED
TO SURFACE. KELSO'S PULLED TUBING AND COPELAND TOPPED OFF WELL
HEAD WITH 10 SXS. THEY FINISHED @3:15 PM. THEY USED A TOTAL OF 295 SXS
OF 60/40 POS W/ 4% GEL TK #34584. 8/18/2010 I CHECK TOP PLUG. IT WAS DOWN
ABOUT 4' ON THE BACKSIDE AND ABOUT 25' DOWN THE INSIDE OF THE 7". I
SPOKE TO DENNY WALKER AND HE WILL HAVE SOME SLURRY BROUGHT OUT
AND TOP IT OFF.

Тор	Bot	Thru	Comments
3476	3478	ОН	
			D==-
			RECEIVED
			SEP 0 1 2010
			OLI W I ZUIU
		KI	CC WICHITA
		1.66	ALIDOINA DE

Remarks:

District: 02

PLUGGED BY COMMISSION ORDER. WELL HAS BEEN DOWN MORE THAN 10 YEARS. CASE CLOSED

8/16/2010 SJ

Plugged through: TBG

Signed

(TECHNICIAN)