23 457-00-00 90431-10-10

To:	API NUMBER	<u> 15-205-</u> –	707 <u>9</u>	<i>UV~UU</i>
STATE CORPORATION COMMISSION	SW SW NW	_Sec/Twp/Rge	Sec 3 T28	S R17E
Wichita State Office Bldg PLUGGING SECTION	2739 (gps)	_feet from so	outh section I	line
130 S. Market, Room 2078 Wichita, Kansas 67202	4954 (gps)	_feet from ea	ast section lir	ne
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Stover	STO 11	
Operator License # 101	County	Wilson		
Operator: State Of Kansas Fee Fund	Well Total Depth		1632	feet
Name & Stover Lease Project	Production Pipe:	2.875"	_Size Feet	1632'
Address	Surface Casing:	6.25	_Size Feet	20'
AB oil well Gas Well SW	O Well/ Input Well	D-22421.0	_ D&A	
Other well as hereinafter indicated:				
Plugging Contractor: Kepley Well Service, LLC			_ Lic. #	33749
Address: 19245 Ford Road, Chanute, Kansas 66720				·
Company to plug at: Hour: Day	:29	Month:	9	2010
Plugging proposal received from: Mike Kepley				
Company Name: Kepley Well Service, LLC	<u></u>	_Phone:	620-431-8	945
Were: Clean well to TD and pump full of portland of	ement.			
Plugging Proposal R	eceived by:	Alan M. Du	nning TECHNICIAN	1
Plugging Proposal R Plugging attended by Agent: All	eceived by:	Alan M. Du	TECHNICIAN	xxxxxx
	Part		TECHNICIAN None	XXXXXX
Plugging attended by Agent: All	Part : 29	Month:	TECHNICIAN None	2010
Plugging attended by Agent: All Operations Completed: Hour: Day	Part : 29 washed down to 161	Month:	TECHNICIAN None 9 vas pumped fi	XXXXXX 2010 ull of
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: All Day At 1" cement string was	Part 29 washed down to 161 of 69 sacks of portl	Month:	TECHNICIAN None 9 vas pumped fi	XXXXXX 2010 ull of
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: A 1" cement string was cement from btm to top thru this cement string. A total	Part 29 washed down to 161 of 69 sacks of portl	Month:	TECHNICIAN None 9 vas pumped fi	2010 ull of plug
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: A 1" cement string was cement from btm to top thru this cement string. A total	Part 29 washed down to 161 of 69 sacks of portl	Month:	TECHNICIAN None 9 vas pumped fi	2010 ull of plug RECEIVED
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Cement from btm to top thru this cement string. A total well. The well was cut off below plow depth and the local complete in the string was completed.	Part 29 washed down to 161 of 69 sacks of portleation restored.	Month: 5' . The well wand cement	TECHNICIAN None 9 vas pumped fu	2010 ull of plug RECEIVED FEB 1 7 2011
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: Cement from btm to top thru this cement string. A total well. The well was cut off below plow depth and the local Remarks: Control #20110002-011 This we	Part 29 washed down to 161 of 69 sacks of portleation restored.	Month: 5' . The well wand cement	TECHNICIAN None 9 vas pumped fu	2010 ull of plug RECEIVED FEB 1 7 2011
Plugging attended by Agent: All Operations Completed: Hour: Day Actual Plugging Report: A 1" cement string was cement from btm to top thru this cement string. A total well. The well was cut off below plow depth and the loc Remarks: Control #20110002-011 This well (If additional description is necessary, u	Part 29 washed down to 161 of 69 sacks of portleation restored.	Month: 5' . The well wand cement	TECHNICIAN None 9 vas pumped fu	2010 ull of plug RECEIVED FEB 1 7 2011