## KCC OIL/GAS REGULATORY OFFICES

| Date: 01/28/11  | District: <u>01</u> | · · · · · · · · · · · · · · · · · · · | Case #:                               |
|---|---------------------|---------------------------------------|---------------------------------------|
|   | New Si              | tuation                               | Lease Inspection                      |
|   | Respon              | se to Request                         | Complaint                             |
|   | Follow              | -Up                                   | Field Report                          |
|   |                     | ,                                     |                                       |
| Operator License No: 31783  |                     | mber: <u>15-101-22,2</u>              |                                       |
| Op Name: Mid-Continent Energy Operating Co.                       |                     |                                       | 7 Twp 19 S Rng 27 E / W               |
| Address 1: 100W 5th St. Ste 450                                   |                     |                                       | Feet from N/_ S Line of Section       |
| Address 2:  |                     |                                       | Feet fromE / W Line of Section        |
| City: <u>Tulsa</u>  |                     |                                       | 100.29438 Date: 1/28/11               |
| State: Ok. Zip Code: 74103 -4254                                  | Lease Name:         | Bier                                  | Well #: <u>1-27</u>                   |
| Operator Phone #: (918) 587-6363                                  | County: La          | ne                                    |                                       |
| Reason for Investigation:   |                     |                                       |                                       |
| Witness Alt.II  |                     |                                       |                                       |
| Problem:  |                     |                                       |                                       |
| None cement circulated to surface.                                |                     |                                       |                                       |
|   | ·<br>               |                                       |                                       |
| Persons Contacted:  | <u>,</u>            | · · · · · · · · · · · · · · · · · · · | · · · · · · · · · · · · · · · · · · · |
|   |                     |                                       |                                       |
| Findings:   |                     |                                       | ,                                     |
| 8-5/8" @ 'W/sxs<br>TD. @ 4700'                                    |                     |                                       | •                                     |
| 4-1/2 @ 4694'W/200sxs<br>Port Collar @ 2105W/ 250sxs-smd-1/4# flo | seal-2%cc-2         | Osxs to pit                           | RECIEWED                              |
| Total Gold G 2100 VV 2000 X Sind IV III no                        | 554, 27,000 2       | oone to pit                           | FFD 4 % 2014                          |
|   |                     |                                       | 9-18-11<br>FB 19 5011                 |
| ,   |                     |                                       | KCC WICHITA                           |
|   |                     |                                       | NOC WIGHTIA                           |
|   |                     |                                       |                                       |
| Action/Recommendations: Follo                                     | ow Up Required      | Yes No                                | Date: 7/14/09                         |
| Alt.II requirements have been met.                                |                     |                                       |                                       |
|   |                     |                                       |                                       |
|   |                     |                                       |                                       |
|   | •                   |                                       |                                       |
|   |                     |                                       |                                       |
| Verification Sources:   |                     |                                       | Photos Taken:                         |
| RBDMS KGS   | TA Program          |                                       |                                       |
| T-I Database  | Courthouse          | By: Michael M                         | aler                                  |
| Other:  |                     |                                       | CHI.                                  |
| Retain 1 Copy District OffiRECEIVED                               |                     |                                       | 2                                     |
| Send 1 Copy to Conservation Division                              |                     |                                       | Form: <u>02/22/2008</u>               |
| FEB 1 4 2011  |                     |                                       |                                       |

KCC DODGE CITY

| Date. <u>01/26/11</u>               |                   |                  | Distri       | ct. <u>U 1</u>   |           | License               | #• <u>31/03</u>   |  |  |
|-------------------------------------|-------------------|------------------|--------------|--|-----------|-----------------------|-------------------|--|--|
| Op Name: <u>31783</u>               |                   |                  | Spot: ]      | Spot: <u>E/2-NW-NE-NW</u> Sec <u>27</u> Twp <u>19</u> S Rng <u>27</u> E  W |           |                       |                   |  |  |
| County: Lane Leas                   |                   |                  | Lease 1      | Name: <u>Bje</u>   | er        | Well #: <u>1-27</u>   |                   |  |  |
| I.D. Sign Yes                       | No                |                  | 2            | Gas V  | enting [  | Yes No                | <u></u>           |  |  |
| Tank Battery Cond Condition: Good . |                   | ole Overflow     | ving         | Pi<br>Fluid  |           | ft; Approx. Size: _   | ft. xft.          |  |  |
| Pits, Injection Site                |                   |                  |              | 1 5.   | ltwater P | inelines              | িক্র ডিক          |  |  |
| Fluid Depth:                        | _ft; Approx. S    | Size:ff          | t. xft.      |  |           |                       | ed for Leaks: Y N |  |  |
| Oil Spill Evidence                  |                   |                  |              | FI   | owing Ho  | les                   |                   |  |  |
| Abandoned Well                      | Potential Poll    | ution Problem [  | Yes No 🔯     | Т  | 'A Wells  |                       |                   |  |  |
|                                     |                   |                  | <u></u> ∏м   | Monitoring Records   |           |                       |                   |  |  |
| Lease Cleanliness Very Good S       | atisfactory       | Poor Ver         | y Bad        |  |           |                       |                   |  |  |
| SWD/ER Injection Well Permit #: Pi  |                   |                  | Lane 🗐       |  |           | ions Yes No           | ; C/SP Annulus:   |  |  |
| Permit #: Pi                        |                   |                  |              |  |           |                       | ; C/SP Annulus:   |  |  |
| Permit #: Pi                        | ressure – Actu    | al: psi; Au      | thorized: p  |  |           |                       | ; C/SP Annulus:   |  |  |
| Permit #: Pi                        | rėsšure – Actu    | al: psi; Au      | thorized: ps | si Tubii   | ng:       | ; T/C Annulus:        | ; C/SP Annulus:   |  |  |
| 1. 11 - N                           |                   |                  |              | . ***  |           |                       |                   |  |  |
| API<br>Number                       | Footages          | Spot<br>Location | GPS          |  | Well #    |                       | Well<br>tatus     |  |  |
| 15-101-22,275-00-00                 | 345FNL<br>1778FWL | E/2-NW-NE-NW     | 38.37778-100 | ).29438  | 1-27      | New well, Alt.II comp | leted             |  |  |
|                                     |                   |                  |              |  |           |                       |                   |  |  |
|                                     |                   |                  |              |  |           |                       |                   |  |  |
|                                     |                   |                  |              |  |           |                       |                   |  |  |
|                                     |                   |                  |              |  |           |                       |                   |  |  |
|                                     | I                 | ľ                | 1            |  | i         | i                     |                   |  |  |