KCC OIL/GAS REGULATORY OFFICES

Date: 02/21/11	District: <u>01</u>		Case #:			
	New Situ	ıation	Lease Inspection			
	Response	e to Request	Complaint			
	Follow-U	Jp	Field Repor	d Report		
Operator License No: <u>4058</u>	API Well Num	nber: <u>15-083-21,</u> 6	689-00-00			
Op Name: American Warrior			7Twp_21	S Rng <u>24</u> □ E / ✓ W		
Address 1: P.O. Box 399	_	(1394)		N/ S Line of Section		
Address 2: P.O. Box 783188		(952)		E/ W Line of Section		
City: Garden City	•	3.23643 Long	<u></u>	Date: <u>2/21/11</u>		
State: <u>Kansas</u> Zip Code: <u>67846</u> -0399	`	Davidson				
Operator Phone #: (620) 587-3224	County: Hoc					
Reason for Investigation:						
Witness Alt.II	,			,		
Problem:						
None, cement circulated to surface						
Persons Contacted:						
				•		
			•			
Findings:						
8-5/8" @ 215W/150sxs cement TD @ 4538' 5-1/2" @ 4529'W/125sxs cement Port Collar @ 1495' cemented with 130sxs	-smd-1/4# flo s	eal-2%cc-15sx	s went to pit			
Action/Recommendations: Fol	low Up Required	Yes No	Date:			
Alt.II requirements have been met				RECEIVED		
				MAC -		
		•		MAK 0 1 2011		
		·		RECEIVED MAR 0 1 2011 KCC WICHITA		
				VICHITA		
Verification Sources:				Photos Taken:		
RBDMS T-I Database Other: RBDMS KGS District Files	TA Program Courthouse	By: <u>Michael N</u>	//aier			
Retain 1 Copy District Office Send 1 Copy to Conservation Division 4 00445	<u> </u>	-				

KCC DODGE CIT

Form: 02/22/2008

Date: <u>02/21/11</u>		-	District:	: <u>01</u>	_	Lice	ense #: <u>4058</u>		
Op Name: <u>4058</u>	.058 Spo			N-NE-S	E	Sec <u>7</u> Twp <u>21</u>	S Rng <u>24</u>	E	
County: Hodgeman			Lease Na	me: Davidson Well #: 2-7					
I.D. Sign Yes	No	,	S)	Gas Ve	enting [Yes No		3	
Tank Battery Condition Condition: Good Questionable Overflowing				Pits		ft; Approx. Siz	e:ft.	xft.	
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. x				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N					
Oil Spill Evidence				Flo	wing Hol	les			
Abandoned Well	Potential Poll	ution Problem [Yes No 🖄	TA	A Wells				
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	Mo	onitoring	Records			
SWD/ER Injection Well	Yes	No	Hodgeman 🔯	Gauge	Connect	ions Yes No		3 5	
Permit #:P	ressure – Actu	al: psi; Au	thorized: psi	Tubing	g:	; T/C Annulus:	; C/SP A	ınulus:	
Permit #:P	ressure – Actu	al: psi; Au	thorized: psi	Tubing	g:	; T/C Annulus:	; C/SP A1	nnulus:	
Permit #: P	Permit #: Pressure – Actual: psi; Authorized: ps			Tubing	g:	; T/C Annulus:	; C/SP Aı	nnulus:	
Permit #: P	ressure – Actu	al: psi; Au	thorized: psi	Tubin	g:	; T/C Annulus:	; C/SP Aı	nnulus:	
API Number	Footages	Spot Location	GPS		Well #		Well Status	,	
15-083-21,689-00-00	1394FSL 952FEK	SW-NE-SE	38.23643-99.99	9506	2-7	New well, Alt.II completed			
. •									
\^*									
						•			