KCC OIL/GAS REGULATORY OFFICES

Date: <u>03/01/11</u>	District: <u>01</u>	<u> </u>	Case	:#:
	New Sit	tuation	Lease In	spection
	Respon	se to Request	Complai	nt
	Follow-	-Up	Field Re	port
5.444	4 DE 157 11 37	1 45 405	<u> </u>	
Operator License No: 5144	•	mber: <u>15-135-</u>		a n 20
Op Name: Mull Drilling Company, Inc.	-			S Rng 22
Address 1: 1700 N Waterfront Pkwy	•	030)		N/ S Line of Section
Address 2: Bldg. 1200	•	•		Date: 3/1/11
City: Wichita			Long: <u>99.78798</u>	
State: <u>Kansas</u> Zip Code: <u>67206</u> -6637			-	Well #: <u>1-17</u>
Operator Phone #: (316) 264-6365	County: Ne	ess		
Reason for Investigation:			<u> </u>	
Witness Alt.II				
Problem:				
None, cement circulated to surface				•
	•			
				· · · · · · · · · · · · · · · · · ·
Persons Contacted:				
				•
E. N				
Findings:		·		
8-5/8" @ 228' W/160sxs cement	•			
TD @ 4530' 5-1/2" @ 4518' W/200sxs cement			•	•
Port Collar @ 1800' cement with 145sxs-sn	nd-1/4# flo se	al-2%cc-20s)	s went to pit	;
Total Collins (Collins III Collins III Col		a , , , , , , , , , , , , , , , , , ,		
			,	
Action/Recommendations: Fol	low Up Required	√ Yes No	Date: .	
,			Name of the second seco	RECEIVED
Alt.II requirements have been met.				MAR 0 9 2011
RECEIVED\)				KCC WICHITA
MAD TO 2011				Million
MAR - 7 2011				
Verification SourcesCC DODGE CITY				Photos Taken:
RBDMS KGS	TA Program	•		
T-I Database ✓ District Files	Courthouse	By: <u>Micha</u>	ael Maier	
Other:				- R
Retain 1 Copy District Office		,		9)

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: 03/01/11		<u> </u>	District:	01:	·	License #: <u>5144</u>			
	-		Spot: <u>N</u> E	E-NW-SW-	SW	Sec <u>17</u> Twp <u>16</u> S Rng <u>22</u> E 🕢 W			
County: Ness			Lease Na	me: <u>Wierm</u>	an "E	B" Well #: <u>1-17</u>			
I.D. Sign Yes No				Gas Venting Yes No					
Tank Battery Condition Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.					
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N					
Oil Spill Evidence				Flowin	g Hol	les			
Abandoned Well	Potential Poll	ution Problem [Yes No 🖾	TA W	ells				
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	Monito	oring]	Records			
SWD/ER Injection Well Permit #: Pr Permit #: Pr Permit #: Pr	ressure – Actu ressure – Actu ressure – Actu	al:psi; Aut al:psi; Aut al:psi; Aut	thorized: psi	Tubing: Tubing: Tubing:		ions Yes No ; T/C Annulus:; C/SP Annulus:; T/C Annulus:; C/SP Annulus:; T/C Annulus:; C/SP Annulus:; T/C Annulus:; C/SP Annulus:;			
API Number	Footages	Spot Location	GPS	W	ell#	Well Status			
15-135-25,210-00-00	1030FSL 415FWL	NE-NW-SW-SW	38.65737-99.78	3798 1-1	7	New well, Alt.II completed			
					•				
			· · · · · · · · · · · · · · · · · · ·		·				