KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

Circulated hole with heavy mud, set cementing plug at 600', displaced

plug. 1/2 sack hulls and 15 sax cement, heavy mud to 40', set cementing

20 sax cement through drill pipe, heavy mud to 220', set cementing

plug. 1/2 sack hulls and 10 sax cement to bottom cellar.

8 5/8" 234' circulated with cement.

| | CONSERVATION DIVISION AGENT'S REPORT | |
|---|--|--------------|
| TO: Jewel M. Ogden, Director 500 Insurance Building | | ** |
| 212 North Market Wichita 2, Kansas | | , s |
| File No. | County: Ellis | - |
| Location: NW NW NE | Sec. 31 Twp. 13 Rge. 20 (E) (| w)_ <u>·</u> |
| Name of Field: | Total Depth: 3980 | |
| I have this date completed | d supervision of plugging of: | • • |
| Lease Name: Kroeger | | |
| Operator's Full Name: | Leben Drg Co | |
| Complete Address: | 905 Central Bldg Wichita, Kans | • |
| Plugging Contractor: | same | |
| Address: | same License No. | |
| Oil WellGas Well | 1 Input Well SWD Well D & A X | х. |
| Other well as hereafter in | ndicated: | |
| Was any delay in plugging | operations caused by Conservation Division Agent? YesN | lo |
| If yes how long? | Reason: | |
| | | |
| | | |
| Operation Completed: Hour | r <u>9AM</u> Day <u>6th</u> Month <u>11</u> Year | 58 |
| The above well was plugged | d as follows: | • |

Signed: Conservation Division Agent

Remarks:

FILE SEC 31 T 13 R 20W BOOK PAGE 146LINE 32

RECEIVED PLUGGING STATECCORPORATION COMMISSION

NOV 121958