

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____
LOCATION NE NE NE
SEC. 24 TWP 14 RGE. 18W

Dry Hole x Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Brull 1516 Liberty Bank Bldg.
Operator Altman Pet Co Transit Corp. Address OKla. Okla. Okla.

Field _____ County Ellis

Total Depth 3030 Feet.

Plugging Contractor Transit Corp & Halliburton Co

Plugging Contractor's License No. _____

Address _____
(Describe briefly the manner in which the well was plugged)

8 5/8" at 1190' circulated with cement.

Filled hole with heavy mud - pumped cementing plug to 200'

followed by 80 sax cement - cement 200' to 0'.

Cementing by Halliburton Co.

Edmond Kelly
District Conservation Agent

Date 5-5-55

PLUGGING
FILE SEC 24 TWP 14 RGE 18W
BOOK PAGE 117 LINE 24

05-09-55