

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NW-SE-SE

SEC. 6 TWP. 14 RGE. 11W

Dry Hole *** Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Beisel

Operator Frontier Oil Co. Address 536 Petroleum Bldg.
 Wichita, Kansas.

Field _____ County Russell

Total Depth 3310' Feet.

Plugging Contractor Sierra Co., Inc.

Plugging Contractor's License No. _____

Address Russell, Kansas.

(Describe briefly the manner in which the well was plugged)

Surface pipe - 8 5/8" @ 365' c.w.c.

 Jet up mud pit and load hole, then pulled out drill pipe. Filled hole with
 heavy mud to 300' from top, 3/4 sx. hulls H.O.W.C.O. plug and 20 sx. cem.
 through drill pipe. Mud to 40' from top, 3/4 sx. hulls H.O.W.C.O. plug
 and 10 sx. cem. to base of cellar.

Milton E. ...
District Conservation Agent

Date 6-11-56

06-13-56

PLUGGING
FILE SEC. 6 T. 14 R. 11W
BOOK PAGE 70 LINE 44