KCC OIL/GAS REGULATORY OFFICES

Date: 04/29/11	District: 01 Case #:	Case #:				
	New Situation Lease Inspec	tion				
	Response to Request Complaint					
	Follow-Up Field Report					
20740	45 405 05 000 00					
Operator License No: 30742	API Well Number: 15-135-25,232-00-00	26 🗀 📆				
Op Name: Palomino Petroleum, Inc.	Spot: SW-SE-SE-SW Sec 11 Twp 17 S					
Address 1: 4924 SE 84th St.		N S Line of Section				
Address 2: P.O. Box 783188		E/W Line of Section				
City: Newton	GPS: Lat: 38.58128 Long: 100.16690					
State: Kansas Zip Code: 67114 _8827	Lease Name: Dumler W	'ell #: 1				
Operator Phone #: (316) 799-1000	County:					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None cement circulated to surface						
Persons Contacted:		·				
·						
Findings:						
8-5/8" @ 220'W/150sxs cement	•					
TD @ 4765'						
5-1/2" @ 4754'-cemented with 200 sxs ceme						
Port Collar @ 1918' cemented with 145sxs-s	md-1/4# flo seal-2%cc-15sxs went to pit					
		RECEIVED				
		BAAGA				
		MAY 1 3 2011				
		MAY 1 3 2011 KCC WICHIT				
		NOC WICHIT				
Action/Recommendations: Follo	w Up Required Yes No Date:					
None Alt.II requirements have been met.						
Trong / Ikin roganomente nave zeen men						
·						
·						
Verification Sources:		Photos Taken:				
RBDMS KGS	TA Program					
T-I Database District Files	Courthouse By: Michael Maier	-				
Other: RECEIVED	·					
Retain 1 Copy District Office MAY - 6 2011 Send 1 Copy to Conservation Division						

KCC DODGE CITY

Form:

Date: 04/29/11		District	01	_	Lie	cense #: <u>30742</u>		
Op Name: <u>30742</u>		Spot: <u>S\</u>	Spot: SW-SE-SE-SW Sec				_E √w	
County:		Lease Na	Lease Name: Dumler Well #: 1					
I.D. Sign Yes No		নি	Gas Ve	enting Ye	s No		3	
Tank Battery Condition Condition: Good Questionable Overflowing			Pits Fluid Depth:ft; Approx. Size:ft. xft.					
Pits, Injection Site Fluid Depth:ft; Approx. Si	ze:	ft. xft.	Ь.	twater Pipelin	. —	Tested for Leaks:	YN	
Oil Spill Evidence			Flo	wing Holes				
Abandoned Well Potential Pollu	tion Problem	Yes No 🔊	TA	A Wells				
Lease Cleanliness Very Good Satisfactory	leas Va	w Pod	Mo	onitoring Reco	ords			
SWD/ER Injection Well Yes		ry Bau	Gauge	Connections	Yes No		ক	
Permit #: Pressure – Actua		uthorized: psi	_			; C/SP Annu	ılus:	
Permit #: Pressure - Actua	ıl: psi; A	uthorized: psi	Tubin	g:	; T/C Annulus: _	; C/SP Annu	ılus:	
Permit #: Pressure - Actua	l: psi; A	uthorized: psi				; C/SP Annu		
Permit #: Pressure - Actua	l: psi; A	uthorized: psi	Tubin	g:	; T/C Annulus: _	; C/SP Annu	ılus:	
API Footages	Spot Location	GPS		Well Number		Well Status	_	
15-135-25,232-00-00 43FSL-2240FWL	SW-SE-SE-SW	38.58128-100.10	690	1	New well, Alt,	,II completed		
	-							
				:				
							-	
			•					
					7			
	19 -			1		· · · · · · · · · · · · · · · · · · ·		

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: