KCC OIL/GAS REGULATORY OFFICES

Date: <u>06/10/11</u>	District: 01	Case #:							
•	New Situation	Lease Inspection							
	Response to Request	Complaint							
	Follow-Up	Field Report							
Operator License No: 4058	API Well Number: <u>15-135-25,205-00-00</u>								
Op Name: American Warrior	Spot: NE-NW-SW-SW	Sec <u>15 </u>							
Address 1: P.O. Box 399	1251 (1213)	Feet from N/ S Line of Section							
Address 2: P.O. Box 783188	484 (562)	Feet from E/\subseteq W Line of Section							
City: Garden City	GPS: Lat: 38.48351	Long: 99.75031 Date: 6/10/11							
State: Kansas Zip Code: 67846 -0399	Lease Name: Connie	Well #: <u>1-15</u>							
Operator Phone #: (620) 587-3224	County: Ness								
Reason for Investigation:									
Witness Alt.II		,							
Problem:									
None, cement circulated to surface									
Persons Contacted:									
Findings:									
8-5/8" @ 224W/160sxs cement									
TD @ 4290'									
5-1/2" @ 4289'W/175sxs cement Port Coller @ 1/30' comented with 125sys and 1/4# fle seal-2%cc-10sys went to nit									
Port Collar @ 1439' cemented with 125sxs-smd-1/4# flo seal-2%cc-10sxs went to pit									
·									
Action/Recommendations: Follow	v Up Required Yes N	No Date: RECEIVED							
Alt.II requirements have been met		JUN 2 2 2011							
פרסביו/בס		KCC WICHITA							
RECEIVED()		(100							
JUN 16 2011									
Verification Sources: KCC DODGE CITY		Photos Taken:							
	ΓA Program								
	Courthouse By: Mi	chael Maier							
Retain 1 Copy District Office Send 1 Copy to Conservation Division		Farm: 02/22/2009							

Date: <u>06/10/11</u>		_	District	: <u>01</u>		, Li	cense #: <u>4058</u>		
Op Name: 4058			Spot: <u>N</u>	Spot: <u>NE-NW-SW-SW</u> Sec <u>15</u> Twp <u>18</u> S Rng <u>22</u> E					
County: Ness			Lease Na	Lease Name: <u>Connie</u>			Well #: <u>1-15</u>		
I.D. Sign Yes	No		হ	Gas V	enting [Yes No		<u>*1</u>	
Tank Battery Condi		ble Overflow	ring 🤝	Pi Fluid		ft; Approx. S	ize:ft. x	ft.	
Pits, Injection Site Fluid Depth:	ft; Approx. S	Size:ff	i. xft.	$\boldsymbol{\vdash}$	altwater Pi aks Visible		Tested for Leaks:	o o	
Oil Spill Evidence				FI	lowing Ho	les			
Abandoned Well	Potential Poll	ution Problem	Yes No v	Т	A Wells				
Lease Cleanliness Very Good Sa	ntisfactory	Poor Very	y Bạd	М	lonitoring	Records			
SWD/ER Injection Well Permit #: Pr Permit #: Pr Permit #: Pr	ressure – Acturessure – Acturessure – Acture	al: psi; Aut al: psi; Aut al: psi; Aut	thorized: psi thorized: psi	Tubin Tubin Tubin	ng: ng: ng:	ions Yes No ; T/C Annulus: _ ; T/C Annulus: _ ; T/C Annulus: _ ; T/C Annulus: _	; C/SP Ann ; C/SP Ann ; C/SP Ann	ulus:	
API Number	Footages	Spot Location	GPS		Well #		Well Status		
15-135-25,205-00-00	1213FSL 562FWL	NE-NW-SW-SW	38.48351-99.75	5031	1-15	New well, Alt.II completed			
		,							
	:								