KCC OIL/GAS REGULATORY OFFICES

Date: <u>06/09/11</u>	District: _0	1		Case	#:	
·	New S	Situation		Lease Ins	pection	
	Respo	nse to Request		Complain	t	
	Follov	v-Up		Field Rep	ort	
Operator License No: 33770	_ API Well N	umber: <u>15-13</u>	35-25.245-0	0-00	,	
Op Name: Ares Energy, LTD	_		-		S Rng 21 E	/ √ W
Address 1: 405 N Marienfeld, Ste 250	994 (9	992)		Feet from	N/ S Line of	Section
Address 2:		909)		Feet from	E/ W Line of	Section
City: Midland	GPS: Lat:	38.49736	_Long: <u>99.</u>	76448	Date: <u>6/9/11</u>	
State: Texas Zip Code: 79701 -	_ Lease Name	: Boese			Well #: <u>9-16</u>	
Operator Phone #: (432) 685-1960	_ County: _N	ess	•			
Reason for Investigation:						
Witness Alt.II						
Problem:						
None						
Persons Contacted:						
				•		
77. 14						
Findings:	·					
8-5/8" @ 312'W/ TD @					,	
5-1`/2" @ 4448'W/125sxs						
Port Collar @ 1446'W/125sxs-smd-1/4# flo	seal-2%cc	10sxs to pit.	,			
		•				
-					·	
	-	•				
·						
Action/Recommendations: Fo	llow Up Required	Yes N	0 2	Date:		
None, Alt.II requirements have been met.	•				RECEIVED	
RECEIVED					JUN 2 2 2011	
JUN 16 2011					KCC WICHIT	Α
Verification Source CC DODGE CITY					Photos Taken:	
RBDMS KGS	TA Program		LINE	۸۸ ۲	in In.D	
T-I Database District Files Other:	Courthouse	By:	WY.		W	
Paralla I Carro District Office	. , .					

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form:

Date: <u>06/09/11</u>			District: <u>(</u>			ise #: <u>33770</u>			
			Spot: <u>NE</u> -	E-NW-SE-SE Sec 9 Twp 18 S Rng 21 E 🗸 W					
County: Ness			Lease Nam	ame: Boese Well #: 9-16					
I.D. Sign Yes No	0		9	Gas Venting	Yes No	2			
				Pits					
Tank Battery Condition: Good		Overflowin	ισ · 🛅		ft; Approx. Size	:ft. xft.			
Condition: Good G	Questionavio	overnown	.5						
μ									
Pits, Injection Site				Saltwater Pip		ested for Leaks: Y N			
Fluid Depth:f	t; Approx. Si	ze:ft.	xft.	Leaks Visible:		ested for Leaks.			
:					•				
Oil Spill Evidence	<u> </u>			Flowing Hole	es				
				TA Wells					
Abandoned Well P	otential Pollu	tion Problem] Yes No 🖭	L JA Wells		·			
					·				
,				Monitoring I	Records				
Lease Cleanliness			P						
Very Good Sat	tisfactory	Poor Very							
SWD/ER Injection Well			Ness 🖸		ons Yes No	; C/SP Annulus:			
Permit #: Pro						; C/SP Annulus:			
Permit #: Pro						; C/SP Annulus:			
И			horized: psi			; C/SP Annulus:			
		0 1				Well			
API Number	Footages	Spot Location	GPS	Well #		Status			
15-135-25,245-00-00	992FSL 909FEL	NE-NW-SE-SE	<u>38.49736-99.6</u> 4	9-16	New well, Alt,II co	mpleted			
4						· .			
1					,	-			
· ·									

Retain T Copy District Office Send 1 Copy to Conservation Division

Form: _____